

Motor Insurance Claim Investigation Report

AI-generated | Powered by ClaimIntel | 06 June 2026

DECISION: REJECT | Settlement: Rs. 0

Claim Details		Investigation Summary			
Claim ID	CLM-2026-06-000006	Fraud Risk Score		39%	
Policy No.	POL-221144				
Claimant	Sunita Patel	Label	Confidence		
Vehicle	Tata Altroz XZ Plus (DL12CU7624)	Low	90%		
Claim Type	Motor - Own Damage	Verification Checks			
Date	2026-06-02T20:44	Damage Consistency		FAIL	Low
Location	noida, up	Incident Consistency		PASS	High
AI Estimate	Rs. 0	External Verification		PASS	High
Submitted	2026-06-06	Behavioural Analysis		PASS	Low Risk
Status	Rejected				

Incident Description

"my vehicle was damaged because of some overspeeding vehicle in front of me got stopped in the middle of the road"

Agent Investigation Findings

Agent 1 - Damage Assessment (Vision AI)


No damaged parts identified.

Vehicle Match	Yes
Plate in Image	DL12CU7624
Pre-existing Dmg	None found
Total Estimate	Rs. 0 - Rs. 0

Note: The vehicle seems undamaged. The claim description mentions an accident, but no damage is visible in the provided image.

Agent 2 - Fraud Intelligence (Rule Engine + AI)

Fraud Score: 39% (Low Risk)



Fraud Indicators Detected (4):

- * Lapse-Reinstate Before Claim
- * Serial Claimant
- * FI-DMG-002: Physics Mismatch
- * FS-002

Matched Fraud Schemes:

- * New Policy Pre-Existing Damage Fraud (ID: FS-001)

KB References: FS-001 | FI-DMG-002 | FS-002

Agent 3 - Incident Reconstruction (Vision AI)

Collision Type	Front impact
Impact Direction	Frontal impact, likely from a stationary or slow-moving vehicle
Damage Matches Story	Yes
Confidence	80%

Reconstruction Narrative:

The vehicle was likely stationary or moving slowly when it was struck from the front, possibly by another vehicle that had overspeeded and stopped suddenly. The impact caused damage to the front of the vehicle.

Agent 4 - Context Verification (Geocoding + Policy)

Location Verified	Yes
Geocoded Location	Noida, Dadri, Gautam Buddha Nagar, Uttar Pradesh, India
Weather	Few Clouds, 34degC, Humidity: 35%, Visibility: 10000m
Policy Coverage	No obvious coverage exclusions detected from policy document

Decision Rationale & Reasoning

REJECT - Settlement: Rs. 0 - Confidence: 90%

Why This Decision? - Plain-Language Explanation

- * Fraud score of 39 is below the escalate threshold, but damage assessment indicates no visible damage, contradicting the claim description
- * Agent 1's damage assessment reports 'overall_severity: None' and 'total_repair_estimate: {'min': 0, 'max': 0}', suggesting no damage
- * Vehicle seems undamaged according to Agent 1's notes, which directly contradicts the claim of an accident
- * Matched scheme 'New Policy Pre-Existing Damage Fraud (ID: FS-001)' and indicator 'FI-DMG-002: Physics Mismatch' raise concerns about the claim's legitimacy

Agent 5 - Settlement Reasoning Trail (7 Steps)

- Step 1: Damage Assessment indicates no damage, contradicting the claim description
- Step 2: Fraud Intelligence reports a low fraud score but matches a potentially fraudulent scheme
- Step 3: Incident Reconstruction suggests the damage could match the story, but this is contradicted by the lack of damage found
- Step 4: Context & Policy verification confirms the location but does not address the damage discrepancy
- Step 5: Historical Precedents do not directly apply, but the lack of damage and matched fraudulent scheme are key factors
- Step 6: Settlement Calculation is not applicable due to the rejection decision
- Step 7: Final Decision to reject based on the cumulative evidence of no damage and potential fraud indicators

Knowledge Base Precedents Applied

- * FS-001
- * FI-DMG-002

DISCLAIMER: This report is generated by an AI system (ClaimIntel) and is intended to assist human insurance adjudicators. It does not constitute a final legal or contractual decision. All findings must be reviewed and confirmed by a licensed insurance professional before any settlement action is taken. AI recommendations are based on probabilistic analysis and may not reflect all relevant facts.