

Motor Insurance Claim Investigation Report

AI-generated | Powered by ClaimIntel | 10 June 2026

DECISION: APPROVE | Settlement: Rs. 41,079

Claim Details		Investigation Summary			
Claim ID	CLM-2026-06-000003	Fraud Risk Score		23%	
Policy No.	POL-112233				
Claimant	Aditya Nair	Label	Confidence		
Vehicle	Kia Seltos HTX Plus (TN12AJ1603)	Low	90%		
Claim Type	Motor - Third Party	Verification Checks			
Date	2026-06-08T13:02	Damage Consistency		PASS	High
Location	Perungudi, Chennai	Incident Consistency		PASS	High
AI Estimate	Rs. 51,200	External Verification		PASS	High
Submitted	2026-06-10	Behavioural Analysis		PASS	Low Risk
Status	Approved				

Incident Description

"An unexpected obstacle appeared on the roadway, causing the driver to lose control momentarily. The vehicle then collided with a vehicle that had come to a sudden stop ahead, resulting in damage."

Agent Investigation Findings

Agent 1 - Damage Assessment (Vision AI)				
Part	Severity	Estimate (Rs.)	Repair Type	Pricing
bonnet	Severe	Rs. 18,400 - Rs. 30,400	Replace	segment_catalog
front bumper		Rs. 7,400 - Rs. 11,200	Replace	live_web
headlight left		Rs. 6,900 - Rs. 14,400	Replace	segment_catalog
radiator grille		Rs. 5,000 - Rs. 8,700	Replace	segment_catalog
Vehicle Match	Yes			
Plate in Image	TN12AJ1603			
Pre-existing Dmg	None found			
Total Estimate	Rs. 37,700 - Rs. 64,700			
Note: The vehicle has severe front-end damage consistent with a high-speed collision.				

Agent 2 - Fraud Intelligence (Rule Engine + AI)

Fraud Score: 23% (Low Risk)

KB References: New Policy Syndrome

Agent 3 - Incident Reconstruction (Vision AI)	
Collision Type	Front impact
Impact Direction	Direct frontal impact
Damage Matches Story	Yes
Confidence	80%
Reconstruction Narrative:	
The vehicle likely collided with another vehicle or obstacle directly in front of it, causing severe damage to the front end, including the bonnet, front bumper, headlights, and radiator grille.	

Agent 4 - Context Verification (Geocoding + Policy)	
Location Verified	Yes
Geocoded Location	Zone 14 Perungudi, Chennai Corporation, Sholinganallur, Chennai, Tamil
Weather	Overcast Clouds, 37.11degC, Humidity: 52%, Visibility: 10000m
Policy Coverage	No obvious coverage exclusions detected from policy document

Decision Rationale & Reasoning

APPROVE - Settlement: Rs. 41,079 - Confidence: 90%

Deductibles applied: Rs. 1,000

Why This Decision? - Plain-Language Explanation

- * Fraud score of 23 is below the IRDAI Approve threshold of 40
- * Damage assessment indicates severe front-end damage consistent with a high-speed collision, matching the incident description
- * Location verification confirms the incident occurred at Perungudi, Chennai, as claimed
- * No pre-existing damage was observed, and the garage inflation flag is False
- * Vehicle match in image is confirmed, supporting the claimant's story

Agent 5 - Settlement Reasoning Trail (7 Steps)

1. Step 1: Damage Assessment indicates severe front-end damage, consistent with the incident description
2. Step 2: Fraud Intelligence reports a low fraud score of 23, indicating a low risk of fraud
3. Step 3: Incident Reconstruction confirms the collision type as front impact, consistent with the story
4. Step 4: Context & Policy verification confirms the location and policy coverage, with no obvious exclusions
5. Step 5: Historical Precedents do not indicate any similar cases of fraud or inflated claims
6. Step 6: Settlement Calculation applies IRDAI depreciation and deductibles, resulting in a recommended settlement of Rs.37,700
7. Step 7: Final Decision is to Approve the claim, based on the low fraud score and consistent evidence

DISCLAIMER: This report is generated by an AI system (ClaimIntel) and is intended to assist human insurance adjudicators. It does not constitute a final legal or contractual decision. All findings must be reviewed and confirmed by a licensed insurance professional before any settlement action is taken. AI recommendations are based on probabilistic analysis and may not reflect all relevant facts.