


# COMMERCIAL VEHICLES PRE-INSPECTION REPORT

Request No: KP-N-INDIA-2021-10

Ref. No. : 1234

Proposer/Customer Name: test		Address: H-602 Pan Oasis Apartments Sector 70
Requested Date: 2021-10-25	Requested Time: 18:34	Inspected Date & Time: 2021-10-27 13:01

CABIN ASSLY-STEEL	DESCRIPTION	REMARKS
CABIN CONDITION	Good	N/A
FR PANEL/HOOD	Intact	N/A
RH FENDER	Intact	N/A
RH PILLAR FRONT-A	Intact	N/A
RH DOOR PANEL	Intact	N/A
LH DOOR PANEL	Intact	N/A
RH WHEEL ARC/FOOTBOARD	Intact	N/A
RH RR PILLAR	Intact	N/A
CABIN BACK PANEL	Intact	N/A
LH RR PILLAR	Intact	N/A
LH RR PANEL	Intact	N/A
LH WHEEL ARC/FOOTBOARD	Intact	N/A
LH FENDER	Intact	N/A
CABIN ROOF/SHEET	Intact	N/A
FRONT BUMPER	Intact	N/A
BODY FITTINGS	DESCRIPTION	REMARKS
FR SHOW GRILL	Intact	N/A
RH HEAD LAMP BAZEL	Intact	N/A
RH HEAD LAMP	Intact	N/A
LH HEAD LAMP BAZEL	Intact	N/A
LH HEAD LAMP	Intact	N/A
LOAD BODY	DESCRIPTION	REMARKS
BODY STYLE	Open	N/A
BODY CONDITION	Good	N/A
RH BODY WING	Intact	N/A
LH BODY WING	Intact	N/A
COOLING SYSTEM	DESCRIPTION	REMARKS
RADIATOR	Intact	N/A
INTERCOOLER	Intact	N/A
OTHERS	DESCRIPTION	REMARKS
INSTRUMENT PANEL	Intact	N/A
ENGINE HOOD	Intact	N/A
DESEL TANK	Intact	N/A
SILENSOR ASSLY	Intact	N/A
WHEEL RIMS	Intact	N/A
BATTERY	Intact	N/A
RH FENDER CLIDING	Intact	N/A
LH FENDER CLIDING	Intact	N/A
LH REAR VIEW MIRROR	Intact	N/A
RH REAR VIEW MIRROR	Intact	N/A

INSURER DETAILS		
INSURER	THE NEW INDIA ASSURANCE	
AGENT BRANCH	DELHI BRANCH	
AGENT CODE/NAME	1234	
VEHICLE DETAILS		
VEHICLE NO	up11bc7474	
CHASSIS NO		
ENGINE NO		
MAKE	ASHOK LEYLAND	
MODEL	12M CRS (ALPSV 4-157/LEYM/AIR SUSP) BS-III	
DATE OF REGISTRATION		
YEAR OF MANUFACTURE		
COLOR		
ODOMETER		
FUEL MODE		
R.C VERIFIED		
GLASSES	DESCRIPTION	REMARKS
FR WINDSHIELD GLASS	Intact	N/A
CHASSIS IMPRESSION		
		
RECOMMENDATION FOR INSURANCE		
Yes		
QC REMARKS		

## DECLARATION OF OWNERS:

I hereby confirm & declare that the above mentioned identification details of my vehicles no up11bc7474 as well as that of damage to this vehicle as noted by the inspecting official are correct. Nothing has been hidden/Undisclosed.  
I further confirm & declare that the Vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a third party for injury or death caused to any person or damage to any property/insured vehicle during the period following the expiry of a previous insurance, till the moment it is proposed for insurance.  
I also agree that damage is mentioned above shall be excluded in the event of any claim being lodged.

For Auto Scan Technical Services



Authorized Signature

Note: Damages mentioned in this report and/or seen in the photographs are not to be correct for insurance any correction in report will be informed to concerned authorised person within 24 hours.

The top row of the collage shows three different software interfaces. On the left is the 'EZEEDRY Project Plan' showing a hierarchical tree structure of tasks and sub-tasks. In the center is the 'Builder' application, which appears to be a form or code editor with various tabs and a central workspace. On the right is a calendar application for September 2021, displaying dates and events.

The bottom row of the collage shows three web-based applications. The left application is 'JCS' (Job Costing System) displaying a table of job orders with columns for order number, order name, received order, due date, and status. The middle application is 'WISE HEALTHS' showing a 'Manage SubAdmin' interface with fields for SubAdmin Name and SubAdmin Username, and a table of subadmins. The right application is another 'JCS' interface showing a table of job orders with columns for order number, order name, TOP, BOTTOM, OTHER, and a 'Set Done' button.