


PVT. CARS PRE-INSPECTION REPORT

Request No: kp-bajaj-2018-001210

Ref. No. : 2018-03395147

Proposer/Customer Name: test	Address: H-602 Pan Oasis Apartments Sector 70
Requested Date: 2021-10-25	Requested Time: 16:54
	Inspected Date & Time: 2021-10-25 14:02

BODY PARTS	DESCRIPTION	REMARKS
FR PANEL/HOOD	Good	N/A
RH FENDER	Intact	N/A
FR APRON PANEL	Intact	N/A
RH PILLAR FRONT-A	Intact	N/A
RH FR DOOR PANEL	Intact	N/A
RH PILLAR CENTER-B	Intact	N/A
RH RR DOOR PANEL	Intact	N/A
RH RUNNING BOARD	Intact	N/A
RH QTR PANEL	Intact	N/A
DICKY/BACK DOOR	Intact	N/A
LH QTR PANEL	Intact	N/A
LH RUNNING BOARD	Intact	N/A
LH RR DOOR PANEL	Intact	N/A
LH PILLAR CENTER-B	Intact	N/A
LH FR DOOR PANEL	Intact	N/A
LH PILLAR FRONT-A	Intact	N/A
LH FENDER PANEL	Intact	N/A
LH APRON PANEL	Intact	N/A
ROOF PANEL	Intact	N/A
FLOOR PANEL	Intact	N/A
BODY FITTINGS	DESCRIPTION	REMARKS
FRONT BUMPER	Intact	N/A
FR GRILL	Intact	N/A
RH REAR VIEW MIRROR	Intact	N/A
LH REAR VIEW MIRROR	Intact	N/A
RR BUMPER	Intact	N/A
LIGHTS AND LAMPS	DESCRIPTION	REMARKS
RH HEAD LAMP	Open	N/A
LH HEAD LAMP	Good	N/A
RH FOG LAMP	Intact	N/A
LH FOG LAMP	Intact	N/A
RH TAIL LAMP	Intact	N/A
LH TAIL LAMP	Intact	N/A
COOLING SYSTEM	DESCRIPTION	REMARKS
CONDENSOR	Intact	N/A
RADIATOR	Intact	N/A
INTERIORS	DESCRIPTION	REMARKS
INSTRUMENT PANEL	Intact	N/A
OTHERS	DESCRIPTION	REMARKS
BATTERY	Working	N/A
TYRE CONDITION	Good	N/A

INSURER DETAILS		
INSURER	THE NEW INDIA ASSURANCE	
AGENT BRANCH	DELHI BRANCH	
AGENT CODE/NAME	1234	
VEHICLE DETAILS		
VEHICLE NO	up11bc7474	
CHASSIS NO		
ENGINE NO		
MAKE	AUDI	
MODEL	A3-CABRIOLET	
DATE OF REGISTRATION		
YEAR OF MANUFACTURE		
COLOR		
ODOMETER		
FUEL MODE		
R.C VERIFIED		
ACCESSORIES	DESCRIPTION	REMARKS
STEREO		
CENTER LOCK		
GLASSES	DESCRIPTION	REMARKS
FR WS GLASS	Intact	N/A
RR WS GLASS	Intact	N/A
CHASSIS IMPRESSION		
		
RECOMMENDATION FOR INSURANCE		
Yes		
QC REMARKS		
llkjljkikjl		

DECLARATION OF OWNERS:

I hereby confirm & declare that the above mentioned identification details of my vehicles no up11bc7474 as well as that of damage to this vehicle as noted by the inspecting official are correct. Nothing has been hidden/Undisclosed.
I further confirm & declare that the Vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a third party for injury or death caused to any person or damage to any property/insured vehicle during the period following the expiry of a previous insurance, till the moment it is proposed for insurance.
I also agree that damage is mentioned above shall be excluded in the event of any claim being lodged.

For Auto Scan Technical Services



Authorized Signature

Note: Damages mentioned in this report and/or seen in the photographs are not to be correct for insurance any correction in report will be informed to concerned authorised person within 24 hours.

The screenshot displays the AutoScan software interface. On the left, there's a 'Project Plan' section with a hierarchical tree structure. The main area shows a list of tasks with columns for 'Task Name', 'Status', 'Priority', 'Due Date', and 'Assignee'. A 'Calendar' view is visible on the right, showing tasks scheduled for September 2021. The bottom of the screen shows a Windows taskbar with various application icons.

The screenshot shows the JCS software interface. It features a 'Manage Sub-Admin' form with fields for 'Sub-Admin Name', 'Sub-Admin Username', and 'Sub-Admin Password'. Below the form is a 'Sub-Admin List' table. To the right, there's a calendar view showing tasks for September 2021. The bottom of the screen shows a Windows taskbar with various application icons.

The screenshot displays the JCS software interface. It features a 'Transfer Queue' section with a table showing tasks. To the right, there's a calendar view showing tasks for September 2021. The bottom of the screen shows a Windows taskbar with various application icons.