

Head Office: Sector-16, Rohini, Delhi-110089 Office: CSC-7/43, F Block, DDA Market, Sector-16,

Rohini, Delhi

Phone: 999999999

Website: www.autoscanbookvalue.com

COMMERCIAL VEHICLES PRE-INSPECTION REPORT

Request No: KP-N-INDIA-2021-16 Ref. No.: 13215121

Proposer/Customer Name: OM PRAKASH		Address: VPO RURKEE ROHTAK
Requested Date: 2021-11-09	Requested Time: 13:06	Inspected Date & Time: 2021-11-09 07:00

Requested Date: 2021-11-09		Requested Time: 13:06
CABIN ASSLY-STEEL	DESCRIPTION	REMARKS
CABIN CONDITION	Average	N/A
FR PANEL/HOOD	Intact	N/A
RH FENDER	Intact	N/A
RH PILLAR FRONT-A	Intact	N/A
RH DOOR PANEL	Scratch	MINOR
LH DOOR PANEL	Intact	N/A
RH WHEEL ARC/FOOTBOARD	Intact	N/A
RH RR PILLAR	Intact	N/A
CABIN BACK PANEL	Intact	N/A
LH RR PILLAR	Intact	N/A
LH RR PANEL	Intact	N/A
LH WHEEL ARC/FOOTBOARD	Intact	N/A
LH FENDER	Intact	N/A
CABIN ROOF/SHEET	Intact	N/A
FRONT BUMPER	Dented	MAJOR
BODY FITTINGS	DESCRIPTION	REMARKS
FR SHOW GRILL	Intact	N/A
RH HEAD LAMP BAZEL	Intact	N/A
RH HEAD LAMP	Intact	N/A
LH HEAD LAMP BAZEL	Intact	N/A
LH HEAD LAMP	Intact	N/A
LOAD BODY	DESCRIPTION	REMARKS
BODY STYLE	Closed	N/A
BODY CONDITION	Average	N/A
RH BODY WING	Intact	N/A
LH BODY WING	Intact	N/A
COOLING SYSTEM	DESCRIPTION	REMARKS
RADIATOR	Intact	N/A
INTERCOOLER	Intact	N/A
INTERCOOLER OTHERS	Intact DESCRIPTION	N/A REMARKS
OTHERS	DESCRIPTION	REMARKS
OTHERS INSTRUMENT PANEL	DESCRIPTION Intact	REMARKS N/A
OTHERS INSTRUMENT PANEL ENGINE HOOD	DESCRIPTION Intact Intact	REMARKS N/A N/A
OTHERS INSTRUMENT PANEL ENGINE HOOD DESEL TANK	DESCRIPTION Intact Intact Intact	REMARKS N/A N/A N/A
OTHERS INSTRUMENT PANEL ENGINE HOOD DESEL TANK SILENSOR ASSLY	DESCRIPTION Intact Intact Intact Intact	REMARKS N/A N/A N/A N/A N/A
OTHERS INSTRUMENT PANEL ENGINE HOOD DESEL TANK SILENSOR ASSLY WHEEL RIMS	Intact Intact Intact Intact Intact Intact Intact	REMARKS N/A N/A N/A N/A N/A N/A
OTHERS INSTRUMENT PANEL ENGINE HOOD DESEL TANK SILENSOR ASSLY WHEEL RIMS BATTERY	DESCRIPTION Intact Intact Intact Intact Intact Intact Intact Intact	REMARKS N/A N/A N/A N/A N/A N/A N/A N/A
OTHERS INSTRUMENT PANEL ENGINE HOOD DESEL TANK SILENSOR ASSLY WHEEL RIMS BATTERY RH FENDER CLIDING	DESCRIPTION Intact Intact Intact Intact Intact Intact Intact Intact Intact	REMARKS N/A

Inspected Date & Time: 2021-11-09 07:00				
INSURER DETAILS				
INSURER	THE NEW INDIA ASSURANCE			
AGENT BRANCH	DEHRADUN BRANCH			
AGENT CODE/NAME	9897			
VEHICLE DETAILS				
VEHICLE NO	HR46D0409			
CHASSIS NO	MAT454102D8B05777			
ENGINE NO	497TC96BWY809146			
MAKE	TATA			
MODEL	SFC			
DATE OF REGISTRATION	04-2013			
YEAR OF MANUFACTURE	2013			
COLOR	N/A			
ODOMETER	192673			
FUEL MODE	DIESAL			
R.C VERIFIED	YES			
GLASSES	DESCRIPTION	REMARKS		
FR WINDSHIELD GLASS	Intact	N/A		
CHASSIS IMPRESSION				
×				
RECOMMENDATION FOR INSURANCE				
Yes				
QC REMARKS				

DECLARATION OF OWNERS:

I hearby confirm & declare that the above mentioned identification details of my vehicles no HR46D0409 as well as that of damage to this vehicle as noted by the inspecting offical are correct. Nothing has been hidden/Undisclosed.

I further confirm & declare that the Vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a third party for injury or death caused to any person or damage to any property/insured vehicle during the period following the expiry of a previous insurance, ill the moment it is proposed for insurance.

I also agree that damage is mentioned above shall be excluded in the event of any claim being lodged.

For Auto Scan Technical Services



Note: Damages mentioned in this report and/or seen in the photographs are not to be correct for insurance any correction in report will be informed to concerned authorised person within 24 hours.



Head Office: Sector-16, Rohini, Delhi-110089 Office: CSC-7/43, F Block, DDA Market, Sector-16,

Rohini,Delhi Phone: 9999999999

Website: www.autoscanbookvalue.com



