

## PVT. CARS PRE-INSPECTION REPORT

Request No: KP-N-INDIA-2021-15

Ref. No. : 123456788

Proposer/Customer Name: HARSH	Address: IT Park, sahastradhara road, dehradun
Requested Date: 2021-11-09	Requested Time: 12:13
	Inspected Date & Time: 2021-11-09 01:00

BODY PARTS	DESCRIPTION	REMARKS
FR PANEL/HOOD	Average	N/A
RH FENDER	Scratch	N/A
FR APRON PANEL	Intact	N/A
RH PILLAR FRONT-A	Intact	N/A
RH FR DOOR PANEL	Broken	scratched
RH PILLAR CENTER-B	Intact	N/A
RH RR DOOR PANEL	Broken	Dented
RH RUNNING BOARD	Dented	N/A
RH QTR PANEL	Scratch	N/A
DICKY/BACK DOOR	Broken	N/A
LH QTR PANEL	Damage	Scratched
LH RUNNING BOARD	Intact	N/A
LH RR DOOR PANEL	Dented	Scratched
LH PILLAR CENTER-B	Scratch	N/A
LH FR DOOR PANEL	Scratch	N/A
LH PILLAR FRONT-A	Intact	N/A
LH FENDER PANEL	Scratch	N/A
LH APRON PANEL	Intact	N/A
ROOF PANEL	Intact	N/A
FLOOR PANEL	Intact	N/A
BODY FITTINGS	DESCRIPTION	REMARKS
FRONT BUMPER	Broken	Minor scratched
FR GRILL	Intact	N/A
RH REAR VIEW MIRROR	Intact	N/A
LH REAR VIEW MIRROR	Intact	N/A
RR BUMPER	Broken	Scratched
LIGHTS AND LAMPS	DESCRIPTION	REMARKS
RH HEAD LAMP	Open	N/A
LH HEAD LAMP	Good	N/A
RH FOG LAMP	Intact	N/A
LH FOG LAMP	Intact	N/A
RH TAIL LAMP	Intact	N/A
LH TAIL LAMP	Intact	N/A
COOLING SYSTEM	DESCRIPTION	REMARKS
CONDENSOR	Intact	N/A
RADIATOR	Intact	N/A
INTERIORS	DESCRIPTION	REMARKS
INSTRUMENT PANEL	Intact	N/A
OTHERS	DESCRIPTION	REMARKS
BATTERY	Working	N/A
TYRE CONDITION	Average	N/A

INSURER DETAILS		
INSURER	THE NEW INDIA ASSURANCE	
AGENT BRANCH	DEHRADUN BRANCH	
AGENT CODE/NAME	9897	
VEHICLE DETAILS		
VEHICLE NO	DL 6 CR 6714	
CHASSIS NO	MAT627625JLJ43081	
ENGINE NO	REVTRN03JRYK94132	
MAKE	TATA	
MODEL	NEXON	
DATE OF REGISTRATION	17/11/2018	
YEAR OF MANUFACTURE	2018	
COLOR	CALGARY_WHITE	
ODOMETER	45496	
FUEL MODE	PETROL	
R.C VERIFIED	Yes	
ACCESSORIES	DESCRIPTION	REMARKS
STEREO	yes	yes
CENTER LOCK	yes	yes
GLASSES	DESCRIPTION	REMARKS
FR WS GLASS	Intact	N/A
RR WS GLASS	Intact	N/A



RECOMMENDATION FOR INSURANCE
Yes
QC REMARKS

### DECLARATION OF OWNERS:

I hereby confirm & declare that the above mentioned identification details of my vehicles no DL 6 CR 6714 as well as that of damage to this vehicle as noted by the inspecting official are correct. Nothing has been hidden/Undisclosed.  
I further confirm & declare that the Vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a third party for injury or death caused to any person or damage to any property/insured vehicle during the period following the expiry of a previous insurance, till the moment it is proposed for insurance.  
I also agree that damage is mentioned above shall be excluded in the event of any claim being lodged.

For Auto Scan Technical Services



Authorized Signature

Note: Damages mentioned in this report and/or seen in the photographs are not to be correct for insurance any correction in report will be informed to concerned authorised person within 24 hours.

This is an auto generated Report and Digitally Signed By Authorised Signature

Page 1 of 3







