

Head Office: Sector-16, Rohini, Delhi-110089 Office: CSC-7/43, F Block, DDA Market, Sector-16,

Rohini, Delhi

Phone: 999999999

Website: www.autoscanbookvalue.com

TWO WHEELER PRE-INSPECTION REPORT

Request No: kp-bajaj-2018-001210 Ref. No.: 2018-03395147

Proposer/Customer Name:	RAVISH BEG	Address:H-602 Pan Oasis Apartments Sector 70
Requested Date:12-20-2021	Requested Time:14:40	Inspected Date & Time:21/12/2021 11:00pm

Requested Date: 12-20-2021		ea Time. 14.40
BODY PARTS	DESCRIPTION	REMARKS
FR FENDER	Intact	N/A
FR WHEEL RIM	Intact	N/A
FR FORK ASSLY	Intact	N/A
RH FR SHOCKER	Intact	N/A
HEAD LIGHT	Intact	N/A
FR CENTER COVER	Intact	N/A
RH FR PANEL	Intact	N/A
LH FR PANEL	Intact	N/A
RH FR INDICATOR LT	Intact	N/A
LH FR INDICATOR LT	Intact	N/A
HANDLE BAR	Intact	N/A
SPEEDOMETER ASSLY	Intact	N/A
UTILITY BOX	N/A	N/A
RR BODY	Intact	N/A
RH RR COWL PANEL	Intact	N/A
LH RR COWL PANEL	Intact	N/A
RH RR INDICATOR LT	Intact	N/A
LH RR INDICATOR LT	Intact	N/A
TAIL LIGHT ASSLY	Intact	N/A
LH FOOTREST ASSLY	Intact	N/A
SEAT	Intact	N/A
SILENSOR ASSLY	Intact	N/A
CHASSIS FRAME	Intact	N/A
FR FOOTBOARD PANEL	Intact	N/A
RR WHEEL RIM	Intact	N/A
SPARE WHEEL RIM	N/A	N/A
RH RAER VIEW MIRROR	Intact	N/A
LH REAR VIEW MIRROR	Intact	N/A
BATTERY	Intact	N/A
ENGINE CHAMBER	Intact	N/A
FUEL TANK	Intact	N/A

INSURER DETAILS				
INSURER	NATIONAL INSURANCE CO. LTD.			
AGENT BRANCH	SAHARANPUR BRANCH			
AGENT CODENAME	02322			
VEHICLE DETAILS				
VEHICLE NO		UP11D3474		
CHASSIS NO		DSFJKSLDJGKLF		
ENGINE NO		DFKGLKFGJLKFDJGKLFD		
MAKE		MARUTI		
MODEL		800		
DATE OF REGISTRATION		21/12/2021		
YEAR OF MANUFACTURE		2018		
COLOR		GREEN		
ODOMETER		36783		
FUEL MODE		PETROL		
R.C VERIFIED		YES		
CHASSIS IMPRESSION				

RECOMMENDATION FOR INSURANCE

option1 **QC REMARKS FDGFDGFDGFD**

DECLARATION OF OWNERS:

hearby confirm & declare that the above mentioned identification details of my vehicles no UP11D3474 as well as that of damage to this vehicle as noted by the inspecting offical are correct. Nothing has been hidden/Undisclosed.

I further confirm & declare that the Vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a third party for injury or death caused to any person or damage to any property/insured vehicle during the period following the expiry of a previous insurance, ill the moment it is proposed for insurance.

I also agree that damage is mentioned above shall be excluded in the event of any claim being lodged.

For Auto Scan Technical Services





Head Office: Sector-16, Rohini, Delhi-110089 Office: CSC-7/43, F Block, DDA Market, Sector-16,

Rohini,Delhi Phone: 999999999

Website: www.autoscanbookvalue.com









Head Office: Sector-16, Rohini, Delhi-110089 Office: CSC-7/43, F Block, DDA Market, Sector-16,

Rohini,Delhi Phone: 9999999999

Website: www.autoscanbookvalue.com





