

TWO WHEELER PRE-INSPECTION REPORT

Request No: KP-N-INDIA-2021-13


Ref. No. : 7894521

Proposer/Customer Name: kartik		Address: kirsali shastrdhara
Requested Date: 2021-11-08	Requested Time: 20:33	Inspected Date & Time: 2021-11-08 08:39

BODY PARTS	DESCRIPTION	REMARKS
FR FENDER	Intact	N/A
FR WHEEL RIM	Intact	N/A
FR FORK ASSLY	Intact	N/A
RH FR SHOCKER	Intact	N/A
HEAD LIGHT	Intact	N/A
FR CENTER COVER	Intact	N/A
RH FR PANEL	Intact	N/A
LH FR PANEL	Intact	N/A
RH FR INDICATOR LT	Intact	N/A
LH FR INDICATOR LT	Intact	N/A
HANDLE BAR	Intact	N/A
SPEEDOMETER ASSLY	Intact	N/A
UTILITY BOX	Intact	N/A
RR BODY	Intact	N/A
RH RR COWL PANEL	Intact	N/A
LH RR COWL PANEL	Intact	N/A
RH RR INDICATOR LT	Intact	N/A
LH RR INDICATOR LT	Intact	N/A
TAIL LIGHT ASSLY	Intact	N/A
LH FOOTREST ASSLY	Intact	N/A
SEAT	Intact	N/A
SILENSOR ASSLY	Intact	N/A
CHASSIS FRAME	Intact	N/A
FR FOOTBOARD PANEL	Intact	N/A
RR WHEEL RIM	Intact	N/A
SPARE WHEEL RIM	Intact	N/A
RH RAER VIEW MIRROR	Intact	N/A
LH REAR VIEW MIRROR	Intact	N/A
BATTERY	Intact	N/A
ENGINE CHAMBER	Intact	N/A
FUEL TANK	Intact	N/A

INSURER DETAILS	
INSURER	THE NEW INDIA ASSURANCE
AGENT BRANCH	DEHRADUN BRANCH
AGENT CODENAME	9897

VEHICLE DETAILS	
VEHICLE NO	uk07du7677
CHASSIS NO	MZDKW1C16L1G38351
ENGINE NO	NBE-LG004898
MAKE	jawa motors
MODEL	jawa42
DATE OF REGISTRATION	07-OCT-2020
YEAR OF MANUFACTURE	2020
COLOR	GALACTIC GREEN
ODOMETER	11089
FUEL MODE	PETROL
R.C VERIFIED	YES

CHASSIS IMPRESSION


RECOMMENDATION FOR INSURANCE
Yes
QC REMARKS
DAMAGE MARKED AS PER THE PHOTOGRAPHS.

DECLARATION OF OWNERS:

I hereby confirm & declare that the above mentioned identification details of my vehicles no uk07du7677 as well as that of damage to this vehicle as noted by the inspecting official are correct. Nothing has been hidden/Undisclosed.
I further confirm & declare that the Vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a third party for injury or death caused to any person or damage to any property/insured vehicle during the period following the expiry of a previous insurance, till the moment it is proposed for insurance.
I also agree that damage is mentioned above shall be excluded in the event of any claim being lodged.

For Auto Scan Technical Services



Authorized Signature

Note: Damages mentioned in this report and/or seen in the photographs are not to be correct for insurance any correction in report will be informed to concerned authorised person within 24 hours.

