

Driver's Daily Vehicle Inspection

Information	
	Gurba, Stefan
	20185 - GB WWTP Odour Capture
	Thursday, June 18th 2026, 6:34 AM (MDT -06:00)
General Information	
D0798 Rev0	
Trip Type	
☒	Pre-Trip
Carrier	 Norfab
Address of Inspection	 402 Malvern PI
Driver (Inspector)	 Stefan Gurba
Truck/Tractor Information	
Unit No.	 FPT10 - 2009 GMC Sierra 3500HD
License Plate	 Sce 727
Jurisdiction	 Alberta
Odometer (kms)	 340423
Vehicle Load: Height/Width	 3500
Trailer Information	
Yes ☒ No ☐ NA ☐	Utilizing Trailer - If YES requires information below
Unit No.	 No Response
License Plate	 No Response
Jurisdiction	 No Response
Vehicle/Load: Height/Width	 No Response
Acknowledgement	
Yes ☒ No ☐ NA ☐	I declare that the vehicle(s) shown above have has (have) been inspected in accordance with the applicable requirements of Schedule 1 and/or jurisdiction legislation

If "NO" is selected, fill out the defective item checklist below

Truck/Tractor Inspection

- | | | | |
|-------------------------------------|--------------------------|--------------------------|--|
| ☒ | ☐ | ☐ | Tires & Wheels (Tires/Wheels/Rims/Hubs/Bearings/Fasteners) |
| ☒ | ☐ | ☐ | Coupling & Towing (Coupling devices/Pintle Hook/Towing Attachments/Hitches/Safety Chains/Fifth Wheel) |
| ☒ | ☐ | ☐ | Frame & Cargo body/Cargo Securement |
| ☒ | ☐ | ☐ | Fluids and Hoses (Visual - Oil/Coolant/Brake Fluid/Washer Fluid/Power Steering Fluid/Fuel/Radiator) |
| ☒ | ☐ | ☐ | Air System (Air compressor/Air system condition) |
| ☒ | ☐ | ☐ | Electrical & Visibility (Visual - Battery/Electrical/Lamps/Reflectors/Glass/Mirrors/License Plate Legible) |
| ☒ | ☐ | ☐ | Cab and Controls (Wipers/Signals/Defroster/Heater/Cab Condition/Seat belts/Driver Controls/Horn/Gauges) |
| ☒ | ☐ | ☐ | Safety & Emergency Equipment (Pylons or Triangles/Fire extinguisher/First Aid Kit) |
| ☒ | ☐ | ☐ | Documents (registration, insurance, inspection decal/CVIP if applicable) |

Remarks

☐ No Response

☐ Above defects corrected

☐ Above defects need not be corrected for safe operation of vehicle

Defects En Route

☐ No Response

Trailer Inspection

- | | | | |
|-------------------------------------|----------------------------------|--------------------------|---|
| Yes | ☒ | ☐ | Utilizing Trailer - Requires Trailer Inspection Below |
| ☒ | ☐ | ☐ | Tires, Wheels and Suspension (tires / rims / hubs / bearings / fasteners/ suspension) |
| ☒ | ☐ | ☐ | Brakes (Brake Adjustments / Brake Components) |
| ☒ | ☐ | ☐ | Coupling & Attachment (kingpin / pintle / coupler / safety chains / landing gear / locking devices) |
| ☒ | ☐ | ☐ | Frame & Cargo Body (frame / deck / rails / gates / ramps / floor / securement points) |
| ☒ | ☐ | ☐ | Cargo Securement (tie-downs / binders / straps / winches / anchor points) |
| ☒ | ☐ | ☐ | Electrical & Visibility (lamps / reflectors / conspicuity tape / wiring / plate light & license plate visibility) |
| ☒ | ☐ | ☐ | Inspection Decal / CVIP (if applicable) |

Remarks

☐ No Response

☐ Above defects corrected

☐ Above defects need not be corrected for safe operation of vehicle

Defects En Route

☐ No Response

Acknowledgement

The driver, inspector, and repair person (if applicable) must sign this document

Signatures

Stefan Gurba, *Field Welder*



June 18th 2026, 6:34 AM (MDT -06:00)



53.5414665, -113.3178864