Dealership Progress Report

XPENG Service Center Béziers x GRIM

ZONE PERFORMANCE / South-East / 25 October 2026

PROGRESS	COMPLETED	REMAINING	CAMPAIGNS BELOW TARGET
74.4%	29	10	5
29 completed of 39	records closed	records to complete	of 8 campaigns

Current status

Status	Records	Share of dealership total
Finished	29	74.4%
To be finished	10	25.6%

Where to investigate first

Campaign hotspot: 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection has 3 open of 3 records.

Vehicle signal: New G6 AWD Performance has 3 open records.

10 open campaign records cover 8 distinct VINs.

These are observed workload patterns, not proof that this dealership caused the issue.

Data gap: 10 of 10 open cases lack a job-order number, and 10 lack a completion date. Check source-system data before attributing responsibility or estimating delay.

Campaigns driving open workload

Campaign case counts, completion and open workload for this dealership.

Campaign code / name	Total	Completed	Open	Progress	Extra to 85%
26ODBXI1-1 G9 Wiring Harness Body Deputy Inspection	3	0	3	0.0%	3
25OBTDN1-1 New G6 Cup Holder Replacement(Dark Gray)	5	3	2	60.0%	2
25OBTDN1 New G6 Cup Holder Replacement(Impressive Gray)	4	3	1	75.0%	1
25OTCGN2 G6 Electric tow hook label	9	8	1	88.9%	0
25OTCGN2-1 G9 Electric tow hook label	2	1	1	50.0%	1
25OYKBN1 New G9/New G6 - UWB Smart Key Update	14	13	1	92.9%	0
26OMBSI1-EU P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%	1

By campaign type

Segment	Total	Completed	Open	Completion
PSC(Pre-delivery Service Campaign)	21	16	5	76.2%
CIC(Customer Incoming service Campaign)	4	0	4	0.0%
SSC(Special Service Campaign)	14	13	1	92.9%

Vehicle and record detail

Use vehicle and tier concentrations to narrow a technical review; confirm against campaign eligibility and workshop evidence.

By vehicle model

Segment	Total	Completed	Open	Completion
G9_2024 AWD Performance	3	0	3	0.0%
New G6 AWD Performance	12	9	3	75.0%
New G9 RWD Long Range	2	0	2	0.0%
New G6 RWD Long Range	17	16	1	94.1%
P7+ RWD Long Range	1	0	1	0.0%

By campaign tier

Segment	Total	Completed	Open	Completion
General	24	15	9	62.5%
Important	15	14	1	93.3%

Campaign-by-campaign progress

Use this table to track completion and remaining workload.

Campaign code	Campaign	Total	Completed	Remaining	Progress
25OYKBN1	New G9/New G6 - UWB Smart Key Update	14	13	1	92.9%
25OTCGN2	G6 Electric tow hook label	9	8	1	88.9%
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	5	3	2	60.0%
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	4	3	1	75.0%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	3	0	3	0.0%
25OTCGN2-1	G9 Electric tow hook label	2	1	1	50.0%
25OXDCP1	SC–G6 Repair the 12V Battery negative ground point	1	1	0	100.0%
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	1	0	1	0.0%