Global Service Campaign Report — South-East

Executive summary and review priorities

ZONE PERFORMANCE / South-East / 25 October 2026

OVERALL PROGRESS	REMAINING WORKLOAD	DEALERSHIPS BELOW TARGET	CAMPAIGNS BELOW TARGET
66.4%	**290**	**17**	**13**
574 completed out of 864	records still to complete	of 19 dealerships	of 17 campaigns

Meeting takeaways

Overall: 574 of 864 records completed (66.4%); 290 remain.

Dealerships to review first: XPENG Service Center Valence x Jean Lain Mobilités has 52 open (30.7% complete).

Largest campaign backlog: 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection has 114 open of 142 cases.

Campaign/model overlap: 83 open of 104 for 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection / G9_2024 AWD Performance.

Campaign type CIC(Customer Incoming service Campaign): 137 open of 179; leading model G9_2024 AWD Performance: 91 open of 119.

VIN check: 251 VINs appear in multiple campaigns; 0 extra row(s) repeat the same VIN and campaign (0 with conflicting statuses).

All findings are workload signals, not proof of dealership fault. Open cases lack job-order numbers and completion dates; verify source records before attributing cause or estimating delay.

Workload by status

Status	Records	Share of total
Finished	574	66.4%
To be finished	290	33.6%

Dealership progress

Progress bars are color-coded against the 85% reference target.

Dealership	Total	Completed	Open	Completion	Zone open share
XPENG Service Center Le Cannet x Mozart Autos	125	93	32	74.4%	11.0%
XPENG Service Center Fréjus Mapauto	93	83	10	89.2%	3.4%
XPENG Service Center Valence x Jean Lain Mobilités	75	23	52	30.7%	17.9%
XPENG Service Center Montpellier x GRIM	70	36	34	51.4%	11.7%
XPENG Service Center Toulouse x De Boussac	66	31	35	47.0%	12.1%
XPENG Service Center Marseille x Parascandola	60	40	20	66.7%	6.9%
XPENG Service Center Aix-en-Provence x Deffeuille	57	36	21	63.2%	7.2%
XPENG Service Center Nice x Mozart Autos	54	51	3	94.4%	1.0%
XPENG Service Center Béziers x GRIM	39	29	10	74.4%	3.4%
XPENG Service Center Nîmes x Grim	39	33	6	84.6%	2.1%
XPENG Service RVO Clermont-Ferrand France	34	23	11	67.6%	3.8%
XPENG Service Center Bastia x Groupe SIA	33	26	7	78.8%	2.4%
XPENG Service Center Rodez x Garage Negrier	31	23	8	74.2%	2.8%
XPENG Service Center Perpignan x LG	29	17	12	58.6%	4.1%
XPENG Service Center Bandol x Etoile 83	28	12	16	42.9%	5.5%
XPENG Service Center Gap x Mazet	12	9	3	75.0%	1.0%

Dealership	Total	Completed	Open	Completion	Zone open share
XPENG Service Center Toulon Est x Etoile 83	10	5	5	50.0%	1.7%
XPENG Service Center Limoges x LG	7	4	3	57.1%	1.0%
XPENG Service Center Perigueux x LG	2	0	2	0.0%	0.7%

Zone total: 574 completed of 864 records (66.4%). Records without a dealership: 0.

Dealerships to review

17 of 19 dealerships are below the 85% target. Highest workloads are listed first.

Dealership	Total	Completed	Open	Completion	Extra to 85%	Zone open sh
XPENG Service Center Valence x Jean Lain Mobilités	75	23	52	30.7%	41	17.9%
XPENG Service Center Toulouse x De Boussac	66	31	35	47.0%	26	12.1%
XPENG Service Center Montpellier x GRIM	70	36	34	51.4%	24	11.7%
XPENG Service Center Le Cannet x Mozart Autos	125	93	32	74.4%	14	11.0%
XPENG Service Center Aix-en-Provence x Deffeuille	57	36	21	63.2%	13	7.2%
XPENG Service Center Marseille x Parascandola	60	40	20	66.7%	11	6.9%
XPENG Service Center Bandol x Etoile 83	28	12	16	42.9%	12	5.5%
XPENG Service Center Perpignan x LG	29	17	12	58.6%	8	4.1%
XPENG Service RVO Clermont-Ferrand France	34	23	11	67.6%	6	3.8%
XPENG Service Center Béziers x GRIM	39	29	10	74.4%	5	3.4%
XPENG Service Center Rodez x Garage Negrier	31	23	8	74.2%	4	2.8%
XPENG Service Center Bastia x Groupe SIA	33	26	7	78.8%	3	2.4%
XPENG Service Center Nîmes x Grim	39	33	6	84.6%	1	2.1%
XPENG Service Center Toulon Est x Etoile 83	10	5	5	50.0%	4	1.7%
XPENG Service Center Limoges x LG	7	4	3	57.1%	2	1.0%
XPENG Service Center Gap x Mazet	12	9	3	75.0%	2	1.0%

Dealership	Total	Completed	Open	Completion	Extra to 85%	Zone open sh
XPENG Service Center Perigueux x LG	2	0	2	0.0%	2	0.7%

Campaigns to review

Campaigns below target, ranked by remaining records.

Campaign code	Campaign	Total	Completed	Remaining	Progress	Extra to 85%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	142	28	114	19.7%	93
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	72	48	24	66.7%	14
25OTCGN2-1	G9 Electric tow hook label	60	37	23	61.7%	14
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	78	56	22	71.8%	11
25OTCGN2	G6 Electric tow hook label	111	91	20	82.0%	4
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	20	6	14	30.0%	11
26OCGQI1-2	P7plus - Height Sensor Inspection	16	7	9	43.8%	7
EsimTBOX-G6-1	G6-Esim-TBOX delayed claiming	17	8	9	47.1%	7
EsimTBOX-G9-1	G9-Esim-TBOX delayed claiming	8	2	6	25.0%	5
24OXDYP1	G6-Reduce the concentration of cleaning fluid	31	26	5	83.9%	1
G9MY3231	SC-G9 Pasting the vehicle nameplate	13	10	3	76.9%	2
25WDCFN1-3	SC – G9 HV battery replacement	2	0	2	0.0%	2
24OZYPN1	G6-Driver/Front passenger seat cushion improvement	5	3	2	60.0%	2

Campaign and process drivers

Open cases grouped by campaign and campaign type. Completion bars show the share of records already finished.

Campaign code / name	Total	Completed	Open	Progress	Extra to 85%
26ODBXI1-1 G9 Wiring Harness Body Deputy Inspection	142	28	114	19.7%	93
25OYKBN1 New G9/New G6 - UWB Smart Key Update	194	166	28	85.6%	0
25OBTDN1 New G6 Cup Holder Replacement(Impressive Gray)	72	48	24	66.7%	14
25OTCGN2-1 G9 Electric tow hook label	60	37	23	61.7%	14
25OBTDN1-1 New G6 Cup Holder Replacement(Dark Gray)	78	56	22	71.8%	11
25OTCGN2 G6 Electric tow hook label	111	91	20	82.0%	4
26OMBSI1-EU P7 plus Front Exterior Door Handle Replacement	20	6	14	30.0%	11
25OXDCP1 SC–G6 Repair the 12V Battery negative ground point	91	82	9	90.1%	0
26OCGQI1-2 P7plus - Height Sensor Inspection	16	7	9	43.8%	7
EsimTBOX-G6-1 G6-Esim-TBOX delayed claiming	17	8	9	47.1%	7
EsimTBOX-G9-1 G9-Esim-TBOX delayed claiming	8	2	6	25.0%	5
24OXDYP1 G6-Reduce the concentration of cleaning fluid	31	26	5	83.9%	1
G9MY3231 SC-G9 Pasting the vehicle nameplate	13	10	3	76.9%	2
24OZYPN1 G6-Driver/Front passenger seat cushion improvement	5	3	2	60.0%	2
25WDCFN1-3 SC – G9 HV battery replacement	2	0	2	0.0%	2

Workload by campaign type

Campaign-type groupings show where unresolved cases are concentrated.

By campaign type

Segment	Total	Completed	Open	Completion
CIC(Customer Incoming service Campaign)	179	42	137	23.5%
PSC(Pre-delivery Service Campaign)	448	343	105	76.6%
SSC(Special Service Campaign)	232	186	46	80.2%
CNC(Customer Notification service Campaign)	5	3	2	60.0%

Completed records by year and quarter

Year	Quarter	Completed	Share of completed
Not recorded	Not recorded	574	100.0%

Vehicle and record attributes

Model, tier and delivery-status breakdowns of all open records. Small groups should be interpreted cautiously.

By vehicle model

Segment	Total	Completed	Open	Completion
G9_2024 AWD Performance	119	28	91	23.5%
New G6 RWD Long Range	237	175	62	73.8%
G9_2024 RWD Long Range	35	9	26	25.7%
New G6 AWD Performance	187	161	26	86.1%
P7+ RWD Long Range	36	13	23	36.1%
New G9 AWD Performance	56	35	21	62.5%
G6 RWD Long Range	95	80	15	84.2%
G6 RWD Standard Range	34	25	9	73.5%
G9 AWD Performance	12	5	7	41.7%
New G9 RWD Long Range	28	21	7	75.0%
G6 AWD Performance	23	21	2	91.3%
G9_2024 RWD Standard Range	1	0	1	0.0%

Delivery status and data completeness

Operational data gaps limit how confidently the cause or waiting time of open cases can be assessed.

By delivery status

Segment	Total	Completed	Open	Completion
Delivered	861	573	288	66.6%
Unsold	3	1	2	33.3%

By campaign tier

Segment	Total	Completed	Open	Completion
General	524	283	241	54.0%
Important	304	262	42	86.2%
Tier not recorded	31	26	5	83.9%
Very Important	5	3	2	60.0%

Missing operational fields

Data check	Missing	Records checked	Missing rate
Open records without a job order	290	290	100.0%
Open records without a completion date	290	290	100.0%
Records without an actual operating store	864	864	100.0%
Records without in-store time	864	864	100.0%
Records without repair status	864	864	100.0%
Records without settlement time	864	864	100.0%

Open cases have no job-order number or completion date; operating store, in-store time, repair status and settlement time are blank zone-wide. 290 open campaign records cover 226 distinct VINs. 251 VINs appear in multiple campaigns; 0 same-VIN/same-campaign duplicate key(s) add 0 extra row(s). Repeated VINs across different campaigns are not automatically errors. Check source records before assigning cause or age.

Dealership and campaign hotspots

Top dealership/campaign combinations by open records. Each combination shows its own completion rate and its share of all 290 open zone records.

Dealership	Campaign	Total	Open	Completion	Zone open share
XPENG Service Center Le Cannet x Mozart Autos	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	30	19	36.7%	6.6%
XPENG Service Center Valence x Jean Lain Mobilités	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	18	18	0.0%	6.2%
XPENG Service Center Montpellier x GRIM	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	15	15	0.0%	5.2%
XPENG Service Center Aix-en-Provence x Deffeuille	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	11	11	0.0%	3.8%
XPENG Service Center Toulouse x De Boussac	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	11	11	0.0%	3.8%
XPENG Service Center Bandol x Etoile 83	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	9	9	0.0%	3.1%
XPENG Service Center Toulouse x De Boussac	**EsimTBOX-G6-1** G6-Esim-TBOX delayed claiming	9	8	11.1%	2.8%
XPENG Service Center Valence x Jean Lain Mobilités	**25OXDCP1** SC–G6 Repair the 12V Battery negative ground point	14	8	42.9%	2.8%
XPENG Service Center Bastia x Groupe SIA	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	6	6	0.0%	2.1%
XPENG Service Center Fréjus Mapauto	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	8	6	25.0%	2.1%
XPENG Service Center Montpellier x GRIM	**25OYKBN1** New G9/New G6 - UWB Smart Key Update	18	6	66.7%	2.1%
XPENG Service Center Marseille x Parascandola	**25OBTDN1** New G6 Cup Holder Replacement(Impressive Gray)	9	5	44.4%	1.7%
XPENG Service Center Marseille x Parascandola	**25OYKBN1** New G9/New G6 - UWB Smart Key Update	20	5	75.0%	1.7%
XPENG Service Center Toulouse x De Boussac	**EsimTBOX-G9-1** G9-Esim-TBOX delayed claiming	5	5	0.0%	1.7%
XPENG Service Center Valence x Jean Lain Mobilités	**25OTCGN2** G6 Electric tow hook label	8	5	37.5%	1.7%

Campaign and vehicle overlap

Cross-tabulation of campaign and vehicle model. This isolates specific technical populations for eligibility and repair checks.

Campaign / vehicle model	Total	Open	Completion	Zone open share
26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection G9_2024 AWD Performance	104	83	20.2%	28.6%
26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection G9_2024 RWD Long Range	26	23	11.5%	7.9%
25OTCGN2-1 — G9 Electric tow hook label New G9 AWD Performance	46	20	56.5%	6.9%
25OBTDN1 — New G6 Cup Holder Replacement(Impressive Gray) New G6 RWD Long Range	51	19	62.7%	6.6%
25OBTDN1-1 — New G6 Cup Holder Replacement(Dark Gray) New G6 RWD Long Range	47	17	63.8%	5.9%
25OYKBN1 — New G9/New G6 - UWB Smart Key Update New G6 RWD Long Range	102	16	84.3%	5.5%
26OMBSI1-EU — P7 plus Front Exterior Door Handle Replacement P7+ RWD Long Range	20	14	30.0%	4.8%
25OTCGN2 — G6 Electric tow hook label New G6 RWD Long Range	37	10	73.0%	3.4%
25OTCGN2 — G6 Electric tow hook label New G6 AWD Performance	67	9	86.6%	3.1%
26OCGQI1-2 — P7plus - Height Sensor Inspection P7+ RWD Long Range	16	9	43.8%	3.1%
25OYKBN1 — New G9/New G6 - UWB Smart Key Update New G6 AWD Performance	68	7	89.7%	2.4%
26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection G9 AWD Performance	11	7	36.4%	2.4%
25OXDCP1 — SC–G6 Repair the 12V Battery negative ground point G6 RWD Long Range	61	6	90.2%	2.1%
EsimTBOX-G6-1 — G6-Esim-TBOX delayed claiming G6 RWD Long Range	10	6	40.0%	2.1%
25OBTDN1 — New G6 Cup Holder Replacement(Impressive Gray) New G6 AWD Performance	21	5	76.2%	1.7%

Top 10 dealerships by completion

Ranked by completion percentage, then by record volume. Case counts are shown so lower-volume results can be interpreted in context; ranking is descriptive, not a measure of repair quality.

R	a	n	k			
D	e	a	l	e	r	s
G	r	o	u	p		
R	e	c	o	r	d	s
C	o	m	p	l	e	t
O	p	e	n			
C	o	m	p	l	e	t
1	XPENG Service Center Nice x Mozart Autos	Mozart Autos	54	51	3	94.4%
2	XPENG Service Center Fréjus Mapauto	Group not specified	93	83	10	89.2%
3	XPENG Service Center Nîmes x Grim	Grim	39	33	6	84.6%
4	XPENG Service Center Bastia x Groupe SIA	Groupe SIA	33	26	7	78.8%
5	XPENG Service Center Gap x Mazet	Mazet	12	9	3	75.0%
6	XPENG Service Center Le Cannet x Mozart Autos	Mozart Autos	125	93	32	74.4%
7	XPENG Service Center Béziers x GRIM	GRIM	39	29	10	74.4%
8	XPENG Service Center Rodez x Garage Negrier	Garage Negrier	31	23	8	74.2%
9	XPENG Service RVO Clermont-Ferrand France	Group not specified	34	23	11	67.6%
10	XPENG Service Center Marseille x Parascandola	Parascandola	60	40	20	66.7%