Dealership Progress Report

XPENG Car Avenue Colmar France

ZONE PERFORMANCE / Zone 2 / 26 October 2026

TOTAL CAMPAIGNS	FINISHED	TO BE FINISHED	COMPLETION RATE
14	6	8	42.9%
campaign records	campaign records	campaign records	6 of 14 finished

Campaign status

Status breakdown

Status	Total campaigns	Share of dealership total
To be finished	8	57.1%
Finished	6	42.9%

Where to investigate first

Campaign hotspot: 24OXDYP1 — G6-Reduce the concentration of cleaning fluid has 4 open of 8 records.

Vehicle signal: G6 RWD Standard Range has 6 open records.

8 open campaign records cover 4 distinct VINs.

VIN check: 2 VIN(s) appear in multiple campaigns; 6 extra row(s) repeat the same VIN and campaign (0 with conflicting statuses). Repeated VINs across different campaigns are not automatically errors.

These are observed workload patterns, not proof that this dealership caused the issue.

Data gap: 8 of 8 open cases lack a job-order number, and 8 lack a completion date. Check source-system data before attributing responsibility or estimating delay.

Campaigns driving open workload

Campaign case counts, completion and open workload for this dealership.

Campaign code / name	Total campaigns	Finished	To be finished	Completion rate	Extra to 85%
24OXDYP1 G6-Reduce the concentration of cleaning fluid	8	4	4	50.0%	3
24OZYPN1 G6-Driver/Front passenger seat cushion improvement	2	0	2	0.0%	2
26ODBXI1-1 G9 Wiring Harness Body Deputy Inspection	2	0	2	0.0%	2

By campaign type

Segment	Total campaigns	Finished	To be finished	Completion rate
PSC(Pre-delivery Service Campaign)	12	6	6	50.0%
CIC(Customer Incoming service Campaign)	2	0	2	0.0%

Vehicle and record detail

Use vehicle and tier concentrations to narrow a technical review; confirm against campaign eligibility and workshop evidence.

By vehicle model

Segment	Total campaigns	Finished	To be finished	Completion rate
G6 RWD Standard Range	6	0	6	0.0%
G9 AWD Performance	1	0	1	0.0%
G9 RWD Long Range	1	0	1	0.0%

By campaign tier

Segment	Total campaigns	Finished	To be finished	Completion rate
Tier not recorded	8	4	4	50.0%
General	2	0	2	0.0%
Important	4	2	2	50.0%

Campaign-by-campaign progress

Use this table to track completion and remaining workload.

Campaign code	Campaign	Total campaigns	Finished	To be finished	Completion rate
24OXDYP1	G6-Reduce the concentration of cleaning fluid	8	4	4	50.0%
24OZYPN1	G6-Driver/Front passenger seat cushion improvement	2	0	2	0.0%
25OXDCP1	SC–G6 Repair the 12V Battery negative ground point	2	2	0	100.0%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	2	0	2	0.0%