
Global Service Campaign Report — Zone 2

Executive summary and review priorities

ZONE PERFORMANCE / Zone 2 / 26 October 2026

OVERALL PROGRESS	REMAINING WORKLOAD	DEALERSHIPS WITH RECORDS BELOW TARGET	CAMPAIGNS BELOW TARGET
46.6%	**411**	**21**	**18**
358 completed out of 769	records still to complete	of 26 assigned dealerships; 5 have no campaign records	of 19 campaigns

Finished campaign records by dealership



Meeting takeaways

Overall: 358 of 769 records completed (46.6%); 411 remain.

Dealerships to review first: XPENG Service Center Mulhouse x CAR Avenue has 74 open (35.7% complete).

Largest campaign backlog: 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection has 116 open of 124 cases.

Campaign/model overlap: 69 open of 76 for 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection / G9_2024 AWD Performance.

Campaign type PSC(Pre-delivery Service Campaign): 200 open of 509; leading model G9_2024 AWD Performance: 89 open of 107.

VIN check: 130 VINs appear in multiple campaigns; 193 extra row(s) repeat the same VIN and campaign (0 with conflicting statuses).

All findings are workload signals, not proof of dealership fault. Open cases lack job-order numbers and completion dates; verify source records before attributing cause or estimating delay.

Workload by status

Status	Records	Share of total
To be finished	407	52.9%
Finished	358	46.6%
Repair processing	4	0.5%

Dealership progress — campaign records present

Dealerships with campaign records. Progress bars are color-coded against the 85% reference target. 26 assigned sites are listed in the coverage table.

Dealership	Total	Completed	Open	Completion	Zone open share
XPENG Service Center Lyon x Jean Lain Mobilités	157	91	66	58.0%	16.1%
XPENG Service Center Mulhouse x CAR Avenue	115	41	74	35.7%	18.0%
XPENG Service Center Metz x CAR Avenue	98	38	60	38.8%	14.6%
XPENG Service Center Grenoble x Jean Lain Mobilités	78	41	37	52.6%	9.0%
XPENG Service Center Nancy x CAR Avenue	75	40	35	53.3%	8.5%
XPENG Service Center Chalon x SUMA	43	19	24	44.2%	5.8%
XPENG Service Center Annemasse x Jean Lain Mobilités	29	15	14	51.7%	3.4%
XPENG Service Center Chambery x Delta Savoie	26	14	12	53.8%	2.9%
XPENG Service Troyes x Froment	25	16	9	64.0%	2.2%
XPENG Service Center Annecy x Jean Lain Mobilités	23	3	20	13.0%	4.9%
XPENG Service Center Saint-Étienne x TLA Automobiles	23	11	12	47.8%	2.9%
XPENG Car Avenue Colmar France	14	6	8	42.9%	1.9%
XPENG Service Center Albertville x Delta Savoie	13	11	2	84.6%	0.5%
XPENG Service Center Bourg-en-Bresse x RX Automobiles	11	4	7	36.4%	1.7%
XPENG Service Center Bellegarde x RX Automobiles	10	4	6	40.0%	1.5%
XPENG Service Center Belfort x Nedey Automobiles	8	0	8	0.0%	1.9%

Dealership	Total	Completed	Open	Completion	Zone open share
XPENG Service Center Bourges x Murat Motors	7	0	7	0.0%	1.7%
XPENG Service Center Épinal x Bertrand	6	3	3	50.0%	0.7%
XPENG Service Center Strasbourg × Passion Automobiles	3	0	3	0.0%	0.7%
XPENG Service Center Villefranche-sur-Saône Thivolle	3	1	2	33.3%	0.5%
XPENG Service Center Dijon × Passion Automobiles	2	0	2	0.0%	0.5%

Zone total: 358 completed of 769 records (46.6%). Records without a dealership: 0.

Assigned dealership coverage

This list includes every site from the After-Sales zone file. Sites without matching campaign rows show zero; no campaign records are inferred for them.

Dealership site	Total campaigns	Finished	To be finished	Completion rate	Campaign data
Bernard Montélimar	0	0	0	—	No campaign records
Bertrand Epinal	6	3	3	50.0%	Campaign records found
Car Avenue Longwy	0	0	0	—	No campaign records
Car Avenue Metz	98	38	60	38.8%	Campaign records found
Car Avenue Mulhouse	129	47	82	36.4%	Campaign records found
Car Avenue Nancy	75	40	35	53.3%	Campaign records found
Cassard Besançon	0	0	0	—	No campaign records
Deffeuille Lons-Le-Saunier	0	0	0	—	No campaign records
Deffeuille Pontarlier	0	0	0	—	No campaign records
Delta Savoie Albertville	13	11	2	84.6%	Campaign records found
Delta Savoie Chambéry	26	14	12	53.8%	Campaign records found
DPI Montluçon	0	0	0	—	No campaign records
Froment Troyes	25	16	9	64.0%	Campaign records found
Jean Lain Annecy	23	3	20	13.0%	Campaign records found
Jean Lain Annemasse	29	15	14	51.7%	Campaign records found
Jean Lain Grenoble	78	41	37	52.6%	Campaign records found
Jean Lain Vénissieux	157	91	66	58.0%	Campaign records found
Murat Bourges	7	0	7	0.0%	Campaign records found
Nedey Belfort	8	0	8	0.0%	Campaign records found

Dealership site	Total campaigns	Finished	To be finished	Completion rate	Campaign data
Passion Dijon	2	0	2	0.0%	Campaign records found
Passion Strasbourg	3	0	3	0.0%	Campaign records found
RX Autos Bellegarde-sur-Valserine	10	4	6	40.0%	Campaign records found
RX Autos Bourg-en-Bresse	11	4	7	36.4%	Campaign records found
Suma Chalon-sur-Saône	43	19	24	44.2%	Campaign records found
Thivolle Villefranche-sur-Saône	3	1	2	33.3%	Campaign records found
TLA Saint-Etienne	23	11	12	47.8%	Campaign records found

Dealerships to review

21 of 21 dealerships with campaign records are below the 85% target. Highest workloads are listed first.

Dealership	Total	Completed	Open	Completion	Extra to 85%	Zone open sh
XPENG Service Center Mulhouse x CAR Avenue	115	41	74	35.7%	57	18.0%
XPENG Service Center Lyon x Jean Lain Mobilités	157	91	66	58.0%	43	16.1%
XPENG Service Center Metz x CAR Avenue	98	38	60	38.8%	46	14.6%
XPENG Service Center Grenoble x Jean Lain Mobilités	78	41	37	52.6%	26	9.0%
XPENG Service Center Nancy x CAR Avenue	75	40	35	53.3%	24	8.5%
XPENG Service Center Chalon x SUMA	43	19	24	44.2%	18	5.8%
XPENG Service Center Annecy x Jean Lain Mobilités	23	3	20	13.0%	17	4.9%
XPENG Service Center Annemasse x Jean Lain Mobilités	29	15	14	51.7%	10	3.4%
XPENG Service Center Saint-Étienne x TLA Automobiles	23	11	12	47.8%	9	2.9%
XPENG Service Center Chambery x Delta Savoie	26	14	12	53.8%	9	2.9%
XPENG Service Troyes x Froment	25	16	9	64.0%	6	2.2%
XPENG Service Center Belfort x Nedey Automobiles	8	0	8	0.0%	7	1.9%
XPENG Car Avenue Colmar France	14	6	8	42.9%	6	1.9%
XPENG Service Center Bourges x Murat Motors	7	0	7	0.0%	6	1.7%
XPENG Service Center Bourg-en-Bresse x RX Automobiles	11	4	7	36.4%	6	1.7%
XPENG Service Center Bellegarde x RX Automobiles	10	4	6	40.0%	5	1.5%

Dealership	Total	Completed	Open	Completion	Extra to 85%	Zone open sh
XPENG Service Center Strasbourg × Passion Automobiles	3	0	3	0.0%	3	0.7%
XPENG Service Center Épinal x Bertrand	6	3	3	50.0%	3	0.7%
XPENG Service Center Dijon × Passion Automobiles	2	0	2	0.0%	2	0.5%
XPENG Service Center Villefranche-sur-Saône Thivolle	3	1	2	33.3%	2	0.5%
XPENG Service Center Albertville x Delta Savoie	13	11	2	84.6%	1	0.5%

Campaigns to review

Campaigns below target, ranked by remaining records.

Campaign code	Campaign	Total	Completed	Remaining	Progress	Extra to 85%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	124	8	116	6.5%	98
25OXDCP1	SC–G6 Repair the 12V Battery negative ground point	196	132	64	67.3%	35
25OTCGN2	G6 Electric tow hook label	88	51	37	58.0%	24
G9MY3231	SC-G9 Pasting the vehicle nameplate	48	12	36	25.0%	29
24OXDYP1	G6-Reduce the concentration of cleaning fluid	106	72	34	67.9%	19
25OTCGN2-1	G9 Electric tow hook label	42	19	23	45.2%	17
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	42	19	23	45.2%	17
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	18	0	18	0.0%	16
26OCGQI1-2	P7plus - Height Sensor Inspection	18	1	17	5.6%	15
25OYKBN1	New G9/New G6 - UWB Smart Key Update	30	15	15	50.0%	11
24OZYPN1	G6-Driver/Front passenger seat cushion improvement	24	10	14	41.7%	11
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	9	4	5	44.4%	4
24ODHBN1-3	Corrosion prevention of battery pack bottom-G9-1	4	2	2	50.0%	2
EsimTBOX-G9-1	G9-Esim-TBOX delayed claiming	5	3	2	60.0%	2
24ODHBN1-04	Corrosion prevention of battery pack bottom-G9-2	6	4	2	66.7%	2
26OXLSI1	G6 front axle bolts torque not meet SPEC	1	0	1	0.0%	1

Campaign code	Campaign	Total	Completed	Remaining	Progress	Extra to 85%
25WDCFN1	SC–G6 HV battery replacement	1	0	1	0.0%	1
EsimTBOX-G6-1	G6-Esim-TBOX delayed claiming	5	4	1	80.0%	1

Campaign and process drivers

Open cases grouped by campaign and campaign type. Completion bars show the share of records already finished.

Campaign code / name	Total	Completed	Open	Progress	Extra to 85%
26ODBXI1-1 G9 Wiring Harness Body Deputy Inspection	124	8	116	6.5%	98
25OXDCP1 SC–G6 Repair the 12V Battery negative ground point	196	132	64	67.3%	35
25OTCGN2 G6 Electric tow hook label	88	51	37	58.0%	24
G9MY3231 SC-G9 Pasting the vehicle nameplate	48	12	36	25.0%	29
24OXDYP1 G6-Reduce the concentration of cleaning fluid	106	72	34	67.9%	19
25OBTDN1 New G6 Cup Holder Replacement(Impressive Gray)	42	19	23	45.2%	17
25OTCGN2-1 G9 Electric tow hook label	42	19	23	45.2%	17
26OMBSI1-EU P7 plus Front Exterior Door Handle Replacement	18	0	18	0.0%	16
26OCGQI1-2 P7plus - Height Sensor Inspection	18	1	17	5.6%	15
25OYKBN1 New G9/New G6 - UWB Smart Key Update	30	15	15	50.0%	11
24OZYPN1 G6-Driver/Front passenger seat cushion improvement	24	10	14	41.7%	11
25OBTDN1-1 New G6 Cup Holder Replacement(Dark Gray)	9	4	5	44.4%	4
24ODHBN1-04 Corrosion prevention of battery pack bottom-G9-2	6	4	2	66.7%	2
24ODHBN1-3 Corrosion prevention of battery pack bottom-G9-1	4	2	2	50.0%	2
EsimTBOX-G9-1 G9-Esim-TBOX delayed claiming	5	3	2	60.0%	2
25WDCFN1 SC–G6 HV battery replacement	1	0	1	0.0%	1

Campaign code / name	Total	Completed	Open	Progress	Extra to 85%
26OXLSI1 G6 front axle bolts torque not meet SPEC	1	0	1	0.0%	1
EsimTBOX-G6-1 G6-Esim-TBOX delayed claiming	5	4	1	80.0%	1

Workload by campaign type

Campaign-type groupings show where unresolved cases are concentrated.

By campaign type

Segment	Total	Completed	Open	Completion
PSC(Pre-delivery Service Campaign)	509	309	200	60.7%
CIC(Customer Incoming service Campaign)	171	15	156	8.8%
SSC(Special Service Campaign)	88	34	54	38.6%
CNC(Customer Notification service Campaign)	1	0	1	0.0%

Completed records by year and quarter

Year	Quarter	Completed	Share of completed
Not recorded	Not recorded	358	100.0%

Vehicle and record attributes

Model, tier and delivery-status breakdowns of all open records. Small groups should be interpreted cautiously.

By vehicle model

Segment	Total	Completed	Open	Completion
G9_2024 AWD Performance	107	18	89	16.8%
G6 RWD Standard Range	130	77	53	59.2%
G6 RWD Long Range	174	122	52	70.1%
G9_2024 RWD Long Range	49	3	46	6.1%
New G6 AWD Performance	107	62	45	57.9%
New G6 RWD Long Range	61	26	35	42.6%
P7+ RWD Long Range	36	1	35	2.8%
New G9 AWD Performance	37	17	20	45.9%
G9 AWD Performance	17	6	11	35.3%
G6 AWD Performance	28	19	9	67.9%
G9_2024 RWD Standard Range	7	2	5	28.6%
G9 RWD Long Range	4	0	4	0.0%
G9 RWD Standard Range	5	2	3	40.0%
New G9 RWD Long Range	5	2	3	40.0%
G6 DE RWD Standard Range	2	1	1	50.0%

Delivery status and data completeness

Operational data gaps limit how confidently the cause or waiting time of open cases can be assessed.

By delivery status

Segment	Total	Completed	Open	Completion
Delivered	752	354	398	47.1%
Unsold	17	4	13	23.5%

By campaign tier

Segment	Total	Completed	Open	Completion
General	351	109	242	31.1%
Important	307	175	132	57.0%
Tier not recorded	110	74	36	67.3%
Very Important	1	0	1	0.0%

Missing operational fields

Data check	Missing	Records checked	Missing rate
Open records without a job order	407	411	99.0%
Open records without a completion date	411	411	100.0%
Records without an actual operating store	765	769	99.5%
Records without in-store time	765	769	99.5%
Records without repair status	765	769	99.5%
Records without settlement time	769	769	100.0%

Open cases have no job-order number or completion date; operating store, in-store time, repair status and settlement time are blank zone-wide. 411 open campaign records cover 270 distinct VINs. 130 VINs appear in multiple campaigns; 193 same-VIN/same-campaign duplicate key(s) add 193 extra row(s). Repeated VINs across different campaigns are not automatically errors. Check source records before assigning cause or age.

Dealership and campaign hotspots

Top dealership/campaign combinations by open records. Each combination shows its own completion rate and its share of all 411 open zone records.

Dealership	Campaign	Total	Open	Completion	Zone open share
XPENG Service Center Lyon x Jean Lain Mobilités	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	30	27	10.0%	6.6%
XPENG Service Center Metz x CAR Avenue	**25OXDCP1** SC–G6 Repair the 12V Battery negative ground point	46	20	56.5%	4.9%
XPENG Service Center Mulhouse x CAR Avenue	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	18	18	0.0%	4.4%
XPENG Service Center Mulhouse x CAR Avenue	**24OXDYP1** G6-Reduce the concentration of cleaning fluid	22	14	36.4%	3.4%
XPENG Service Center Mulhouse x CAR Avenue	**25OXDCP1** SC–G6 Repair the 12V Battery negative ground point	28	12	57.1%	2.9%
XPENG Service Center Chalon x SUMA	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	11	11	0.0%	2.7%
XPENG Service Center Metz x CAR Avenue	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	11	11	0.0%	2.7%
XPENG Service Center Lyon x Jean Lain Mobilités	**G9MY3231** SC-G9 Pasting the vehicle nameplate	12	10	16.7%	2.4%
XPENG Service Center Mulhouse x CAR Avenue	**G9MY3231** SC-G9 Pasting the vehicle nameplate	14	10	28.6%	2.4%
XPENG Service Center Grenoble x Jean Lain Mobilités	**25OTCGN2** G6 Electric tow hook label	11	9	18.2%	2.2%
XPENG Service Center Grenoble x Jean Lain Mobilités	**25OXDCP1** SC–G6 Repair the 12V Battery negative ground point	26	8	69.2%	1.9%
XPENG Service Center Nancy x CAR Avenue	**25OXDCP1** SC–G6 Repair the 12V Battery negative ground point	26	8	69.2%	1.9%
XPENG Service Center Nancy x CAR Avenue	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	7	7	0.0%	1.7%
XPENG Service Center Annemasse x Jean Lain Mobilités	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	6	6	0.0%	1.5%
XPENG Service Center Chambery x Delta Savoie	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	8	6	25.0%	1.5%

Campaign and vehicle overlap

Cross-tabulation of campaign and vehicle model. This isolates specific technical populations for eligibility and repair checks.

Campaign / vehicle model	Total	Open	Completion	Zone open share
26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection G9_2024 AWD Performance	76	69	9.2%	16.8%
25OXDCP1 — SC–G6 Repair the 12V Battery negative ground point G6 RWD Long Range	124	40	67.7%	9.7%
25OTCGN2 — G6 Electric tow hook label New G6 AWD Performance	66	28	57.6%	6.8%
26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection G9_2024 RWD Long Range	28	28	0.0%	6.8%
24OXDYP1 — G6-Reduce the concentration of cleaning fluid G6 RWD Standard Range	68	26	61.8%	6.3%
25OTCGN2-1 — G9 Electric tow hook label New G9 AWD Performance	37	20	45.9%	4.9%
26OMBSI1-EU — P7 plus Front Exterior Door Handle Replacement P7+ RWD Long Range	18	18	0.0%	4.4%
G9MY3231 — SC-G9 Pasting the vehicle nameplate G9_2024 AWD Performance	28	18	35.7%	4.4%
G9MY3231 — SC-G9 Pasting the vehicle nameplate G9_2024 RWD Long Range	20	18	10.0%	4.4%
26OCGQI1-2 — P7plus - Height Sensor Inspection P7+ RWD Long Range	18	17	5.6%	4.1%
25OBTDN1 — New G6 Cup Holder Replacement(Impressive Gray) New G6 RWD Long Range	21	16	23.8%	3.9%
25OXDCP1 — SC–G6 Repair the 12V Battery negative ground point G6 RWD Standard Range	46	16	65.2%	3.9%
26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection G9 AWD Performance	11	11	0.0%	2.7%
24OZYPN1 — G6-Driver/Front passenger seat cushion improvement G6 RWD Standard Range	14	10	28.6%	2.4%
25OYKBN1 — New G9/New G6 - UWB Smart Key Update New G6 RWD Long Range	16	10	37.5%	2.4%

Top 10 dealerships by completion rate

Ranked by completion percentage, then by record volume. Case counts are shown so lower-volume results can be interpreted in context; ranking is descriptive, not a measure of repair quality.

Rank	Dealership	Network	Cases	Completed	Open	Completion
1	XPENG Service Center Albertville x Delta Savoie	Delta Savoie	13	11	2	84.6%
2	XPENG Service Troyes x Froment	Froment	25	16	9	64.0%
3	XPENG Service Center Lyon x Jean Lain Mobilités	Jean Lain Mobilités	157	91	66	58.0%
4	XPENG Service Center Chambery x Delta Savoie	Delta Savoie	26	14	12	53.8%
5	XPENG Service Center Nancy x CAR Avenue	CAR Avenue	75	40	35	53.3%
6	XPENG Service Center Grenoble x Jean Lain Mobilités	Jean Lain Mobilités	78	41	37	52.6%
7	XPENG Service Center Annemasse x Jean Lain Mobilités	Jean Lain Mobilités	29	15	14	51.7%
8	XPENG Service Center Épinal x Bertrand	Bertrand	6	3	3	50.0%
9	XPENG Service Center Saint-Étienne x TLA Automobiles	TLA Automobiles	23	11	12	47.8%
10	XPENG Service Center Chalon x SUMA	SUMA	43	19	24	44.2%

Top 10 dealerships by finished cases

Ranked by the number of records with Status = Finished. Record totals and completion rates are shown for context.

Rank	Dealership	Group	Total campaigns	Finished	To be finished	Completion rate
1	XPENG Service Center Lyon x Jean Lain Mobilités	Jean Lain Mobilités	157	91	66	58.0%
2	XPENG Service Center Mulhouse x CAR Avenue	CAR Avenue	115	41	74	35.7%
3	XPENG Service Center Grenoble x Jean Lain Mobilités	Jean Lain Mobilités	78	41	37	52.6%
4	XPENG Service Center Nancy x CAR Avenue	CAR Avenue	75	40	35	53.3%
5	XPENG Service Center Metz x CAR Avenue	CAR Avenue	98	38	60	38.8%
6	XPENG Service Center Chalon x SUMA	SUMA	43	19	24	44.2%
7	XPENG Service Troyes x Froment	Froment	25	16	9	64.0%
8	XPENG Service Center Annemasse x Jean Lain Mobilités	Jean Lain Mobilités	29	15	14	51.7%
9	XPENG Service Center Chambery x Delta Savoie	Delta Savoie	26	14	12	53.8%

Rank	Dealership	Group	Total campaigns	Finished	To be finished	Completion rate
10	XPENG Service Center Saint-Étienne x TLA Automobiles	TLA Automobiles	23	11	12	47.8%