Global Service Campaign Report — Zone 4

Executive summary and review priorities

ZONE PERFORMANCE / Zone 4 / 26 October 2026

OVERALL PROGRESS	REMAINING WORKLOAD	DEALERSHIPS WITH RECORDS BELOW TARGET	CAMPAIGNS BELOW TARGET
64.6%	**280**	**17**	**13**
510 completed out of 790	records still to complete	of 27 assigned dealerships; 8 have no campaign records	of 17 campaigns

Finished campaign records by dealership



Meeting takeaways

Overall: 510 of 790 records completed (64.6%); 280 remain.

Dealerships to review first: XPENG Service Center Valence x Jean Lain Mobilités has 63 open (33.0% complete).

Largest campaign backlog: 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection has 123 open of 142 cases.

Campaign/model overlap: 89 open of 104 for 26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection / G9_2024 AWD Performance.

Campaign type CIC(Customer Incoming service Campaign): 148 open of 180; leading model G9_2024 AWD Performance: 99 open of 125.

VIN check: 124 VINs appear in multiple campaigns; 141 extra row(s) repeat the same VIN and campaign (0 with conflicting statuses).

All findings are workload signals, not proof of dealership fault. Open cases lack job-order numbers and completion dates; verify source records before attributing cause or estimating delay.

Workload by status

Status	Records	Share of total
Finished	510	64.6%
To be finished	280	35.4%

Dealership progress — campaign records present

Dealerships with campaign records. Progress bars are color-coded against the 85% reference target. 27 assigned sites are listed in the coverage table.

Dealership	Total	Completed	Open	Completion	Zone open share
XPENG Service Center Le Cannet x Mozart Autos	151	114	37	75.5%	13.2%
XPENG Service Center Valence x Jean Lain Mobilités	94	31	63	33.0%	22.5%
XPENG Service Center Fréjus Mapauto	71	62	9	87.3%	3.2%
XPENG Service Center Nice x Mozart Autos	65	60	5	92.3%	1.8%
XPENG Service Center Montpellier x GRIM	60	32	28	53.3%	10.0%
XPENG Service Center Toulouse De Boussac	53	21	32	39.6%	11.4%
XPENG Service Center Aix-en-Provence x Deffeuille	47	26	21	55.3%	7.5%
XPENG Service Center Bastia x Groupe SIA	46	39	7	84.8%	2.5%
XPENG Service Center Marseille x Parascandola	41	26	15	63.4%	5.4%
XPENG Service RVO Clermont-Ferrand France	29	18	11	62.1%	3.9%
XPENG Service Center Nîmes x Grim	27	22	5	81.5%	1.8%
XPENG Service Center Béziers x GRIM	25	18	7	72.0%	2.5%
XPENG Service Center Bandol x Etoile 83	22	7	15	31.8%	5.4%
XPENG Service Center Perpignan x LG	19	10	9	52.6%	3.2%
XPENG Service Center Rodez Negrier	18	12	6	66.7%	2.1%
XPENG Service Center Gap x Mazet	8	6	2	75.0%	0.7%

Dealership	Total	Completed	Open	Completion	Zone open share
XPENG Service Center Toulon Est x Etoile 83	7	4	3	57.1%	1.1%
XPENG Service Center Limoges x LG	5	2	3	40.0%	1.1%
XPENG Service Center Perigueux x LG	2	0	2	0.0%	0.7%

Zone total: 510 completed of 790 records (64.6%). Records without a dealership: 0.

Assigned dealership coverage

This list includes every site from the After-Sales zone file. Sites without matching campaign rows show zero; no campaign records are inferred for them.

Dealership site	Total campaigns	Finished	To be finished	Completion rate	Campaign data
Amadeus Cannes	151	114	37	75.5%	Campaign records found
Amadeus Nice	65	60	5	92.3%	Campaign records found
De Boussac Toulouse	53	21	32	39.6%	Campaign records found
Deffeuille Aix-en-Provence	47	26	21	55.3%	Campaign records found
Delenne Alès	0	0	0	—	No campaign records
Etoile 83 Bandol	22	7	15	31.8%	Campaign records found
Etoile 83 Toulon-Est	7	4	3	57.1%	Campaign records found
GGA Arles	0	0	0	—	No campaign records
Grim Avignon	0	0	0	—	No campaign records
Grim Béziers	25	18	7	72.0%	Campaign records found
Grim Montpellier	60	32	28	53.3%	Campaign records found
Grim Nîmes	27	22	5	81.5%	Campaign records found
Jean Lain Valence	94	31	63	33.0%	Campaign records found
LG Brive-la-Gaillarde	0	0	0	—	No campaign records
LG Carcassonne	0	0	0	—	No campaign records
LG Castres	0	0	0	—	No campaign records
LG Limoges	5	2	3	40.0%	Campaign records found
LG Perpignan	19	10	9	52.6%	Campaign records found

Dealership site	Total campaigns	Finished	To be finished	Completion rate	Campaign data
LG Périgueux	2	0	2	0.0%	Campaign records found
Mapauto Fréjus	71	62	9	87.3%	Campaign records found
Mazet Gap	8	6	2	75.0%	Campaign records found
Milanesio Salon-de-Provence	0	0	0	—	No campaign records
Negrier Rodez	18	12	6	66.7%	Campaign records found
Parascandola Marseille	41	26	15	63.4%	Campaign records found
Parascandola Vitrolles	0	0	0	—	No campaign records
RVO Clermont-Ferrand	29	18	11	62.1%	Campaign records found
SIA Biguglia	46	39	7	84.8%	Campaign records found

Dealerships to review

17 of 19 dealerships with campaign records are below the 85% target. Highest workloads are listed first.

Dealership	Total	Completed	Open	Completion	Extra to 85%	Zone open share
XPENG Service Center Valence x Jean Lain Mobilités	94	31	63	33.0%	49	22.5%
XPENG Service Center Le Cannet x Mozart Autos	151	114	37	75.5%	15	13.2%
XPENG Service Center Toulouse De Boussac	53	21	32	39.6%	25	11.4%
XPENG Service Center Montpellier x GRIM	60	32	28	53.3%	19	10.0%
XPENG Service Center Aix-en-Provence x Deffeuille	47	26	21	55.3%	14	7.5%
XPENG Service Center Bandol x Etoile 83	22	7	15	31.8%	12	5.4%
XPENG Service Center Marseille x Parascandola	41	26	15	63.4%	9	5.4%
XPENG Service RVO Clermont-Ferrand France	29	18	11	62.1%	7	3.9%
XPENG Service Center Perpignan x LG	19	10	9	52.6%	7	3.2%
XPENG Service Center Béziers x GRIM	25	18	7	72.0%	4	2.5%
XPENG Service Center Bastia x Groupe SIA	46	39	7	84.8%	1	2.5%
XPENG Service Center Rodez Negrier	18	12	6	66.7%	4	2.1%
XPENG Service Center Nîmes x Grim	27	22	5	81.5%	1	1.8%
XPENG Service Center Limoges x LG	5	2	3	40.0%	3	1.1%
XPENG Service Center Toulon Est x Etoile 83	7	4	3	57.1%	2	1.1%
XPENG Service Center Perigueux x LG	2	0	2	0.0%	2	0.7%

Dealership	Total	Completed	Open	Completion	Extra to 85%	Zone open share
XPENG Service Center Gap x Mazet	8	6	2	75.0%	1	0.7%

Campaigns to review

Campaigns below target, ranked by remaining records.

Campaign code	Campaign	Total	Completed	Remaining	Progress	Extra to 85%
26ODBXI1-1	G9 Wiring Harness Body Deputy Inspection	142	19	123	13.4%	102
25OTCGN2-1	G9 Electric tow hook label	60	36	24	60.0%	15
25OBTDN1	New G6 Cup Holder Replacement(Impressive Gray)	72	48	24	66.7%	14
25OTCGN2	G6 Electric tow hook label	111	90	21	81.1%	5
26OMBSI1-EU	P7 plus Front Exterior Door Handle Replacement	20	4	16	20.0%	13
24OXDYP1	G6-Reduce the concentration of cleaning fluid	62	52	10	83.9%	1
26OCGQI1-2	P7plus - Height Sensor Inspection	16	7	9	43.8%	7
EsimTBOX-G6-1	G6-Esim-TBOX delayed claiming	17	8	9	47.1%	7
EsimTBOX-G9-1	G9-Esim-TBOX delayed claiming	8	2	6	25.0%	5
G9MY3231	SC-G9 Pasting the vehicle nameplate	26	20	6	76.9%	3
24OZYPN1	G6-Driver/Front passenger seat cushion improvement	10	6	4	60.0%	3
25OBTDN1-1	New G6 Cup Holder Replacement(Dark Gray)	9	6	3	66.7%	2
25WDCFN1-3	SC – G9 HV battery replacement	2	0	2	0.0%	2

Campaign and process drivers

Open cases grouped by campaign and campaign type. Completion bars show the share of records already finished.

Campaign code / name	Total	Completed	Open	Progress	Extra to 85%
26ODBXI1-1 G9 Wiring Harness Body Deputy Inspection	142	19	123	13.4%	102
25OBTDN1 New G6 Cup Holder Replacement(Impressive Gray)	72	48	24	66.7%	14
25OTCGN2-1 G9 Electric tow hook label	60	36	24	60.0%	15
25OTCGN2 G6 Electric tow hook label	111	90	21	81.1%	5
25OXDCP1 SC–G6 Repair the 12V Battery negative ground point	182	164	18	90.1%	0
26OMBSI1-EU P7 plus Front Exterior Door Handle Replacement	20	4	16	20.0%	13
24OXDYP1 G6-Reduce the concentration of cleaning fluid	62	52	10	83.9%	1
26OCGQI1-2 P7plus - Height Sensor Inspection	16	7	9	43.8%	7
EsimTBOX-G6-1 G6-Esim-TBOX delayed claiming	17	8	9	47.1%	7
EsimTBOX-G9-1 G9-Esim-TBOX delayed claiming	8	2	6	25.0%	5
G9MY3231 SC-G9 Pasting the vehicle nameplate	26	20	6	76.9%	3
25OYKBN1 New G9/New G6 - UWB Smart Key Update	48	43	5	89.6%	0
24OZYPN1 G6-Driver/Front passenger seat cushion improvement	10	6	4	60.0%	3
25OBTDN1-1 New G6 Cup Holder Replacement(Dark Gray)	9	6	3	66.7%	2
25WDCFN1-3 SC – G9 HV battery replacement	2	0	2	0.0%	2

Workload by campaign type

Campaign-type groupings show where unresolved cases are concentrated.

By campaign type

Segment	Total	Completed	Open	Completion
CIC(Customer Incoming service Campaign)	180	32	148	17.8%
PSC(Pre-delivery Service Campaign)	506	402	104	79.4%
SSC(Special Service Campaign)	99	73	26	73.7%
CNC(Customer Notification service Campaign)	5	3	2	60.0%

Completed records by year and quarter

Year	Quarter	Completed	Share of completed
Not recorded	Not recorded	510	100.0%

Vehicle and record attributes

Model, tier and delivery-status breakdowns of all open records. Small groups should be interpreted cautiously.

By vehicle model

Segment	Total	Completed	Open	Completion
G9_2024 AWD Performance	125	26	99	20.8%
New G6 RWD Long Range	128	93	35	72.7%
G9_2024 RWD Long Range	42	13	29	31.0%
P7+ RWD Long Range	36	11	25	30.6%
G6 RWD Long Range	172	149	23	86.6%
New G9 AWD Performance	46	25	21	54.3%
New G6 AWD Performance	105	88	17	83.8%
G6 RWD Standard Range	66	50	16	75.8%
G9 AWD Performance	13	5	8	38.5%
G6 AWD Performance	41	38	3	92.7%
New G9 RWD Long Range	14	11	3	78.6%
G9_2024 RWD Standard Range	1	0	1	0.0%

Delivery status and data completeness

Operational data gaps limit how confidently the cause or waiting time of open cases can be assessed.

By delivery status

Segment	Total	Completed	Open	Completion
Delivered	785	508	277	64.7%
Unsold	5	2	3	40.0%

By campaign tier

Segment	Total	Completed	Open	Completion
General	455	220	235	48.4%
Important	268	235	33	87.7%
Tier not recorded	62	52	10	83.9%
Very Important	5	3	2	60.0%

Missing operational fields

Data check	Missing	Records checked	Missing rate
Open records without a job order	280	280	100.0%
Open records without a completion date	280	280	100.0%
Records without an actual operating store	790	790	100.0%
Records without in-store time	790	790	100.0%
Records without repair status	790	790	100.0%
Records without settlement time	790	790	100.0%

Open cases have no job-order number or completion date; operating store, in-store time, repair status and settlement time are blank zone-wide. 280 open campaign records cover 225 distinct VINs. 124 VINs appear in multiple campaigns; 141 same-VIN/same-campaign duplicate key(s) add 141 extra row(s). Repeated VINs across different campaigns are not automatically errors. Check source records before assigning cause or age.

Dealership and campaign hotspots

Top dealership/campaign combinations by open records. Each combination shows its own completion rate and its share of all 280 open zone records.

Dealership	Campaign	Total	Open	Completion	Zone open share
XPENG Service Center Le Cannet x Mozart Autos	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	30	24	20.0%	8.6%
XPENG Service Center Valence x Jean Lain Mobilités	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	18	18	0.0%	6.4%
XPENG Service Center Valence x Jean Lain Mobilités	**25OXDCP1** SC–G6 Repair the 12V Battery negative ground point	28	16	42.9%	5.7%
XPENG Service Center Montpellier x GRIM	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	15	15	0.0%	5.4%
XPENG Service Center Aix-en-Provence x Deffeuille	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	11	11	0.0%	3.9%
XPENG Service Center Toulouse De Boussac	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	11	11	0.0%	3.9%
XPENG Service Center Bandol x Etoile 83	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	9	9	0.0%	3.2%
XPENG Service Center Toulouse De Boussac	**EsimTBOX-G6-1** G6-Esim-TBOX delayed claiming	9	8	11.1%	2.9%
XPENG Service Center Valence x Jean Lain Mobilités	**24OXDYP1** G6-Reduce the concentration of cleaning fluid	20	8	60.0%	2.9%
XPENG Service Center Bastia x Groupe SIA	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	6	6	0.0%	2.1%
XPENG Service Center Fréjus Mapauto	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	8	6	25.0%	2.1%
XPENG Service Center Marseille x Parascandola	**25OBTDN1** New G6 Cup Holder Replacement(Impressive Gray)	9	5	44.4%	1.8%
XPENG Service Center Nice x Mozart Autos	**26ODBXI1-1** G9 Wiring Harness Body Deputy Inspection	9	5	44.4%	1.8%
XPENG Service Center Toulouse De Boussac	**EsimTBOX-G9-1** G9-Esim-TBOX delayed claiming	5	5	0.0%	1.8%
XPENG Service Center Valence x Jean Lain Mobilités	**25OTCGN2** G6 Electric tow hook label	8	5	37.5%	1.8%

Campaign and vehicle overlap

Cross-tabulation of campaign and vehicle model. This isolates specific technical populations for eligibility and repair checks.

Campaign / vehicle model	Total	Open	Completion	Zone open share
26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection G9_2024 AWD Performance	104	89	14.4%	31.8%
26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection G9_2024 RWD Long Range	26	25	3.8%	8.9%
25OTCGN2-1 — G9 Electric tow hook label New G9 AWD Performance	46	21	54.3%	7.5%
25OBTDN1 — New G6 Cup Holder Replacement(Impressive Gray) New G6 RWD Long Range	51	19	62.7%	6.8%
26OMBSI1-EU — P7 plus Front Exterior Door Handle Replacement P7+ RWD Long Range	20	16	20.0%	5.7%
25OXDCP1 — SC–G6 Repair the 12V Battery negative ground point G6 RWD Long Range	122	12	90.2%	4.3%
25OTCGN2 — G6 Electric tow hook label New G6 RWD Long Range	37	11	70.3%	3.9%
25OTCGN2 — G6 Electric tow hook label New G6 AWD Performance	67	9	86.6%	3.2%
26OCGQI1-2 — P7plus - Height Sensor Inspection P7+ RWD Long Range	16	9	43.8%	3.2%
26ODBXI1-1 — G9 Wiring Harness Body Deputy Inspection G9 AWD Performance	11	8	27.3%	2.9%
24OXDYP1 — G6-Reduce the concentration of cleaning fluid G6 RWD Standard Range	30	6	80.0%	2.1%
EsimTBOX-G6-1 — G6-Esim-TBOX delayed claiming G6 RWD Long Range	10	6	40.0%	2.1%
25OBTDN1 — New G6 Cup Holder Replacement(Impressive Gray) New G6 AWD Performance	21	5	76.2%	1.8%
24OXDYP1 — G6-Reduce the concentration of cleaning fluid G6 RWD Long Range	30	4	86.7%	1.4%
24OZYPN1 — G6-Driver/Front passenger seat cushion improvement G6 RWD Standard Range	8	4	50.0%	1.4%

Top 10 dealerships by completion rate

Ranked by completion percentage, then by record volume. Case counts are shown so lower-volume results can be interpreted in context; ranking is descriptive, not a measure of repair quality.

Rank	Dealership	Group	Records	Completed	Open	Completion
1	XPENG Service Center Nice x Mozart Autos	Mozart Autos	65	60	5	92.3%
2	XPENG Service Center Fréjus Mapauto	Group not specified	71	62	9	87.3%
3	XPENG Service Center Bastia x Groupe SIA	Groupe SIA	46	39	7	84.8%
4	XPENG Service Center Nîmes x Grim	Grim	27	22	5	81.5%
5	XPENG Service Center Le Cannet x Mozart Autos	Mozart Autos	151	114	37	75.5%
6	XPENG Service Center Gap x Mazet	Mazet	8	6	2	75.0%
7	XPENG Service Center Béziers x GRIM	GRIM	25	18	7	72.0%
8	XPENG Service Center Rodez Negrier	Group not specified	18	12	6	66.7%
9	XPENG Service Center Marseille x Parascandola	Parascandola	41	26	15	63.4%
10	XPENG Service RVO Clermont-Ferrand France	Group not specified	29	18	11	62.1%

Top 10 dealerships by finished cases

Ranked by the number of records with Status = Finished. Record totals and completion rates are shown for context.

Rank	Dealership	Group	Total campaigns	Finished	To be finished	Completion rate
1	XPENG Service Center Le Cannet x Mozart Autos	Mozart Autos	151	114	37	75.5%
2	XPENG Service Center Fréjus Mapauto	Group not specified	71	62	9	87.3%
3	XPENG Service Center Nice x Mozart Autos	Mozart Autos	65	60	5	92.3%
4	XPENG Service Center Bastia x Groupe SIA	Groupe SIA	46	39	7	84.8%
5	XPENG Service Center Montpellier x GRIM	GRIM	60	32	28	53.3%
6	XPENG Service Center Valence x Jean Lain Mobilités	Jean Lain Mobilités	94	31	63	33.0%
7	XPENG Service Center Aix-en-Provence x Deffeuille	Deffeuille	47	26	21	55.3%
8	XPENG Service Center Marseille x Parascandola	Parascandola	41	26	15	63.4%
9	XPENG Service Center Nîmes x Grim	Grim	27	22	5	81.5%
10	XPENG Service Center Toulouse De Boussac	Group not specified	53	21	32	39.6%