

OFFICIAL INSPECTION RECORD

Unit Identification: HSR-001

AUTHORIZED LOCATION

Main Corridor A

ASSET TYPE & WEIGHT

Fire Hose Reel - 30m

Inspector: Mmalo Zulu

Date: 2026-05-06

Checklist Responses:

Is the hose reel easily accessible?	NA
Is the signage clearly visible?	NO
Is the hose in good condition (no cracks/leaks)?	YES
Is the drum/reel secure and undamaged?	NO
Does the valve open and close properly?	YES
Is there adequate water pressure?	YES
Does the hose unwind and rewind smoothly?	YES
Is the nozzle functioning properly (spray control works)?	YES
Are inspection tags updated?	YES
Has the hose reel been tested recently?	YES

Visual Evidence:



[Open in New Tab](#)