

City Hospital - 2026-01-09

Document handover-city-hospital-2026-01-09-31 · revision 1 · effective 2026-01-09

Machine types: SDM-43

Item numbers: 1.291-101.0

Serial numbers: SDM43-2026-10005

Site: city-hospital

Shift note

Nights at City Hospital. Took SDM43-2026-10005 over from the previous crew at shift start.

Observations

- Recovery tank smelled bad at the end of the run, probably not rinsed properly yesterday.
- Water on the floor behind the machine in the last hour, squeegee not picking up cleanly.
- Brushes look close to worn out to me. Someone should measure them properly.

Actions taken

- Topped up the solution tank and checked the detergent dosing was set right.
- Put it on charge at end of shift, charger showed green before I left.

Outstanding

- Battery wants a full charge cycle, do not take it out on a short top-up.
- Needs the brushes measured against the wear limit before next use.

L. Brennan. Back Thursday.