WORK ORDER REQUEST

Lakeline Property Management | 1200 Lakeline Blvd, Suite 300, Cedar Park, TX 78613

Date issued: 2026-10-13 Work order #: LPM-20931

Requested by

Name: Maria Gonzalez (Maintenance Coordinator)

Email: maria.gonzalez@lakelinepm.example Phone: 512-555-0177

Service location

Property: 4815 Brushy Creek Rd, Unit 12B, Round Rock, TX 78681

Tenant: Daniel Okafor - 737-555-0148 (tenant is home after 2pm on weekdays)

Problem description

Kitchen sink is leaking under the cabinet; water damage starting on the cabinet floor. Garbage disposal hums but does not turn. Please repair the leak and replace the disposal if it cannot be fixed (owner approved up to $450 without further approval).

Scheduling

Requested appointment: Thursday, October 16, 2026 at 2:00 PM (Central Time). Lockbox on front door, code 7731. Bill Lakeline Property Management, reference LPM-20931.