



555 N. MAIN ST. • PO BOX 2185 • MANTECA, CA 95336-1160
 PHONE: (209) 239-3561 • FAX: (209) 239-8530
 WWW.MANTECAFORD.COM

SO # 550795

**SERVICE ORDER
 CUSTOMER COPY**



Printed 07/10/2026 1:41:40 PM

User 507 Page 1

Customer No 257287
 Attn: MICHAEL LADUCER (CELL)
 NORTH SKY COMMUNICATIONS, LLC
 16701 SE MCGILLIVRAY
 VANCOUVER, WA 98683

Home (971) 412-8469 **Bus** (360) 254-6920
Cell (209) 678-2437 **Today**
Email accountspayable@northskycomm.com

Term Charge

Advisor ROXANA **Promised** 06/05/2026 5:00 PM **Tag#** Y914
Shop QL **Opened** 06/05/2026 8:01 AM **Location**
Priority **Cashiered** 06/08/2026 12:55 PM **PO #**

License **Odom In** 18147 **Odom Out** 18149 **In Service Date** **Stock No**
Year 2026 **Make** FORD **Model** SUPER DUTY F-250 SRW X2B **Model Number** **Color**
Vehicle ID No 1FT7X2BA7TED34447 **Selling Dealer** **Extended Warranty** **Delivery Date**
Engine 6.8L 2V DEVCT NA PFI V8 GAS **Fleet #**

Request	Description	Job	CSR	Status
45FOZ10	CUSTOMER STATES VEHICLE HAS A GRINDING/CRANKING NOISE WHEN TURNING LEFT ON THE DRIVER SIDE OF WHEEL WELL	1	831	Original
Labor	Description	Type	Amount	
45FOZ10	CUSTOMER STATES VEHICLE HAS A GRINDING/CRANKING NOISE WHEN TURNING LEFT ON THE DRIVER SIDE OF WHEEL WELL	C	220.00	
Technician	718 -	Est Parts	0.00	
Cause	PERFORMED ROAD TEST , VERIFIED CLUNKING NOISE FROM FRONT END WHEN TURNING , EXPECIALLY WHEN TURNING LEFT . LIFTED VEHICLE ON RACK . CHECKED ALL FRONT END U JOINTS, AXLES AND BALL JOINTS. VISUAL INSPECTION OK AND CHECKING FOR ABNORMAL PLAY IN SUSPENSION COMPONENTS ALL PASSED. TESTED 4X4 SYSTEM , FOUND FRONT 4X4 HUBS WERE IN MANUAL LOCK POSITION . SET FRONT HUBS ADJUSTMENT KNOB TO AUTO POSITION AND PERFORMED ROAD TEST ONCE AGAIN , NOISE NOW GONE .	Est Labor	220.00	
		Labor Total	220.00	
		Request Sub-total	220.00	
	NO PROBLEM FOUND WITH VEHICLE. CUSTOMER JUST LEFT FRONT HUBS IN " LOCKED " POSITION AND FORGOT TO SET BACK TO "AUTO " POSITION .			
Correction	SET 4X4 FRONT HUBS TO AUTO POSITION .			

Request	Description	Job	CSR	Status
Q99P	PERFORMED VISUAL MULTI POINT INSPECTION AND SET TIRE PRESSURES TO MANUFACTURE SPECS	2	831	Original
Labor	Description	Type	Amount	
Q99PX	PERFORMED VISUAL MULTI POINT INSPECTION. CHECK TIRE PRESSURES AND SET TO MANUFACTURE SPECS	I		
Technician	999 -	Est Parts	0.00	
Cause	QUICKLANE MULTI POINT INSP.	Est Labor	0.00	
Correction	PERFORMED VISUAL MULTI POINT INSPECTION. CHECK TIRE PRESSURES AND SET TO MANUFACTURE SPECS .			

Request	Description	Job	CSR	Status
GTIRE	TIRES CKD OK	3	831	Approved
Labor	Description	Type	Amount	
GTIRE	TIRES CKD OK	INSP		

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE. *SPECIAL ORDER PARTS MUST BE PRE PAID.
 A CHARGE FOR HAZARDOUS WASTE DISPOSAL WILL BE ADDED TO CONFORM WITH CITY, STATE, AND FEDERAL REGULATIONS.
 I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.

CUSTOMER SIGNATURE _____

E.P.A. # CAD028651552 • B.A.R. # ARD185962



555 N. MAIN ST. • PO BOX 2185 • MANTECA, CA 95336-1160
 PHONE: (209) 239-3561 • FAX: (209) 239-8530
 WWW.MANTECAFORD.COM

SO # 550795

**SERVICE ORDER
 CUSTOMER COPY**



Printed 07/10/2026 1:41:41 PM

User 507 Page 2

Customer No 257287
 Attn: MICHAEL LADUCER (CELL)
 NORTH SKY COMMUNICATIONS, LLC
 16701 SE MCGILLIVRAY
 VANCOUVER, WA 98683

Home (971) 412-8469 **Bus** (360) 254-6920
Cell (209) 678-2437 **Today**
Email accountspayable@northskycomm.com

Term Charge

Advisor ROXANA **Promised** 06/05/2026 5:00 PM **Tag#** Y914
Shop QL **Opened** 06/05/2026 8:01 AM **Location**
Priority **Cashiered** 06/08/2026 12:55 PM **PO #**

License	Odom In	Odom Out	In Service Date	Stock No
	18147	18149		
Year	Make	Model	Model Number	Color
2026	FORD	SUPER DUTY F-250 SRW	X2B	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FT7X2BA7TED34447				
Engine	6.8L 2V DEVCT NA PFI V8 GAS	Fleet #		

Technician	999 -	Est Parts	0.00
Cause	INSPECTED TIRES FOUND ALL TO BE OK 7/32ND OR BETTER	Est Labor	0.00
Correction			

Request	Description	Job	CSR	Status
GBK	BRAKES OK	4	831	Approved
Labor	Description		Type	Amount
GBK	BRAKES OK		INSP	
Technician	999 -	Est Parts		0.00
Cause	INSPECTED BRAKES PADS MEASURED,6MM OR BETTER SHOES OVER 2MM	Est Labor		0.00
Correction	INSPECTED BRAKES PADS MEASURED,6MM OR BETTER SHOES OVER 2MM			

Request	Description	Job	CSR	Status
GBATT	BATTERY TESTED GREEN PASSED	5	831	Approved
Labor	Description		Type	Amount
GBATT	BATTERY TESTED GREEN PASSED		INSP	
Technician	999 -	Est Parts		0.00
Cause	BATTERY CHECKED OK AT THIS TIME	Est Labor		0.00
Correction	BATTERY TESTED OK AT THIS TIME			

916-926-9890 GILBERT

Labor	220.00
Parts	0.00
Supplies	0.00
Sub-Total	220.00
Tax	0.00
Total Invoice	220.00

ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE. *SPECIAL ORDER PARTS MUST BE PRE PAID.
 A CHARGE FOR HAZARDOUS WASTE DISPOSAL WILL BE ADDED TO CONFORM WITH CITY, STATE, AND FEDERAL REGULATIONS.
 I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.

CUSTOMER SIGNATURE _____