

CUSTOMER #: PF70441
UNIT# 71825

194563

INVOICE



MIKE WHITE

Ford of Coeur d'Alene

315 Clayton Ave., Coeur d'Alene, ID 83815
Phone 208-664-9211, Spokane 509-747-8211
Toll Free in Idaho 800-331-0244
www.mikewhitefordcda.com

NORTHSKY COMMUNICATIONS
16701 SE MCGILLIVRAY BLVD SUITE 200
VANCOUVER, WA 98683
HOME:503-858-3871 CONT:208-610-5206
BUS: CELL:208-610-5206

PAGE 1

SERVICE ADVISOR: 70294 ADAM RITCH

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
WHITE	18	FORD F-350		1FD8W3H60JEC12747	Y128356	146384/146388		T9831
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
25APR18 IS								
25APR18 DD	07MAR18		17:00	26JUN25	040506		CHG	03JUL25
R.O. OPENED		READY		OPTIONS: W-COMP:W ENG:6.2L_GAS TRN:6R140				
09:22 03JUN25		15:39 03JUL25						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A MULTI-POINT VEHICLE INSPECTION

99P Multi-Point Vehicle Inspection

70446	CCF	0.30				0.00	0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	0.00
146384 0.30 MPI COMPLETE. OIL CHANGE DUE PER DASH/STICKER. ORANGE COOLANT, RECOMMEND FLUSH. EXHAUST LEAK NOTED ON STARTUP, FOUND DRIVER EXHAUST MANIFOLD CRACKED. NO CRACKS OR MISSING STUDS NOTED FROM PASSENGER SIDE. RECOMMEND REPLACE DRIVER MANIFOLD AND RE TEST FOR EXHAUST LEAKS. 4 3/4 ROUND RED LED MARKER LIGHTS INOP, REPLACE. TRANS FLUID IS DARK, RECOMMEND SERVICE. ENGINE AIR FILTER DIRTY, RECOMMEND REPLACE. CEL IS ON - DIAG.							

B CUSTOMER STATES THAT THE POWER BRAKES AND POWER STEERING STOPPED WORKING. PLEASE CHECK AND ADVISE.

BRAKES Concerns related to braking system

70446	CCF	1.00				100.00	100.00
PARTS:	0.00	LABOR:	100.00	OTHER:	0.00	TOTAL LINE B:	100.00
146384 1.00 C/S POWER STEERING AND POWER BRAKES INOP. INSPECTED VEHICLE, FOUND SERP BELT TO BE PROPERLY INSTALLED AND IN GOOD SHAPE. FOUND POWER STEERING FLUID RESERVOIR TO BE EMPTY. INSPECTED FOR DAMAGED COMPONENTS OR DISCONNECTED HOSES, NONE FOUND. NOTED HYDROBOOST AREA IS WET. ADDED 1 QT LV, STARTED ENGINE AND BLED POWER STEERING. VERIFIED PROPER OPERATION OF POWER STEERING AND BRAKES. PUMP IS HEALTHY, INDICATED VEHICLE WAS NOT DRIVEN WITHOUT FLUID. CLEANED ALL RESIDUAL FLUID FROM HYDROBOOST AREA. IDLED ENGINE, ALLOW TO REACH OPERATING TEMPERATURE, AND INSPECTED FOR LEAKS. FOUND HYDROBOOST IS LEAKING FROM FRONT SEAL, BEHIND BRAKE MASTER CYL. RECOMMEND REPLACE HYDROBOOST, CLEAN RESIDUAL, RE TEST FOR LEAKS.							

C VEHICLE WAS TOWED IN. CONNECT DRIVESHAFT?

MISC MISC

70446	ICF	0.00					(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE C:	0.00
146384 0.00 DRIVESHAFT WAS CONNECTED.							

DISCLAIMER OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability of fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of said products. The product is sold by the seller "As Is" and the entire risk as to quality and performance of the product is with the buyer and/or manufacturer. If the product proves to be defective after purchase, the buyer and/or manufacturer, not the seller, shall assume the entire cost of all necessary remedies.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

X
CUSTOMER SIGNATURE

CUSTOMER #: PF70441
UNIT# 71825

194563

INVOICE



MIKE WHITE

Ford of Coeur d'Alene

315 Clayton Ave., Coeur d'Alene, ID 83815
Phone 208-664-9211, Spokane 509-747-8211
Toll Free in Idaho 800-331-0244
www.mikewhitefordcda.com

NORTHSKY COMMUNICATIONS
16701 SE MCGILLIVRAY BLVD SUITE 200
VANCOUVER, WA 98683
HOME:503-858-3871 CONT:208-610-5206
BUS: CELL:208-610-5206

PAGE 2

SERVICE ADVISOR: 70294 ADAM RITCH

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
WHITE	18	FORD F-350		1FD8W3H60JEC12747	Y128356	146384/146388		T9831
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
25APR18 IS								
25APR18 DD	07MAR18		17:00	26JUN25	040506		CHG	03JUL25
R.O. OPENED		READY		OPTIONS: W-COMP:W ENG:6.2L_GAS TRN:6R140				
09:22 03JUN25		15:39 03JUL25						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

D** CUSTOMER APPROVED TO DIAGNOSE WHY THE CHECK ENGINE LIGHT IS ON.
PLEASE CHECK AND ADVISE.

GASP CUSTOMER CONCERN FOR GAS ENGINE PERFORMANCE
ISSUES - CEL/DRIVABILITY/POWER/NOISE

70446 CCF 1.00 100.00 100.00
PARTS: 0.00 LABOR: 100.00 OTHER: 0.00 TOTAL LINE D: 100.00

146384 1.00 CUSTOMER APPROVED CEL DIAG. SCANNED DTCS, FOUND P0420.
INSPECTED EXHAUST, IT WAS PREVIOUSLY NOTED DRIVER (BANK 2) MANIFOLD IS
CRACKED. NO CONCERNS NOTED WITH BANK 1. CHECK OASIS, NO CONCERNS. CAT
CONVERTER REPLACEMENT IS REQUIRED.

E** CUSTOMER APPROVED TO REPLACE THE DRIVERS SIDE EXHAUST MANIFOLD
60R GAS ENGINE REPAIR

70446 CCF 2.30 483.00 483.00
1 BC3Z*9431*DA MANIFOLD ASY - EXHAUST 135.32 108.26 108.26
1 BC3Z*9448*B GASKET 33.17 26.54 26.54
8 *W714869*S901 STUD 4.25 3.40 27.20
8 *W714870*S430 NUT 3.25 2.60 20.80
4 *W707753*S900 STUD 12.50 10.00 40.00
4 *W520514*S440 NUT - HEX. 2.06 1.65 6.60
1 *N808684*S101 BOLT 2.20 1.76 1.76
2 *W716090*S437 BOLT 3.25 2.60 5.20

PARTS: 236.36 LABOR: 483.00 OTHER: 0.00 TOTAL LINE E: 719.36

146384 2.30 DURING INSPECTION, NOTED DRIVER EXHAUST MANIFOLD
CRACKED AND LEAKING. CUSTOMER APPROVED EXHAUST MANIFOLD REPLACEMENT.
REMOVE AND REPLACE DRIVER EXHAUST MANIFOLD, STUDS, NUTS, AND GASKETS.
REPLACED DOWNPIPE NUTS. STARTED ENGINE, VERIFIED NO EXHAUST LEAKS.
REPAIR VERIFIED.

F** CUSTOMER APPROVED TO REPLACE THE HYDRO BOOST
20R BRAKE SYSTEM REPAIR

70446 CCF 3.70 777.00 777.00
1 PC3Z*2005*A BOOSTER ASY - BRAKE 522.98 418.38 418.38
1 BC3Z*3F887*A KIT - "O" RING - PWR STEERING 61.33 49.06 49.06

DISCLAIMER OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability of fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of said products. The product is sold by the seller "As Is" and the entire risk as to quality and performance of the product is with the buyer and/or manufacturer. If the product proves to be defective after purchase, the buyer and/or manufacturer, not the seller, shall assume the entire cost of all necessary remedies.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

X
CUSTOMER SIGNATURE

CUSTOMER #: PF70441
UNIT# 71825

194563

INVOICE

NORTHSKY COMMUNICATIONS
16701 SE MCGILLIVRAY BLVD SUITE 200
VANCOUVER, WA 98683
HOME:503-858-3871 CONT:208-610-5206
BUS: CELL:208-610-5206

PAGE 3

SERVICE ADVISOR: 70294 ADAM RITCH



MIKE WHITE

Ford of Coeur d'Alene

315 Clayton Ave., Coeur d'Alene, ID 83815
Phone 208-664-9211, Spokane 509-747-8211
Toll Free in Idaho 800-331-0244
www.mikewhitefordcda.com

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
WHITE	18	FORD F-350		1FD8W3H60JEC12747	Y128356	146384/146388		T9831
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
25APR18 IS								
25APR18 DD	07MAR18		17:00	26JUN25	040506		CHG	03JUL25
R.O. OPENED		READY		OPTIONS: W-COMP:W ENG:6.2L_GAS TRN:6R140				
09:22 03JUN25		15:39 03JUL25						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1			*W716538*S442 NUT AND WASHER ASY - HEX.		4.25	3.40	3.40
4			*W520212*S440 NUT		3.25	2.60	10.40
3			XT*10*BLV OIL - AUTOMATIC TRANSMISSION		5.57	4.46	13.38
PARTS: 494.62 LABOR: 777.00 OTHER: 0.00				TOTAL LINE F:			1271.62

146384 3.70 CUSTOMER APPROVED HYDROBOOST REPLACEMENT. REMOVED BRAKE MASTER CYL FOR ACCESS. REMOVE AND REPLACE HYDROBOOST. REASSEMBLED VEHICLE. REPLACED NUTS. TOP OFF POWER STEERING FLUID. BLEED POWER STEERING. CLEANED ALL RESIDUAL POWER STEERING FLUID. ROAD TEST, VERIFIED PROPER OPERATION. CHECK FLUID LEVEL, OK. RE CHECK FOR LEAKS, NONE. REPAIR VERIFIED.

YOU MAY RECEIVE A SURVEY FROM THE FACTORY.
THIS SURVEY IS OUR REPORT CARD! WE HOPE WE
EARNED A 5 STAR RATING. PLEASE CONTACT US IF
THERE ARE ANY CONCERNS WE NEED TO ADDRESS.
YOUR COMPLETE SATISFACTION IS OUR DESIRE!!!

DISCLAIMER OF WARRANTIES

Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either expressed or implied, including any implied warranty of merchantability of fitness for a particular purpose, and neither assumes nor authorizes any person to assume for it any liability in connection with the sale of said products. The product is sold by the seller "As Is" and the entire risk as to quality and performance of the product is with the buyer and/or manufacturer. If the product proves to be defective after purchase, the buyer and/or manufacturer, not the seller, shall assume the entire cost of all necessary remedies.

DESCRIPTION	TOTALS
LABOR AMOUNT	1460.00
PARTS AMOUNT	730.98
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	2190.98
LESS INSURANCE	0.00
SALES TAX	43.86
PLEASE PAY THIS AMOUNT	2234.84

X
CUSTOMER SIGNATURE