

QUALITY INSPECTION CERTIFICATE

Generated: 2025-11-04 09:07



Work Order Information

Work Order Number: WO2025112183
Job Card Number: JC-2025-0003
Title: Servicing of Gensets
Asset: Backup Generator
Location: Generator Room
Work Order Type: Preventive Maintenance
Maintenance Type: Preventive
Priority: Medium
Completed Date: N/A

Inspection Details

Checklist: General - Preventive Maintenance QC
Inspection Date: 04-Nov-25 08:04:32
Overall Result: Pass
Score: 100%
Minimum Passing Score: 80%
Inspector Notes: Work completed using the highest standards

Checklist Results

#	Item	Result	Notes
1	All scheduled tasks completed	Pass	
2	Equipment cleaned	Pass	
3	Lubrication performed where needed	Pass	
4	Functional test passed	Pass	
5	Safety check completed	Pass	
6	Work area clean and safe	Pass	
7	Documentation complete	Pass	

Inspector Signature
Date: 04-Nov-25 09:07:12

Supervisor Signature
Date: _____