

QUALITY INSPECTION CERTIFICATE

Generated: 2025-11-19 11:16



Work Order Information

Work Order Number: WO2025118993
Job Card Number: JC-2025-0008
Title: Broken down vehicle
Asset: Nissan Hilux Pickup
Location: HQ
Work Order Type: Preventive Maintenance
Maintenance Type: Preventive
Priority: High
Completed Date: 19-Nov-25 11:14:15

Inspection Details

Checklist: General - Preventive Maintenance QC
Inspection Date: 19-Nov-25 11:14:15
Overall Result: Pass
Score: 100%
Minimum Passing Score: 80%
Inspector Notes: Passed

Checklist Results

#	Item	Result	Notes
1	All scheduled tasks completed	Pass	
2	Equipment cleaned	Pass	
3	Lubrication performed where needed	Pass	
4	Functional test passed	Pass	
5	Safety check completed	Pass	
6	Work area clean and safe	Pass	
7	Documentation complete	Pass	

Inspector Signature
Date: 19-Nov-25 11:16:31

Supervisor Signature
Date: _____