

1	Aquaculture, Biology, Science and Technology (AquaBEST) Bldg	<table><tr><td>RVS SCORE:</td><td>2.3</td><td>Structure may not be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">No adverse defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of minor non-structural defects</td></tr></table>	RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	No adverse defects		NONSTRUCTURAL	Presence of minor non-structural defects		6	Physical Plant and Security Services Office	<table><tr><td>RVS SCORE:</td><td>2.3</td><td>Structure may not be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">No adverse defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of minor non-structural defects</td></tr></table>	RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	No adverse defects		NONSTRUCTURAL	Presence of minor non-structural defects		11	Management Department Bldg No. 1	<table><tr><td>RVS SCORE:</td><td>0.8</td><td>Structure may be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">Presence of minor structural defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of minor non-structural defects</td></tr></table>	RVS SCORE:	0.8	Structure may be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	Presence of minor structural defects		NONSTRUCTURAL	Presence of minor non-structural defects	
RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	No adverse defects																																																																																																	
NONSTRUCTURAL	Presence of minor non-structural defects																																																																																																	
RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	No adverse defects																																																																																																	
NONSTRUCTURAL	Presence of minor non-structural defects																																																																																																	
RVS SCORE:	0.8	Structure may be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	Presence of minor structural defects																																																																																																	
NONSTRUCTURAL	Presence of minor non-structural defects																																																																																																	
2	Pangasiwaan Supply Office	<table><tr><td>RVS SCORE:</td><td>0.4</td><td>Structure may be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">No adverse defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of minor non-structural defects</td></tr></table>	RVS SCORE:	0.4	Structure may be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	No adverse defects		NONSTRUCTURAL	Presence of minor non-structural defects		7	Gym Canteen	<table><tr><td>RVS SCORE:</td><td>2.3</td><td>Structure may not be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">Presence of minor structural defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of minor non-structural defects</td></tr></table>	RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	Presence of minor structural defects		NONSTRUCTURAL	Presence of minor non-structural defects		12	Management Department Bldg No. 2	<table><tr><td>RVS SCORE:</td><td>0.8</td><td>Structure may be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">Presence of minor structural defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of localized defect found</td></tr></table>	RVS SCORE:	0.8	Structure may be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	Presence of minor structural defects		NONSTRUCTURAL	Presence of localized defect found	
RVS SCORE:	0.4	Structure may be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	No adverse defects																																																																																																	
NONSTRUCTURAL	Presence of minor non-structural defects																																																																																																	
RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	Presence of minor structural defects																																																																																																	
NONSTRUCTURAL	Presence of minor non-structural defects																																																																																																	
RVS SCORE:	0.8	Structure may be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	Presence of minor structural defects																																																																																																	
NONSTRUCTURAL	Presence of localized defect found																																																																																																	
3	Human Resource Office Accounting Office	<table><tr><td>RVS SCORE:</td><td>2.3</td><td>Structure may not be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">Presence of minor structural defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">No adverse defects</td></tr></table>	RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	Presence of minor structural defects		NONSTRUCTURAL	No adverse defects		8	Infirmary	<table><tr><td>RVS SCORE:</td><td>2.3</td><td>Structure may not be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">Presence of minor structural defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of minor non-structural defects</td></tr></table>	RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	Presence of minor structural defects		NONSTRUCTURAL	Presence of minor non-structural defects		13	Management Department Bldg No. 3	<table><tr><td>RVS SCORE:</td><td>0.8</td><td>Structure may be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">Presence of minor structural defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of minor non-structural defects</td></tr></table>	RVS SCORE:	0.8	Structure may be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	Presence of minor structural defects		NONSTRUCTURAL	Presence of minor non-structural defects	
RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	Presence of minor structural defects																																																																																																	
NONSTRUCTURAL	No adverse defects																																																																																																	
RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	Presence of minor structural defects																																																																																																	
NONSTRUCTURAL	Presence of minor non-structural defects																																																																																																	
RVS SCORE:	0.8	Structure may be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	Presence of minor structural defects																																																																																																	
NONSTRUCTURAL	Presence of minor non-structural defects																																																																																																	
4	Cooperative Office	<table><tr><td>RVS SCORE:</td><td>1.9</td><td>Structure may be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">Presence of minor structural defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of localized defect found</td></tr></table>	RVS SCORE:	1.9	Structure may be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	Presence of minor structural defects		NONSTRUCTURAL	Presence of localized defect found		9	Aklatan	<table><tr><td>RVS SCORE:</td><td>2.3</td><td>Structure may not be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">No adverse defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">No adverse defects</td></tr></table>	RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	No adverse defects		NONSTRUCTURAL	No adverse defects		14	Management Department Bldg No. 4	<table><tr><td>RVS SCORE:</td><td>0.8</td><td>Structure may be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">Presence of some severe defect found</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">Presence of minor non-structural defects</td></tr></table>	RVS SCORE:	0.8	Structure may be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	Presence of some severe defect found		NONSTRUCTURAL	Presence of minor non-structural defects	
RVS SCORE:	1.9	Structure may be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	Presence of minor structural defects																																																																																																	
NONSTRUCTURAL	Presence of localized defect found																																																																																																	
RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	No adverse defects																																																																																																	
NONSTRUCTURAL	No adverse defects																																																																																																	
RVS SCORE:	0.8	Structure may be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	Presence of some severe defect found																																																																																																	
NONSTRUCTURAL	Presence of minor non-structural defects																																																																																																	
5	Office of the Student Affairs and Services Central Student Government Office Reserve Officers' Training Corps Office	<table><tr><td>RVS SCORE:</td><td>2.3</td><td>Structure may not be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">No adverse defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">No adverse defects</td></tr></table>	RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	No adverse defects		NONSTRUCTURAL	No adverse defects		10	Science, Technology and Applied Research (STA)	<table><tr><td>RVS SCORE:</td><td>2.3</td><td>Structure may not be vulnerable to Seismic Hazard</td></tr><tr><td colspan="3">BUILDING LOCATION IS VULNERABLE TO:</td></tr><tr><td>Earthquake?</td><td colspan="2">YES</td></tr><tr><td>Landslide/Soil Erosion?</td><td colspan="2">NO</td></tr><tr><td>Liquefaction?</td><td colspan="2">YES</td></tr><tr><td>Tsunami?</td><td colspan="2">YES</td></tr><tr><td>Storm Surge?</td><td colspan="2">NO</td></tr><tr><td colspan="3">PHYSICAL CONDITION EVALUATION</td></tr><tr><td>STRUCTURAL</td><td colspan="2">No adverse defects</td></tr><tr><td>NONSTRUCTURAL</td><td colspan="2">No adverse defects</td></tr></table>	RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard	BUILDING LOCATION IS VULNERABLE TO:			Earthquake?	YES		Landslide/Soil Erosion?	NO		Liquefaction?	YES		Tsunami?	YES		Storm Surge?	NO		PHYSICAL CONDITION EVALUATION			STRUCTURAL	No adverse defects		NONSTRUCTURAL	No adverse defects		15	Management Department Bldg No. 5																															
RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	No adverse defects																																																																																																	
NONSTRUCTURAL	No adverse defects																																																																																																	
RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard																																																																																																
BUILDING LOCATION IS VULNERABLE TO:																																																																																																		
Earthquake?	YES																																																																																																	
Landslide/Soil Erosion?	NO																																																																																																	
Liquefaction?	YES																																																																																																	
Tsunami?	YES																																																																																																	
Storm Surge?	NO																																																																																																	
PHYSICAL CONDITION EVALUATION																																																																																																		
STRUCTURAL	No adverse defects																																																																																																	
NONSTRUCTURAL	No adverse defects																																																																																																	

	RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard
BUILDING LOCATION IS VULNERABLE TO:			
	Earthquake?		YES
	Landslide/Soil Erosion?		NO
	Liquefaction?		YES
	Tsunami?		YES
	Storm Surge?		NO
PHYSICAL CONDITION EVALUATION			
	STRUCTURAL	Presence of minor structural defects	
	NONSTRUCTURAL	Presence of localized defect found	

RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard
BUILDING LOCATION IS VULNERABLE TO:		
Earthquake?		YES
Landslide/Soil Erosion?		NO
Liquefaction?		YES
Tsunami?		YES
Storm Surge?		NO
PHYSICAL CONDITION EVALUATION		
STRUCTURAL	No adverse defects	
NONSTRUCTURAL	Presence of minor non-structural defects	

RVS SCORE:	2.3	Structure may not be vulnerable to Seismic Hazard
BUILDING LOCATION IS VULNERABLE TO:		
Earthquake?		YES
Landslide/Soil Erosion?		NO
Liquefaction?		YES
Tsunami?		YES
Storm Surge?		NO
PHYSICAL CONDITION EVALUATION		
STRUCTURAL	Presence of minor structural defects	
NONSTRUCTURAL	Presence of minor non-structural defects	