

REPORT:

Company

Test and Tag Supplies

User:

James

Date

6/5/26 8:45:57 AM

Location

Wacol

Instrument

Model

newtoservice

Serial

0

User data

Model

MI 3309BT

Serial

14220268

User data

Model

MI 3309BT

Serial

18480413

User data

0	Test and/	
1	Test and/Warehouse/	
2	Test and/Warehouse/TTS00008/	PASS
	Name: Electric Knife	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Std	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 15:15:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 11.01.2024 15:15:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
3	Test and/Warehouse/TTS00011/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2022 00:00:00	
	Visual Inspection 17.01.2022 16:45:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 17.01.2022 16:45:00	PASS
	Instrument : 18480413	

	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 17.01.2022 16:45:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 17.01.2022 16:45:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
4	Test and/Warehouse/TTS00012/	PASS
	Name: Solder Station	
	(Room) Location: Warehouse	
	Test code: Earthed App Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 16:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 11.01.2024 16:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.03 mA	
	Limit : 5.00 mA	
	S : 0.10 kVA	
	PARAMETERS	
	Duration : 10 s	
5	Test and/Warehouse/TTS00013/	PASS
	Name: Flouro Lamp	
	(Room) Location: Warehouse	
	Test code: Earthed App Std	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 13:44:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 13:44:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 13:44:00	PASS

	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
6	Test and/Warehouse/TTS00014/	PASS
	Name: Lamp	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 15:32:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 11.01.2024 15:32:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.01 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
7	Test and/Warehouse/TTS00015/	PASS
	Name: Solder Station	
	(Room) Location: Warehouse	
	Test code: Earthed App Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 16:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.27 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 11.01.2024 16:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.26 mA	
	Limit : 5.00 mA	
	S : 0.32 kVA	
	PARAMETERS	
	Duration : 10 s	
8	Test and/Warehouse/TTS00018/	PASS
	Name: Power Board	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	

	Earth Continuity 19.07.2022 16:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.07.2022 16:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 19.07.2022 16:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
9	Test and/Warehouse/TTS00022/	PASS
	Name: IEC Lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 18.07.2023 00:00:00	
	Visual Inspection 18.07.2022 16:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 18.07.2022 16:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 18.07.2022 16:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 18.07.2022 16:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
10	Test and/Warehouse/TTS00023/	PASS
	Name: Oscilloscope	
	(Room) Location: CAL Room	
	Test code: Earthed App Std	
	Next test of appliance: 18.07.2023 00:00:00	
	Visual Inspection 18.07.2022 16:13:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 18.07.2022 16:13:00	PASS
	Instrument : 18480413	

	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 18.07.2022 16:13:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.20 mA	
	Limit : 5.00 mA	
	S : 0.04 kVA	
	PARAMETERS	
	Duration : 30 s	
11	Test and/Warehouse/TTS00026/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.01.2023 00:00:00	
	Visual Inspection 20.07.2022 11:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 20.07.2022 11:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 20.07.2022 11:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 20.07.2022 11:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
12	Test and/Warehouse/TTS00027/	PASS
	Name: Computer PSU	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 19.01.2023 00:00:00	
	Visual Inspection 20.07.2022 11:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 20.07.2022 11:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 20.07.2022 11:26:00	PASS

	Instrument : 18480413	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 5.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
13	Test and/Warehouse/TTS00028/	PASS
	Name: Power Board	
	(Room) Location: CAL Room	
	Test code: Ext Lead Lkg	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 15:43:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 15:43:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Polarity 19.07.2022 15:43:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
	Differential Leakage 19.07.2022 15:43:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.06 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 2 s	
14	Test and/Warehouse/TTS00033/	PASS
	Name: IEC lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 06.08.2025 00:00:00	
	Visual Inspection 04.02.2025 15:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 15:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 15:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	

	Output iso voltage : 500 V Duration : 2 s	
	Polarity 04.02.2025 15:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
15	Test and/Warehouse/TTS00038/	PASS
	Name: Desk Powerboard	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 17:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 17:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.03 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 17:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 17:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
16	Test and/Warehouse/TTS00040/	PASS
	Name: Transformer	
	(Room) Location: CAL Room	
	Test code: Earthed App Std	
	Next test of appliance: 18.07.2023 00:00:00	
	Visual Inspection 18.07.2022 16:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 18.07.2022 16:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.12 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 18.07.2022 16:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
17	Test and/Warehouse/TTS00041/	PASS

	Name: Drill Press	
	(Room) Location: Warehouse	
	Test code: Earthed App Std	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 12:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 12:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.19 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 12:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
18	Test and/Warehouse/TTS00046/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.06 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 16:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
19	Test and/Warehouse/TTS00047/	PASS
	Name: IEC lead	
	(Room) Location: WAREHOUSE	
	Test code: IEC/Ext Lead	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 15:50:00	PASS
	Instrument : 18480413	

	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 15:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.05 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 15:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 15:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
20	Test and/Warehouse/TTS00048/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 11.01.2025 00:00:00	
	Visual Inspection 12.01.2024 16:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 16:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
21	Test and/Warehouse/TTS00050/	PASS
	Name: IEC lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 15:23:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	

	PARAMETERS	
	Earth Continuity 11.01.2024 15:23:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 15:23:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 15:23:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
22	Test and/Warehouse/TTS00051/	PASS
	Name: Label Printer	
	(Room) Location: Warehouse	
	Test code: Earthed App Std	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.12 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
23	Test and/Warehouse/TTS00053/	PASS
	Name: Label Printer	
	(Room) Location: Warehouse	
	Test code: Earthed App Std	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.30 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	

	l out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
24	Test and/Warehouse/TTS00059/	PASS
	Name: Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:33:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 11.01.2024 16:33:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
25	Test and/Warehouse/TTS00064/	PASS
	Name: Vacuum Cleaner	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Std	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 12:03:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 11.01.2024 12:03:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
26	Test and/Warehouse/TTS0075/	PASS
	Name: Extension Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 13:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 13:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	

	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 13:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 13:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
27	Test and/Warehouse/TTS0077/	PASS
	Name: Glue Gun	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Std	
	Next test of appliance: 31.07.2025 00:00:00	
	Visual Inspection 29.01.2025 15:34:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 29.01.2025 15:34:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
28	Test and/Warehouse/TT012353/	PASS
	Name: SEW Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 13:30:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 13:30:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.04 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 13:30:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 13:30:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
29	Test and/Warehouse/TTS00071/	PASS

	Name: METREL 2121	
	(Room) Location: WAREHOUSE	
	Test code: Earthed App Std	
	Next test of appliance: 23.09.2023 00:00:00	
	Visual Inspection 23.09.2022 14:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 23.09.2022 14:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 23.09.2022 14:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
30	Test and/Warehouse/TTS00099/	PASS
	Name: C6 IEC Lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 15:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 15:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 21.07.2023 15:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 21.07.2023 15:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
31	Test and/Warehouse/TTS00100/	PASS
	Name: Zebra PSU	
	(Room) Location: WAREHOUSE	
	Test code: Encap Earth	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 15:27:00	PASS
	Instrument : 18480413	

	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 21.07.2023 15:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 21.07.2023 15:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.19 mA	
	Limit : 5.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
32	Test and/Warehouse/TTS00037/	PASS
	Name: DESK POWERBOARD	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.07.2022 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 19.07.2022 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
33	Test and/Warehouse/RCD001/	PASS
	Name: RCD Cal bench	
	(Room) Location: WAREHOUSE	
	Test code: Fixed 30mA RCD	
	Next test of appliance: 24.07.2024 00:00:00	
	RCD 25.07.2023 08:47:00	PASS
	Instrument : 18480413	
	RESULTS	
	(+) ,t IΔN x1 : 26.3 ms	
	(-) ,t IΔN x1 : 35.0 ms	
	PARAMETERS	
	Test : RCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
34	Test and/Warehouse/TTS00101/	PASS

	Name: Seaward lead (Room) Location: CAL Room Test code: Encap Earth Next test of appliance: 10.02.2026 00:00:00	
	Visual Inspection 10.02.2025 14:19:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Insulation 10.02.2025 14:19:00 Instrument : 18480413 RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	PASS
	Differential Leakage 10.02.2025 14:19:00 Instrument : 18480413 RESULTS Idiff : 0.02 mA Limit : 5.00 mA S : 0.00 kVA PARAMETERS Duration : 10 s	PASS
35	Test and/Warehouse/RCD002/	PASS
	Name: RCD 15 A (Room) Location: CAL Room Test code: Fixed 30mA RCD Next test of appliance: 24.07.2024 00:00:00	
	RCD 25.07.2023 08:39:00 Instrument : 18480413 RESULTS (+) ,t IΔN x1 : 9.3 ms (-) ,t IΔN x1 : 18.9 ms PARAMETERS Test : RCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	PASS
36	Test and/Warehouse/TT012350/	PASS
	Name: IEC Lead (Room) Location: Warehouse Test code: IEC/Ext Lead Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 13:32:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Earth Continuity 11.01.2024 13:32:00 Instrument : 18480413 RESULTS R : 0.04 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	PASS
	Insulation 11.01.2024 13:32:00 Instrument : 18480413 RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS	PASS

	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 13:32:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
37	Test and/Warehouse/AT2000/	PASS
	Name: Battery Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 06.08.2025 00:00:00	
	Visual Inspection 04.02.2025 11:53:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 04.02.2025 11:53:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.05 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
38	Test and/Warehouse/AT2002/	PASS
	Name: SEW Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 07.08.2025 00:00:00	
	Visual Inspection 05.02.2025 09:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 05.02.2025 09:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 05.02.2025 09:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 05.02.2025 09:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
39	Test and/Warehouse/TTS0081/	PASS
	Name: Fig 8 Lead	
	(Room) Location: Warehouse	
	Test code: 1	
	Next test of appliance: 12.07.2024 00:00:00	

	Visual Inspection 11.01.2024 13:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
40	Test and/Warehouse/AT2004/	PASS
	Name: Heat Gun	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Std	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 15:28:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 11.01.2024 15:28:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
41	Test and/Warehouse/AT2009/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 11:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 11:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 11:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 11:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
42	Test and/Warehouse/AT2010-PH1/	PASS
	Name: 3 Phase RCD	
	(Room) Location: WAREHOUSE	
	Test code: Fixed 30mA RCD	
	Next test of appliance: 24.07.2024 00:00:00	
	RCD 25.07.2023 08:41:00	PASS
	Instrument : 18480413	
	RESULTS	

	(+) ,t IΔN x1 : 25.7 ms	
	(-) ,t IΔN x1 : 35.8 ms	
	PARAMETERS	
	Test : RCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
43	Test and/Warehouse/AT2011/	PASS
	Name: RCD	
	(Room) Location: CAL Room	
	Test code: Fixed 30mA RCD	
	Next test of appliance: 24.07.2024 00:00:00	
	RCD 25.07.2023 08:44:00	PASS
	Instrument : 18480413	
	RESULTS	
	(+) ,t IΔN x1 : 40.0 ms	
	(-) ,t IΔN x1 : 29.5 ms	
	PARAMETERS	
	Test : RCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
44	Test and/Warehouse/TTS8003/	PASS
	Name: Red IEC Lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 05.02.2026 00:00:00	
	Visual Inspection 05.02.2025 08:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 05.02.2025 08:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 05.02.2025 08:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 05.02.2025 08:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
45	Test and/Warehouse/TTS00105/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 15:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 15:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.04 Ohm	

	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 15:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 15:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
46	Test and/Warehouse/TTS00106/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2022 00:00:00	
	Visual Inspection 17.01.2022 16:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 17.01.2022 16:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 17.01.2022 16:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 17.01.2022 16:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
47	Test and/Warehouse/TTS00109/	PASS
	Name: Fume Extractor	
	(Room) Location: WAREHOUSE	
	Test code: Earthed App Std	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 15:20:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 15:20:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.07 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	

	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 15:20:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
48	Test and/Warehouse/TTS00112/	PASS
	Name: Kyoritsu Lead	
	(Room) Location: CAL Room	
	Test code: Encap Earth	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 04.02.2025 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 04.02.2025 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 5.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
49	Test and/Warehouse/TTS00115/	PASS
	Name: Phone Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 31.07.2025 00:00:00	
	Visual Inspection 29.01.2025 15:45:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 29.01.2025 15:45:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
50	Test and/Warehouse/TTS00116/	PASS
	Name: Var Tx	
	(Room) Location: CAL Room	
	Test code: Earthed App Std	
	Next test of appliance: 18.07.2023 00:00:00	
	Visual Inspection 18.07.2022 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	

	Result : 0	
	PARAMETERS	
	Earth Continuity 18.07.2022 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.15 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 18.07.2022 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
51	Test and/Warehouse/TTS00117/	PASS
	Name: Figure 8 Lead	
	(Room) Location: CAL Room	
	Test code: 1	
	Next test of appliance: 22.07.2023 00:00:00	
	Visual Inspection 22.07.2022 12:32:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
52	Test and/Warehouse/0001/	PASS
	Name: Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 19.01.2023 00:00:00	
	Visual Inspection 20.07.2022 12:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 20.07.2022 12:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.15 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
53	Test and/Warehouse/00370/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:29:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:29:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.03 Ohm	
	Limit : 1.00 Ohm	

	PARAMETERS I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:29:00 Instrument : 18480413	PASS
	RESULTS Riso : >200 MOhm Limit : 1 MOhm	
	PARAMETERS Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 16:29:00 Instrument : 18480413	PASS
	RESULTS Fault : 1	
	PARAMETERS	
54	Test and/Warehouse/TTS00124/ Name: RCD Portable (Room) Location: Show Room Test code: Prtble 30mA RCD Next test of appliance: 19.01.2024 00:00:00	PASS
	Visual Inspection 20.07.2023 14:36:00 Instrument : 18480413	PASS
	RESULTS Result : 0	
	PARAMETERS	
	Earth Continuity 20.07.2023 14:36:00 Instrument : 18480413	PASS
	RESULTS R : 0.10 Ohm Limit : 1.00 Ohm	
	PARAMETERS I out : 200 mA Duration : 2 s	
	Differential Leakage 20.07.2023 14:36:00 Instrument : 18480413	PASS
	RESULTS Idiff : 0.03 mA Limit : 1.00 mA S : 0.00 kVA	
	PARAMETERS Duration : 2 s	
	RCD 20.07.2023 14:36:00 Instrument : 18480413	PASS
	RESULTS (+) ,t IΔN x1 : 27.7 ms (-) ,t IΔN x1 : 17.8 ms	
	PARAMETERS Test : PRCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
55	Test and/Warehouse/TTS00125/ Name: Fig 8 Lead (Room) Location: Warehouse Test code: 1 Next test of appliance: 31.07.2025 00:00:00	PASS
	Visual Inspection 29.01.2025 15:33:00 Instrument : 18480413	PASS
	RESULTS Result : 0	
	PARAMETERS	
56	Test and/Warehouse/TTS00126/ Name: CT Test Box (Room) Location: CAL Room	PASS

	Test code: Dbl Ins Lkg	
	Next test of appliance: 22.07.2023 00:00:00	
	Visual Inspection 22.07.2022 12:34:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 22.07.2022 12:34:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
57	Test and/Warehouse/TTS00127/	PASS
	Name: IEC Lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 16:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.07.2022 16:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 19.07.2022 16:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
58	Test and/Warehouse/TTS00128/	PASS
	Name: Service PC	
	(Room) Location: CAL Room	
	Test code: Earthed App Std	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.08 Ohm	
	Limit : 1.00 Ohm	

	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.07.2022 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
59	Test and/Warehouse/TTS00129/	PASS
	Name: IEC Lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 15:47:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 15:47:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.07.2022 15:47:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 19.07.2022 15:47:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
60	Test and/Warehouse/TTS00130/	PASS
	Name: Monitor PSU	
	(Room) Location: CAL Room	
	Test code: Encap Earth	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 15:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 19.07.2022 15:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 19.07.2022 15:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.07 mA	
	Limit : 5.00 mA	

	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
61	Test and/Warehouse/TTS00131/	PASS
	Name: Laminator	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Std	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 12:51:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 11.01.2024 12:51:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
62	Test and/Warehouse/TTS00132/	PASS
	Name: Phone Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 12.01.2024 16:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
63	Test and/Warehouse/TTS0027/	PASS
	Name: Power Board	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.06 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	

	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
64	Test and/Warehouse/TTS00133/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 11.01.2025 00:00:00	
	Visual Inspection 12.01.2024 16:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.07 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 16:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
65	Test and/Warehouse/TTS00134/	PASS
	Name: Fig 8 Lead	
	(Room) Location: Warehouse	
	Test code: 1	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:00:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
66	Test and/Warehouse/TTS00148/	PASS
	Name: Fig 8 Lead	
	(Room) Location: Warehouse	
	Test code: 1	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:51:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
67	Test and/Warehouse/TTS00147/	PASS

	Name: Battery Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:53:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 11.01.2024 16:53:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.12 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
68	Test and/Warehouse/TTS1306/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 31.07.2025 00:00:00	
	Visual Inspection 29.01.2025 15:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 29.01.2025 15:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 29.01.2025 15:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 29.01.2025 15:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
69	Test and/Warehouse/TTS00155/	PASS
	Name: C6 IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 13:36:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 13:36:00	PASS
	Instrument : 18480413	
	RESULTS	

	R : 0.12 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 13:36:00 Instrument : 18480413 RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	PASS
	Polarity 11.01.2024 13:36:00 Instrument : 18480413 RESULTS Fault : 1 PARAMETERS	PASS
70	Test and/Warehouse/TTS00156/ Name: Power Board (Room) Location: Warehouse Test code: IEC/Ext Lead Next test of appliance: 11.07.2024 10:46:00	PASS
	Visual Inspection 11.01.2024 10:46:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Earth Continuity 11.01.2024 10:46:00 Instrument : 18480413 RESULTS R : 0.09 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	PASS
	Insulation 11.01.2024 10:46:00 Instrument : 18480413 RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	PASS
	Polarity 11.01.2024 10:46:00 Instrument : 18480413 RESULTS Fault : 1 PARAMETERS	PASS
71	Test and/Warehouse/TTS00157/ Name: IEC Lead (Room) Location: Warehouse Test code: IEC/Ext Lead Next test of appliance: 06.08.2025 00:00:00	PASS
	Visual Inspection 04.02.2025 12:10:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Earth Continuity 04.02.2025 12:10:00 Instrument : 18480413 RESULTS R : 0.09 Ohm Limit : 1.00 Ohm	PASS

	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 12:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 04.02.2025 12:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
72	Test and/Warehouse/TTS00158/	PASS
	Name: Scales	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 18.01.2024 00:00:00	
	Visual Inspection 19.07.2023 16:42:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 19.07.2023 16:42:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 19.07.2023 16:42:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 5.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
73	Test and/Warehouse/TTS00159/	PASS
	Name: C6 IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 15.07.2022 00:00:00	
	Visual Inspection 13.01.2022 09:38:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 13.01.2022 09:38:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 13.01.2022 09:38:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	

	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 13.01.2022 09:38:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
74	Test and/Warehouse/TTS00160/	PASS
	Name: Battery Charger	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 15.07.2022 00:00:00	
	Visual Inspection 13.01.2022 09:41:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 13.01.2022 09:41:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : 48.9 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 13.01.2022 09:41:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.05 mA	
	Limit : 5.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
75	Test and/Warehouse/TTS00164/	PASS
	Name: Fig 8 Lead	
	(Room) Location: CAL Room	
	Test code: 1	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:51:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
76	Test and/Warehouse/TTS00165/	PASS
	Name: Metrel Charger	
	(Room) Location: CAL Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 19.07.2022 16:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.14 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	

	PARAMETERS	
	Duration : 10 s	
77	Test and/Warehouse/TTS0059/	PASS
	Name: Power Board	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 14:11:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 14:11:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.03 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 14:11:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 14:11:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
78	Test and/Warehouse/TTS168/	PASS
	Name: Programme PSU	
	(Room) Location: WAREHOUSE	
	Test code: Earthed App Lkg	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:28:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 16:28:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.19 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 19.07.2022 16:28:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.63 mA	
	Limit : 5.00 mA	
	S : 0.16 kVA	
	PARAMETERS	
	Duration : 30 s	
79	Test and/Warehouse/0003/	PASS
	Name: Red IEC Lead	
	(Room) Location: CAL Room	

	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:20:00 Instrument : 18480413	PASS
	RESULTS Result : 0 PARAMETERS	
	Earth Continuity 19.07.2022 16:20:00 Instrument : 18480413	PASS
	RESULTS R : 0.09 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	
	Insulation 19.07.2022 16:20:00 Instrument : 18480413	PASS
	RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	
	Polarity 19.07.2022 16:20:00 Instrument : 18480413	PASS
	RESULTS Fault : 1 PARAMETERS	
80	Test and/Warehouse/TTS169/	PASS
	Name: RCD (Room) Location: CAL Room Test code: Prtble 30mA RCD Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:42:00 Instrument : 18480413	PASS
	RESULTS Result : 0 PARAMETERS	
	Earth Continuity 19.07.2022 16:42:00 Instrument : 18480413	PASS
	RESULTS R : 0.09 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	
	Differential Leakage 19.07.2022 16:42:00 Instrument : 18480413	PASS
	RESULTS Idiff : 0.03 mA Limit : 1.00 mA S : 0.00 kVA PARAMETERS Duration : 2 s	
	RCD 19.07.2022 16:42:00 Instrument : 18480413	PASS
	RESULTS (+) ,t IΔN x1 : 12.0 ms (-) ,t IΔN x1 : 11.5 ms PARAMETERS Test : PRCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
81	Test and/Warehouse/TTS170/	PASS
	Name: Laminator	

	(Room) Location: WAREHOUSE	
	Test code: Dbl Ins Std	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 12:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 11.01.2024 12:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
82	Test and/Warehouse/TTS8014/	PASS
	Name: Red IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2024 00:00:00	
	Visual Inspection 20.07.2023 16:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 20.07.2023 16:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 20.07.2023 16:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 20.07.2023 16:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
83	Test and/Warehouse/TTS00054/	PASS
	Name: Monitor	
	(Room) Location: Warehouse	
	Test code: Earthed App Std	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.28 Ohm	
	Limit : 1.00 Ohm	

	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
84	Test and/Warehouse/TTS00174/	PASS
	Name: Label Winder	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 15:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 12.01.2024 15:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
85	Test and/Warehouse/TTS00183/	PASS
	Name: Printer	
	(Room) Location: Warehouse	
	Test code: Earthed App Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 11:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 11:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 11.01.2024 11:18:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.14 mA	
	Limit : 5.00 mA	
	S : 0.88 kVA	
	PARAMETERS	
	Duration : 10 s	
86	Test and/Warehouse/TTS00190/	PASS
	Name: 15A IEC	
	(Room) Location: WAREHOUSE	
	Test code: IEC/Ext Lead	
	Next test of appliance: 05.01.2026 00:00:00	
	Visual Inspection 06.01.2021 15:44:00	PASS
	Instrument : 18480413	

	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 06.01.2021 15:44:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 06.01.2021 15:44:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 06.01.2021 15:44:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
87	Test and/Warehouse/TTS00191/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 05.01.2026 00:00:00	
	Visual Inspection 06.01.2021 15:48:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 06.01.2021 15:48:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 06.01.2021 15:48:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 06.01.2021 15:48:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
88	Test and/Warehouse/TTS00192/	PASS
	Name: PSU	
	(Room) Location: WAREHOUSE	
	Test code: Earthed App Lkg	
	Next test of appliance: 05.01.2026 00:00:00	
	Visual Inspection 06.01.2021 15:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	

	PARAMETERS	
	Earth Continuity 06.01.2021 15:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.08 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 06.01.2021 15:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.18 mA	
	Limit : 5.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
89	Test and/Warehouse/TTS00193/	PASS
	Name: IEC lead	
	(Room) Location: WAREHOUSE	
	Test code: IEC/Ext Lead	
	Next test of appliance: 05.01.2026 00:00:00	
	Visual Inspection 06.01.2021 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 06.01.2021 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 06.01.2021 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 06.01.2021 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
90	Test and/Warehouse/TTS00194/	PASS
	Name: Modem PSU	
	(Room) Location: WAREHOUSE	
	Test code: Dbl Ins Std	
	Next test of appliance: 05.01.2026 00:00:00	
	Visual Inspection 06.01.2021 15:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 06.01.2021 15:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	

	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
91	Test and/Warehouse/TTS00195/	PASS
	Name: IEC lead	
	(Room) Location: WAREHOUSE	
	Test code: IEC/Ext Lead	
	Next test of appliance: 05.01.2026 00:00:00	
	Visual Inspection 06.01.2021 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 06.01.2021 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 06.01.2021 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 06.01.2021 16:07:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
92	Test and/Warehouse/TTS00197/	PASS
	Name: Red IEC Lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 05.02.2026 00:00:00	
	Visual Inspection 05.02.2025 08:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 05.02.2025 08:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 05.02.2025 08:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 05.02.2025 08:50:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	

93	Test and/Warehouse/TTS00206/	PASS
	Name: Extension Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 12:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 12:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 12:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 12:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
94	Test and/Warehouse/TTS00217/	PASS
	Name: Power Supply	
	(Room) Location: Warehouse	
	Test code: Earthed App Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.22 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 11.01.2024 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.34 mA	
	Limit : 5.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
95	Test and/Warehouse/TTS00237/	PASS
	Name: Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 31.07.2025 00:00:00	

	Visual Inspection 29.01.2025 15:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 29.01.2025 15:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
96	Test and/Warehouse/TTS00238/	PASS
	Name: Kyoritsu lead	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 13:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 11.01.2024 13:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 11.01.2024 13:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
97	Test and/Warehouse/TTS00239/	PASS
	Name: Seaward Lead	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 13:20:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 11.01.2024 13:20:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 11.01.2024 13:20:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 1.00 mA	

	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
98	Test and/Warehouse/TTS00241/	PASS
	Name: Power Board	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:12:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:12:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.08 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:12:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 16:12:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
99	Test and/Warehouse/TTS00242/	PASS
	Name: PC	
	(Room) Location: Warehouse	
	Test code: Earthed App Std	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:15:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:15:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.11 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:15:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
100	Test and/Warehouse/TTS00243/	PASS
	Name: Dyson vac	
	(Room) Location: Warehouse	

	Test code: Dbl Ins Lkg	
	Next test of appliance: 19.01.2023 00:00:00	
	Visual Inspection 20.07.2022 10:30:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 20.07.2022 10:30:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.06 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
101	Test and/Warehouse/TTS00248/	PASS
	Name: IEC Lead	
	(Room) Location: WAREHOUSE	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 11:47:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 11:47:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 11:47:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 11:47:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
102	Test and/Warehouse/TTS00172/	PASS
	Name: Power Supply	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 11.07.2024 11:49:00	
	Visual Inspection 11.01.2024 11:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 11.01.2024 11:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	

	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 11.01.2024 11:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.11 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
103	Test and/Warehouse/TTS0076/	PASS
	Name: Drill	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Std	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 12:55:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 11.01.2024 12:55:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
104	Test and/Warehouse/TTS00104/	PASS
	Name: Extension Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 12:28:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 12:28:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 12:28:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 12:28:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
105	Test and/Warehouse/TTS00039/	PASS
	Name: Extension Lead	
	(Room) Location: Warehouse	

	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 12:21:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 12:21:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 12:21:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 12:21:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
106	Test and/Warehouse/0002/	PASS
	Name: Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:45:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 11.01.2024 16:45:00	PASS
	Instrument : 18480413	
	RESULTS	
	I _{to} : 0.01 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
107	Test and/Warehouse/TTS00151/	PASS
	Name: Power Supply	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:48:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 11.01.2024 16:48:00	PASS
	Instrument : 18480413	
	RESULTS	
	I _{to} : 0.06 mA	
	Limit : 1.00 mA	

	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
108	Test and/Warehouse/TTS0084/	PASS
	Name: Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:43:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 11.01.2024 16:43:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.11 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
109	Test and/Warehouse/TTS00256/	PASS
	Name: C6 IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 11:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 11:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 11:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 11:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
110	Test and/Warehouse/TTS00257/	PASS
	Name: Power Supply	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 11:11:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	

	PARAMETERS	
	Insulation 11.01.2024 11:11:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 11.01.2024 11:11:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.05 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
111	Test and/Warehouse/TTS00258/	PASS
	Name: Power Board	
	(Room) Location: Warehouse	
	Test code: Ext Lead Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 12:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 12:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Polarity 11.01.2024 12:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
	Differential Leakage 11.01.2024 12:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.07 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 2 s	
112	Test and/Warehouse/TTS00259/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 16:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.04 Ohm	

	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 16:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 16:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
113	Test and/Warehouse/TTS00260/	PASS
	Name: Power Board	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.05 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
114	Test and/Warehouse/TTS00262/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 11.07.2024 11:02:00	
	Visual Inspection 11.01.2024 11:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 11:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	

	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 11:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 11:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
115	Test and/Warehouse/TTS00263/	PASS
	Name: Monitor	
	(Room) Location: Warehouse	
	Test code: Earthed App Std	
	Next test of appliance: 11.07.2024 11:04:00	
	Visual Inspection 11.01.2024 11:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 11:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 11:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
116	Test and/Warehouse/TTS00264/	PASS
	Name: Figure 8 Lead	
	(Room) Location: WAREHOUSE	
	Test code: 1	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 10:59:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
117	Test and/Warehouse/TTS00265/	PASS
	Name: Printer PSU	
	(Room) Location: WAREHOUSE	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 11.07.2024 10:57:00	
	Visual Inspection 11.01.2024 10:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 11.01.2024 10:57:00	PASS
	Instrument : 18480413	

	RESULTS	
	Itou : 0.06 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
118	Test and/Warehouse/TTS01003/	PASS
	Name: POWER BOARD	
	(Room) Location: WAREHOUSE	
	Test code: Earthed App Lkg	
	Next test of appliance: 31.07.2025 00:00:00	
	Visual Inspection 29.01.2025 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 29.01.2025 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 29.01.2025 15:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.03 mA	
	Limit : 5.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
119	Test and/Warehouse/TTS171/	PASS
	Name: PSU	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 23.01.2024 00:00:00	
	Visual Inspection 24.07.2023 15:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 24.07.2023 15:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.04 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
120	Test and/Warehouse/TTS01001/	PASS
	Name: IEC Lead	
	(Room) Location: WAREHOUSE	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	

	Earth Continuity 11.01.2024 16:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.05 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 16:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 16:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
121	Test and/Warehouse/TTS01003/	PASS
	Name: AA BATT CHARGER	
	(Room) Location: WAREHOUSE	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 31.07.2025 00:00:00	
	Visual Inspection 29.01.2025 15:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 29.01.2025 15:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.07 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
122	Test and/Warehouse/TTS00275/	PASS
	Name: Monitor PSU	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 14:01:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 11.01.2024 14:01:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.07 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
123	Test and/Warehouse/TTS00276/	PASS
	Name: MRL	
	(Room) Location: Warehouse	
	Test code: 1	

	Next test of appliance: 31.07.2025 00:00:00	
	Visual Inspection 29.01.2025 15:40:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
124	Test and/Warehouse/TTS00277/	PASS
	Name: IEC Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 13:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 11.01.2024 13:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.03 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 11.01.2024 13:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 11.01.2024 13:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
125	Test and/Warehouse/TTS00278/	PASS
	Name: Mini PC PSU	
	(Room) Location: WAREHOUSE	
	Test code: Encap Earth	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 13:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 11.01.2024 13:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 11.01.2024 13:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.06 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	

126	Test and/Warehouse/TTS01004/	PASS
	Name: TSC Psu	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 16:56:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 11.01.2024 16:56:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 11.01.2024 16:56:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.13 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
127	Test and/Warehouse/TTS00279/	NO RESULT
	Name: Power board	
	(Room) Location: Warehouse	
	Test code: Ext Lead Lkg	
	Next test of appliance: 25.01.2024 08:51:54	
128	Test and/Warehouse/TTS00161/	PASS
	Name: Phone Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 11:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 04.02.2025 11:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
129	Test and/Warehouse/TTS00235/	PASS
	Name: Phone Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 10:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	

	PARAMETERS	
	Touch Leakage 04.02.2025 10:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
130	Test and/Warehouse/TTS00139/	PASS
	Name: Phone Charger	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 15.02.2024 00:00:00	
	Visual Inspection 15.02.2023 12:34:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 15.02.2023 12:34:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
131	Test and/Warehouse/TTS00143/	PASS
	Name: Seaward Lead	
	(Room) Location: Show Room	
	Test code: Earthed App Std	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 11:36:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 11:36:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 11:36:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
132	Test and/Warehouse/TTS00152/	PASS
	Name: Battery Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 15.02.2024 00:00:00	
	Visual Inspection 15.02.2023 17:31:00	PASS
	Instrument : 18480413	
	RESULTS	

	Result : 0	
	PARAMETERS	
	Touch Leakage 15.02.2023 17:31:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.01 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
133	Test and/Warehouse/TTS00153/	PASS
	Name: Fig 8 Lead	
	(Room) Location: Show Room	
	Test code: 1	
	Next test of appliance: 15.02.2024 00:00:00	
	Visual Inspection 15.02.2023 17:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
134	Test and/Warehouse/TTS00154/	PASS
	Name: Power Supply	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 15.02.2024 00:00:00	
	Visual Inspection 15.02.2023 17:23:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 15.02.2023 17:23:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.14 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
135	Test and/Warehouse/TTS1003/	PASS
	Name: SEW Lead	
	(Room) Location: Show Room	
	Test code: Earthed App Std	
	Next test of appliance: 05.02.2026 00:00:00	
	Visual Inspection 05.02.2025 08:59:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 05.02.2025 08:59:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.08 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 05.02.2025 08:59:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	

	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
136	Test and/Warehouse/TTS00171/	PASS
	Name: C6 IEC Lead	
	(Room) Location: Showroom	
	Test code: IEC/Ext Lead	
	Next test of appliance: 15.02.2024 00:00:00	
	Visual Inspection 15.02.2023 17:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 15.02.2023 17:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 15.02.2023 17:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 15.02.2023 17:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
137	Test and/Warehouse/TTS00218/	PASS
	Name: Power Supply	
	(Room) Location: Show Room	
	Test code: Encap Earth	
	Next test of appliance: 15.02.2024 00:00:00	
	Visual Inspection 15.02.2023 17:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 15.02.2023 17:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 15.02.2023 17:26:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.14 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
138	Test and/Warehouse/TTS2011/	PASS
	Name: Instaltest Lead	

	(Room) Location: Show Room	
	Test code: Encap Earth	
	Next test of appliance: 05.02.2026 00:00:00	
	Visual Inspection 05.02.2025 09:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 05.02.2025 09:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 05.02.2025 09:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 5.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
139	Test and/Warehouse/TTS00221/	PASS
	Name: Kyoritsu Lead	
	(Room) Location: Show Room	
	Test code: Earthed App Std	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 11:51:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 11:51:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 11:51:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
140	Test and/Warehouse/TTS00223/	PASS
	Name: Phone Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 15.02.2024 00:00:00	
	Visual Inspection 15.02.2023 17:21:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 15.02.2023 17:21:00	PASS
	Instrument : 18480413	

	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
141	Test and/Warehouse/TTS00224/	PASS
	Name: Kyoritsu Lead	
	(Room) Location: Show Room	
	Test code: Earthed App Std	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 15:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 15:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.06 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 15:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
142	Test and/Warehouse/TTS00244/	PASS
	Name: IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 15.02.2024 00:00:00	
	Visual Inspection 15.02.2023 17:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 15.02.2023 17:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 15.02.2023 17:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 15.02.2023 17:25:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
143	Test and/Warehouse/TTS00247/	PASS

	Name: Charger (Room) Location: Show Room Test code: Encap Earth Next test of appliance: 15.02.2024 00:00:00	
	Visual Inspection 15.02.2023 17:17:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Insulation 15.02.2023 17:17:00 Instrument : 18480413 RESULTS Riso : 73.7 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	PASS
	Differential Leakage 15.02.2023 17:17:00 Instrument : 18480413 RESULTS Idiff : 0.05 mA Limit : 1.00 mA S : 0.01 kVA PARAMETERS Duration : 10 s	PASS
144	Test and/Warehouse/TTS00291/	PASS
	Name: Charger (Room) Location: Warehouse Test code: Dbl Ins Lkg Next test of appliance: 12.07.2024 00:00:00	
	Visual Inspection 11.01.2024 10:53:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Touch Leakage 11.01.2024 10:53:00 Instrument : 18480413 RESULTS Itou : 0.04 mA Limit : 1.00 mA S : 0.00 kVA PARAMETERS Duration : 10 s	PASS
145	Test and/Warehouse/TTS00289/	PASS
	Name: C6 IEC Lead (Room) Location: Warehouse Test code: IEC/Ext Lead Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 15:10:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Earth Continuity 12.01.2024 15:10:00 Instrument : 18480413 RESULTS R : 0.08 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	PASS

	Insulation 12.01.2024 15:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 15:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
146	Test and/Warehouse/TTS00290/	PASS
	Name: Ultrasonic	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 15:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 12.01.2024 15:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 12.01.2024 15:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.04 mA	
	Limit : 1.00 mA	
	S : 0.14 kVA	
	PARAMETERS	
	Duration : 10 s	
147	Test and/Warehouse/TTS00291/	NO RESULT
	Name:	
	(Room) Location: Warehouse	
	Test code:	
	Next test of appliance: 12.01.2025 15:32:52	
148	Test and/Warehouse/TTS00294/	PASS
	Name: Truecon Lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 15:35:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 15:35:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.03 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	

	Insulation 12.01.2024 15:35:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 12.01.2024 15:35:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
149	Test and/Warehouse/TTS00051/	PASS
	Name: Label Printer	
	(Room) Location: Warehouse	
	Test code: custom	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 12.01.2024 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.11 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 12.01.2024 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Test and/Warehouse/TTS00003/	PASS
	Name: Scales	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 13.07.2024 00:00:00	
	Visual Inspection 12.01.2024 16:36:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 12.01.2024 16:36:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 12.01.2024 16:36:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	

	Duration : 10 s	
151	Test and/Warehouse/TTS00296/	PASS
	Name: RCD Portable	
	(Room) Location: Warehouse	
	Test code: Prtble 30mA RCD	
	Next test of appliance: 19.07.2024 00:00:00	
	Visual Inspection 18.01.2024 13:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 18.01.2024 13:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.03 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 18.01.2024 13:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.03 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 2 s	
	RCD 18.01.2024 13:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	(+) ,t IΔN x1 : 34.0 ms	
	(-) ,t IΔN x1 : 17.8 ms	
	PARAMETERS	
	Test : PRCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
152	Test and/Warehouse/rcd3/	PASS
	Name: Drill	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Std	
	Next test of appliance: 15.05.2025 00:00:00	
	Visual Inspection 15.05.2024 12:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 15.05.2024 12:54:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
153	Test and/Warehouse/8001/	PASS
	Name: Drill	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Std	
	Next test of appliance: 15.05.2025 00:00:00	
	Visual Inspection 15.05.2024 13:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	

	PARAMETERS	
	Insulation-P 15.05.2024 13:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
154	Test and/Warehouse/TTS00300/	PASS
	Name: Extension lead	
	(Room) Location: Warehouse	
	Test code: iec	
	Next test of appliance: 29.07.2025 15:13:14	
	Visual Inspection 29.01.2025 15:17:34	PASS
	Instrument : 0	
	RESULTS	
	Result : 0	
	PARAMETERS	
155	Test and/Warehouse/TTS00302/	NO RESULT
	Name: Arlec Grid Conn	
	(Room) Location: Warehouse	
	Test code:	
	Next test of appliance: 29.07.2025 15:28:09	
156	Test and/Warehouse/TTS00303/	NO RESULT
	Name:	
	(Room) Location: Warehouse	
	Test code:	
	Next test of appliance: 29.07.2025 15:54:01	
157	Test and/Warehouse/TTS00306/	PASS
	Name: Power Board	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 06.08.2025 00:00:00	
	Visual Inspection 04.02.2025 10:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 10:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 10:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 04.02.2025 10:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	

158	Test and/Warehouse/TTS00310/	PASS
	Name: Power Supply	
	(Room) Location: Warehouse	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 12.08.2025 00:00:00	
	Visual Inspection 10.02.2025 13:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 10.02.2025 13:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.06 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 5 s	
159	Test and/Warehouse/TTS00311/	PASS
	Name: IEC Cable	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.08.2025 00:00:00	
	Visual Inspection 17.02.2025 10:12:00	PASS
	Instrument : 14220268	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 17.02.2025 10:12:00	PASS
	Instrument : 14220268	
	RESULTS	
	R : 0.06 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 17.02.2025 10:12:00	PASS
	Instrument : 14220268	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 17.02.2025 10:12:00	PASS
	Instrument : 14220268	
	RESULTS	
	Fault : 1	
	PARAMETERS	
160	Test and/Warehouse/TTS00312/	PASS
	Name: Seaward Lead	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 19.08.2025 00:00:00	
	Visual Inspection 17.02.2025 10:15:00	PASS
	Instrument : 14220268	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 17.02.2025 10:15:00	PASS
	Instrument : 14220268	

	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 17.02.2025 10:15:00	PASS
	Instrument : 14220268	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
161	Test and/Warehouse/TTS00313/	PASS
	Name: Power Supply	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 19.08.2025 00:00:00	
	Visual Inspection 17.02.2025 10:26:00	PASS
	Instrument : 14220268	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 17.02.2025 10:26:00	PASS
	Instrument : 14220268	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 17.02.2025 10:26:00	PASS
	Instrument : 14220268	
	RESULTS	
	Idiff : 0.13 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
162	Test and/Kitchen/	
163	Test and/Kitchen/TTS0044/	FAIL
	Name: Fridge	
	(Room) Location: Kitchen	
	Test code: Earthed App Std	
	Next test of appliance: 19.01.2022 00:00:00	
	Visual Inspection 19.01.2021 11:14:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.01.2021 11:14:00	FAIL
	Instrument : 18480413	
	RESULTS	
	R : >1999 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.01.2021 11:14:00	NO RESULT
	Instrument : 18480413	
	RESULTS	
	Riso : --- MOhm	

	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
164	Test and/Kitchen/TTS1008/	PASS
	Name: Coffee Machine	
	(Room) Location: Kitchen	
	Test code: Encap Earth	
	Next test of appliance: 19.07.2024 00:00:00	
	Visual Inspection 20.07.2023 15:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 20.07.2023 15:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 20.07.2023 15:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.03 mA	
	Limit : 5.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
165	Test and/Kitchen/TTS00065/	PASS
	Name: Microwave	
	(Room) Location: Kitchen	
	Test code: Earthed App Lkg	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 12:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 12:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.06 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 21.07.2023 12:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.27 mA	
	Limit : 5.00 mA	
	S : 1.27 kVA	
	PARAMETERS	
	Duration : 10 s	
166	Test and/Kitchen/TTS0091/	PASS
	Name: Urn	
	(Room) Location: Kitchen	
	Test code: Earthed App Std	
	Next test of appliance: 18.07.2023 00:00:00	

	Visual Inspection 18.07.2022 14:55:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 18.07.2022 14:55:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.82 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 18.07.2022 14:55:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
167	Test and/Kitchen/TTS00067/	PASS
	Name: Sandwich toast	
	(Room) Location: Kitchen	
	Test code: Earthed App Std	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 12:40:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 12:40:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.11 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 21.07.2023 12:40:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
168	Test and/Kitchen/TTS00178/	PASS
	Name: Fridge	
	(Room) Location: Kitchen	
	Test code: Earthed App Lkg	
	Next test of appliance: 20.01.2024 00:00:00	
	Visual Inspection 21.07.2023 12:43:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 12:43:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.07 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	

	Differential Leakage 21.07.2023 12:43:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.06 mA	
	Limit : 5.00 mA	
	S : 0.11 kVA	
	PARAMETERS	
	Duration : 10 s	
169	Test and/Kitchen/TTS00186/	PASS
	Name: HPM TIMER	
	(Room) Location: KITCHEN	
	Test code: Earthed App Lkg	
	Next test of appliance: 19.07.2024 00:00:00	
	Visual Inspection 20.07.2023 17:12:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 20.07.2023 17:12:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.03 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 20.07.2023 17:12:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.01 mA	
	Limit : 5.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
170	Test and/Kitchen/TTS00270/	NO RESULT
	Name:	
	(Room) Location: Kitchen	
	Test code:	
	Next test of appliance: 20.07.2024 17:16:11	
171	Test and/Kitchen/TTS00271/	PASS
	Name: Urn	
	(Room) Location: Kitchen	
	Test code: Earthed App Std	
	Next test of appliance: 19.07.2024 00:00:00	
	Visual Inspection 20.07.2023 17:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 20.07.2023 17:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.16 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 20.07.2023 17:17:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	

	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
172	Test and/Kitchen/TTS00070/	PASS
	Name: RCD	
	(Room) Location: Kitchen	
	Test code: custom	
	Next test of appliance: 24.07.2024 00:00:00	
	RCD 25.07.2023 08:32:00	PASS
	Instrument : 18480413	
	RESULTS	
	(+) ,t IΔN x1 : 8.3 ms	
	(-) ,t IΔN x1 : 17.3 ms	
	PARAMETERS	
	Test : RCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
173	Test and/Kitchen/rcd2/	PASS
	Name: IEC lead	
	(Room) Location: Kitchen	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.04.2025 00:00:00	
	Visual Inspection 19.04.2024 10:15:00	PASS
	Instrument : 14220268	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.04.2024 10:15:00	PASS
	Instrument : 14220268	
	RESULTS	
	R : 0.14 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.04.2024 10:15:00	PASS
	Instrument : 14220268	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 19.04.2024 10:15:00	PASS
	Instrument : 14220268	
	RESULTS	
	Fault : 1	
	PARAMETERS	
174	Test and/Show Room/	
175	Test and/Show Room/TTS2020/	PASS
	Name: IEC Lead	
	(Room) Location: Reception	
	Test code: IEC/Ext Lead	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 15:53:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 15:53:00	PASS
	Instrument : 18480413	
	RESULTS	

	R : 0.09 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	
	Insulation 21.07.2023 15:53:00 Instrument : 18480413 RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	PASS
	Polarity 21.07.2023 15:53:00 Instrument : 18480413 RESULTS Fault : 1 PARAMETERS	PASS
176	Test and/Show Room/TTS00140/ Name: EFTPOS Charger (Room) Location: Reception Test code: Dbl Ins Lkg Next test of appliance: 18.07.2023 00:00:00	PASS
	Visual Inspection 18.07.2022 14:30:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Touch Leakage 18.07.2022 14:30:00 Instrument : 18480413 RESULTS Itou : 0.00 mA Limit : 1.00 mA S : 0.00 kVA PARAMETERS Duration : 10 s	PASS
177	Test and/Show Room/TTS0220/ Name: HP Printer (Room) Location: Reception Test code: Earthed App Lkg Next test of appliance: 20.07.2024 00:00:00	PASS
	Visual Inspection 21.07.2023 15:57:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Earth Continuity 21.07.2023 15:57:00 Instrument : 18480413 RESULTS R : 0.10 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	PASS
	Differential Leakage 21.07.2023 15:57:00 Instrument : 18480413 RESULTS Idiff : 0.14 mA Limit : 5.00 mA S : 0.01 kVA PARAMETERS Duration : 10 s	PASS
178	Test and/Show Room/TTS00141/	PASS

	Name: IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 17.01.2023 00:00:00	
	Visual Inspection 18.07.2022 11:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 18.07.2022 11:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 18.07.2022 11:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 18.07.2022 11:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
179	Test and/Show Room/TTS00142/	PASS
	Name: Printer Charger	
	(Room) Location: Show Room	
	Test code: Encap Earth	
	Next test of appliance: 17.01.2023 00:00:00	
	Visual Inspection 18.07.2022 11:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 18.07.2022 11:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 18.07.2022 11:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.19 mA	
	Limit : 5.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
180	Test and/Show Room/TTS0088/	PASS
	Name: IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 16:00:00	PASS

	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 16:00:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 21.07.2023 16:00:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 21.07.2023 16:00:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
181	Test and/Show Room/TTS001/	PASS
	Name: Scan Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 23.12.2021 00:00:00	
	Visual Inspection 23.06.2021 17:20:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 23.06.2021 17:20:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.14 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
182	Test and/Show Room/TTS00145/	PASS
	Name: IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 10:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 10:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 10:08:00	PASS
	Instrument : 18480413	

	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 04.02.2025 10:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
183	Test and/Show Room/TTS00146/	PASS
	Name: Printer Charger	
	(Room) Location: Show Room	
	Test code: Encap Earth	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 11:55:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 04.02.2025 11:55:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 04.02.2025 11:55:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.04 mA	
	Limit : 5.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
184	Test and/Show Room/TTS8015/	PASS
	Name: RCD Portable	
	(Room) Location: Show Room	
	Test code: Prtble 30mA RCD	
	Next test of appliance: 06.08.2025 00:00:00	
	Visual Inspection 04.02.2025 12:00:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 12:00:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 04.02.2025 12:00:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.01 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 2 s	

	RCD 04.02.2025 12:00:00	PASS
	Instrument : 18480413	
	RESULTS	
	(+) ,t IΔN x1 : 15.0 ms	
	(-) ,t IΔN x1 : 14.2 ms	
	PARAMETERS	
	Test : PRCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
185	Test and/Show Room/TTS00149/	PASS
	Name: Blue IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 20.01.2024 00:00:00	
	Visual Inspection 21.07.2023 15:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 15:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 21.07.2023 15:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 21.07.2023 15:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
186	Test and/Show Room/TTS00150/	PASS
	Name: Orange IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 20.01.2024 00:00:00	
	Visual Inspection 21.07.2023 15:38:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 15:38:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 21.07.2023 15:38:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	

	Polarity 21.07.2023 15:38:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
187	Test and/Show Room/TTS00123/	PASS
	Name: IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 16:01:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 16:01:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 16:01:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 04.02.2025 16:01:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
188	Test and/Show Room/TTS0089/	PASS
	Name: IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 29.01.2026 00:00:00	
	Visual Inspection 29.01.2025 15:59:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 29.01.2025 15:59:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 29.01.2025 15:59:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 29.01.2025 15:59:00	PASS
	Instrument : 18480413	

	RESULTS	
	Fault : 1	
	PARAMETERS	
189	Test and/Show Room/TTS0074/	PASS
	Name: Red IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 05.02.2026 00:00:00	
	Visual Inspection 05.02.2025 08:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 05.02.2025 08:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 05.02.2025 08:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 05.02.2025 08:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
190	Test and/Show Room/TTS00179/	PASS
	Name: Iso Tx	
	(Room) Location: Show Room	
	Test code: Earthed App Std	
	Next test of appliance: 19.01.2024 00:00:00	
	Visual Inspection 20.07.2023 14:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 20.07.2023 14:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.13 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 20.07.2023 14:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
191	Test and/Show Room/TTS00182/	PASS
	Name: Iso Tx	
	(Room) Location: Show Room	

	Test code: Encap Earth	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 15:31:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 21.07.2023 15:31:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 21.07.2023 15:31:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.04 mA	
	Limit : 5.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
192	Test and/Show Room/TTS00185/	PASS
	Name: Red IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 11:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 11:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 11:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 04.02.2025 11:39:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
193	Test and/Show Room/TTS00202/	PASS
	Name: IEC Lead	
	(Room) Location: Reception	
	Test code: IEC/Ext Lead	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 16:02:00	PASS
	Instrument : 18480413	
	RESULTS	

	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 16:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 21.07.2023 16:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 21.07.2023 16:02:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
194	Test and/Show Room/TTS00204/	PASS
	Name: Power board	
	(Room) Location: Reception	
	Test code: IEC/Ext Lead	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 21.07.2023 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 21.07.2023 16:08:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
195	Test and/Show Room/TTS00010/	PASS
	Name: Extension lead	
	(Room) Location: Warehouse	
	Test code: IEC/Ext Lead	
	Next test of appliance: 06.08.2025 00:00:00	
	Visual Inspection 04.02.2025 09:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	

	Earth Continuity 04.02.2025 09:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 09:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 04.02.2025 09:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
196	Test and/Show Room/TTS00110/	PASS
	Name: Lead figure 8	
	(Room) Location: Show Room	
	Test code: 1	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 11:46:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
197	Test and/Show Room/TTS00188/	PASS
	Name: Figure 8 Lead	
	(Room) Location: Show Room	
	Test code: 1	
	Next test of appliance: 23.12.2021 00:00:00	
	Visual Inspection 23.06.2021 16:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
198	Test and/Show Room/TTS003/	PASS
	Name: Printer Charger	
	(Room) Location: Show Room	
	Test code: Encap Earth	
	Next test of appliance: 23.12.2021 00:00:00	
	Visual Inspection 23.06.2021 16:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 23.06.2021 16:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 23.06.2021 16:57:00	PASS
	Instrument : 18480413	
	RESULTS	

	Idiff : 0.14 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
199	Test and/Show Room/TTS00219/	PASS
	Name: RCD	
	(Room) Location: Show Room	
	Test code: Fixed 30mA RCD	
	Next test of appliance: 24.07.2024 00:00:00	
	RCD 25.07.2023 08:30:00	PASS
	Instrument : 18480413	
	RESULTS	
	(+) ,t IΔN x1 : 8.4 ms	
	(-) ,t IΔN x1 : 17.1 ms	
	PARAMETERS	
	Test : RCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
200	Test and/Show Room/TTS00220/	PASS
	Name: C6 IEC Lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 12.08.2025 00:00:00	
	Visual Inspection 10.02.2025 14:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 10.02.2025 14:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 10.02.2025 14:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 10.02.2025 14:06:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
201	Test and/Show Room/TTS00222/	PASS
	Name: Scan Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 15:15:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 21.07.2023 15:15:00	PASS
	Instrument : 18480413	
	RESULTS	

	Itou : 0.03 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
202	Test and/Show Room/TTS00223/	PASS
	Name: Phone Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 17.01.2023 00:00:00	
	Visual Inspection 18.07.2022 11:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 18.07.2022 11:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
203	Test and/Show Room/TTS00225/	PASS
	Name: Phone Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 19.01.2023 00:00:00	
	Visual Inspection 20.07.2022 12:35:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 20.07.2022 12:35:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
204	Test and/Show Room/TTS00226/	PASS
	Name: Phone Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 16:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 04.02.2025 16:10:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	

205	Test and/Show Room/TTS00227/	PASS
	Name: Power Board	
	(Room) Location: Show Room	
	Test code: Ext Lead Lkg	
	Next test of appliance: 20.01.2022 00:00:00	
	Visual Inspection 21.07.2021 09:31:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2021 09:31:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Polarity 21.07.2021 09:31:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
	Differential Leakage 21.07.2021 09:31:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.03 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 2 s	
206	Test and/Show Room/TTS00228/	PASS
	Name: Power Board	
	(Room) Location: Show Room	
	Test code: Ext Lead Lkg	
	Next test of appliance: 06.08.2025 00:00:00	
	Visual Inspection 04.02.2025 10:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 10:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Polarity 04.02.2025 10:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
	Differential Leakage 04.02.2025 10:19:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 2 s	

207	Test and/Show Room/TTS00229/	PASS
	Name: Power Supply	
	(Room) Location: Show Room	
	Test code: Encap Earth	
	Next test of appliance: 10.02.2026 00:00:00	
	Visual Inspection 10.02.2025 14:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 10.02.2025 14:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 10.02.2025 14:09:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.05 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
208	Test and/Show Room/TTS00230/	PASS
	Name: Television	
	(Room) Location: Show Room	
	Test code: Dbl Ins Std	
	Next test of appliance: 10.02.2026 00:00:00	
	Visual Inspection 10.02.2025 13:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation-P 10.02.2025 13:58:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso-S : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
209	Test and/Show Room/TTS00203/	PASS
	Name: Dell PC	
	(Room) Location: Reception	
	Test code: Earthed App Std	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 21.07.2023 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.11 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	

	Insulation 21.07.2023 16:04:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
210	Test and/Show Room/TTS00250/	PASS
	Name: IEC Lead LH	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 05.02.2026 00:00:00	
	Visual Inspection 05.02.2025 08:56:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 05.02.2025 08:56:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 05.02.2025 08:56:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 05.02.2025 08:56:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
211	Test and/Show Room/TTS00251/	PASS
	Name: IEC Lead RH	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2024 00:00:00	
	Visual Inspection 20.07.2023 16:03:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 20.07.2023 16:03:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 20.07.2023 16:03:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	

	Polarity 20.07.2023 16:03:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
212	Test and/Show Room/TTS00267/	PASS
	Name: Power Board	
	(Room) Location: Show Room	
	Test code: Ext Lead Lkg	
	Next test of appliance: 10.02.2026 00:00:00	
	Visual Inspection 10.02.2025 13:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 10.02.2025 13:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Polarity 10.02.2025 13:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
	Differential Leakage 10.02.2025 13:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.05 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 2 s	
213	Test and/Show Room/TTS00268/	PASS
	Name: Power Board	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 10.02.2026 00:00:00	
	Visual Inspection 10.02.2025 13:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 10.02.2025 13:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 10.02.2025 13:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 10.02.2025 13:52:00	PASS

	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
214	Test and/Show Room/TTS00269/	PASS
	Name: Phone Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 16:15:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 04.02.2025 16:15:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
215	Test and/Show Room/TTS00118/	PASS
	Name: IEC lead	
	(Room) Location: Show Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 29.01.2026 00:00:00	
	Visual Inspection 29.01.2025 14:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 29.01.2025 14:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 29.01.2025 14:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 29.01.2025 14:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
216	Test and/Show Room/TTS00167/	PASS
	Name: Battery Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 11:23:00	PASS
	Instrument : 18480413	
	RESULTS	

	Result : 0	
	PARAMETERS	
	Touch Leakage 04.02.2025 11:23:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.05 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
217	Test and/Show Room/TTS00272/	PASS
	Name: Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 11:41:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 04.02.2025 11:41:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
218	Test and/Show Room/TTS00273/	PASS
	Name: Tx	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 04.02.2026 00:00:00	
	Visual Inspection 04.02.2025 15:46:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 04.02.2025 15:46:00	PASS
	Instrument : 18480413	
	RESULTS	
	Itou : 0.00 mA	
	Limit : 1.00 mA	
	S : 0.03 kVA	
	PARAMETERS	
	Duration : 10 s	
219	Test and/Show Room/TTS00274/	PASS
	Name: Charger	
	(Room) Location: Show Room	
	Test code: Dbl Ins Lkg	
	Next test of appliance: 20.07.2024 00:00:00	
	Visual Inspection 21.07.2023 15:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Touch Leakage 21.07.2023 15:49:00	PASS
	Instrument : 18480413	
	RESULTS	

	Itou : 0.01 mA	
	Limit : 1.00 mA	
	S : 0.01 kVA	
	PARAMETERS	
	Duration : 10 s	
220	Test and/Show Room/RCD003/	PASS
	Name: RCD	
	(Room) Location: Show Room	
	Test code: Fixed 30mA RCD	
	Next test of appliance: 24.07.2024 00:00:00	
	RCD 25.07.2023 08:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	(+) ,t IΔN x1 : 5.7 ms	
	(-) ,t IΔN x1 : 15.6 ms	
	PARAMETERS	
	Test : RCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
221	Test and/Show Room/TTS00307/	PASS
	Name: Toaster	
	(Room) Location: Show Room	
	Test code: Earthed App Std	
	Next test of appliance: 06.08.2025 00:00:00	
	Visual Inspection 04.02.2025 12:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 12:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.11 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 12:27:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
222	Test and/Show Room/TTS00308/	PASS
	Name: Iron	
	(Room) Location: Show Room	
	Test code: Earthed App Std	
	Next test of appliance: 06.08.2025 00:00:00	
	Visual Inspection 04.02.2025 12:32:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 04.02.2025 12:32:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.10 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 04.02.2025 12:32:00	PASS

	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
223	Test and/CAL Room/	
224	Test and/CAL Room/TTS00205/	PASS
	Name: Instaltest Lead	
	(Room) Location: Warehouse	
	Test code: Encap Earth	
	Next test of appliance: 06.08.2025 00:00:00	
	Visual Inspection 04.02.2025 16:05:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Insulation 04.02.2025 16:05:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Differential Leakage 04.02.2025 16:05:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.02 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
225	Test and/CAL Room/AT2010-PH3/	PASS
	Name: 3 Phase RCD	
	(Room) Location: CAL Room	
	Test code: Fixed 30mA RCD	
	Next test of appliance: 19.07.2024 00:00:00	
	RCD 20.07.2023 15:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	(+) ,t IΔN x1 : 25.6 ms	
	(-) ,t IΔN x1 : 35.9 ms	
	PARAMETERS	
	Test : RCD IΔN : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
226	Test and/CAL Room/TTS00232/	PASS
	Name: IEC lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 16:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	

	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.07.2022 16:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 19.07.2022 16:22:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
227	Test and/CAL Room/TTS00233/	PASS
	Name: DMM 6500	
	(Room) Location: CAL Room	
	Test code: Earthed App Lkg	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 16:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.07 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 19.07.2022 16:24:00	PASS
	Instrument : 18480413	
	RESULTS	
	Idiff : 0.04 mA	
	Limit : 5.00 mA	
	S : 0.05 kVA	
	PARAMETERS	
	Duration : 10 s	
228	Test and/CAL Room/TTS00072/	PASS
	Name: IEC Lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 29.01.2026 00:00:00	
	Visual Inspection 29.01.2025 16:05:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 29.01.2025 16:05:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 29.01.2025 16:05:00	PASS
	Instrument : 18480413	
	RESULTS	

	Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	
	Polarity 29.01.2025 16:05:00 Instrument : 18480413 RESULTS Fault : 1 PARAMETERS	PASS
229	Test and/CAL Room/TTS00253/	PASS
	Name: IEC Lead RH (Room) Location: CAL Room Test code: IEC/Ext Lead Next test of appliance: 29.01.2026 00:00:00	
	Visual Inspection 29.01.2025 16:02:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Earth Continuity 29.01.2025 16:02:00 Instrument : 18480413 RESULTS R : 0.09 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	PASS
	Insulation 29.01.2025 16:02:00 Instrument : 18480413 RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	PASS
	Polarity 29.01.2025 16:02:00 Instrument : 18480413 RESULTS Fault : 1 PARAMETERS	PASS
230	Test and/CAL Room/TTS00253/	PASS
	Name: Kyoritsu Lead (Room) Location: CAL Room Test code: Encap Earth Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 15:19:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Insulation 19.07.2022 15:19:00 Instrument : 18480413 RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	PASS
	Differential Leakage 19.07.2022 15:19:00 Instrument : 18480413 RESULTS Idiff : 0.01 mA Limit : 1.00 mA	PASS

	S : 0.00 kVA	
	PARAMETERS	
	Duration : 10 s	
231	Test and/CAL Room/TTS00254/	PASS
	Name: Cal Box	
	(Room) Location: CAL Room	
	Test code: Earthed App Lkg	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 15:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 15:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.03 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 19.07.2022 15:37:00	PASS
	Instrument : 18480413	
	RESULTS	
	I _{diff} : 0.12 mA	
	Limit : 5.00 mA	
	S : 0.02 kVA	
	PARAMETERS	
	Duration : 30 s	
232	Test and/CAL Room/AT2005/	PASS
	Name: TOASTER	
	(Room) Location: CAL ROOM	
	Test code: Earthed App Std	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:33:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 16:33:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.17 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.07.2022 16:33:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
233	Test and/CAL Room/TTS00255/	PASS
	Name: RCD Portable	
	(Room) Location: CAL Room	
	Test code: Prtble 30mA RCD	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 16:49:00	PASS
	Instrument : 18480413	

	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 16:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Differential Leakage 19.07.2022 16:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	I _{diff} : 0.04 mA	
	Limit : 1.00 mA	
	S : 0.00 kVA	
	PARAMETERS	
	Duration : 2 s	
	RCD 19.07.2022 16:49:00	PASS
	Instrument : 18480413	
	RESULTS	
	(+) ,t I _{ΔN} x1 : 28.1 ms	
	(-) ,t I _{ΔN} x1 : 22.3 ms	
	PARAMETERS	
	Test : PRCD I _{ΔN} : 30 mA Multiplier : 1 Phase/mode : (0, 180)	
234	Test and/CAL Room/TTS00199/	PASS
	Name: Cal Box Lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 19.07.2023 00:00:00	
	Visual Inspection 19.07.2022 15:33:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 19.07.2022 15:33:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 19.07.2022 15:33:00	PASS
	Instrument : 18480413	
	RESULTS	
	R _{iso} : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 19.07.2022 15:33:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
235	Test and/CAL Room//	PASS
	Name:	
	(Room) Location:	
	Test code: custom	
	Next test of appliance: 29.01.2025 00:00:00	
	Visual Inspection 29.01.2025 15:52:00	PASS

	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 29.01.2025 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 29.01.2025 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 29.01.2025 15:52:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
236	Test and/CAL Room/TTS00305/	PASS
	Name: IEC Lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 31.07.2025 00:00:00	
	Visual Inspection 29.01.2025 15:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Result : 0	
	PARAMETERS	
	Earth Continuity 29.01.2025 15:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	R : 0.09 Ohm	
	Limit : 1.00 Ohm	
	PARAMETERS	
	I out : 200 mA Duration : 2 s	
	Insulation 29.01.2025 15:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Riso : >200 MOhm	
	Limit : 1 MOhm	
	PARAMETERS	
	Output iso voltage : 500 V Duration : 2 s	
	Polarity 29.01.2025 15:57:00	PASS
	Instrument : 18480413	
	RESULTS	
	Fault : 1	
	PARAMETERS	
237	Test and/CAL Room/TTS0285/	PASS
	Name: Extension lead	
	(Room) Location: CAL Room	
	Test code: IEC/Ext Lead	
	Next test of appliance: 07.08.2025 00:00:00	
	Visual Inspection 05.02.2025 09:11:00	PASS
	Instrument : 18480413	
	RESULTS	

	Result : 0 PARAMETERS	
	Earth Continuity 05.02.2025 09:11:00 Instrument : 18480413 RESULTS R : 0.09 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	PASS
	Insulation 05.02.2025 09:11:00 Instrument : 18480413 RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	PASS
	Polarity 05.02.2025 09:11:00 Instrument : 18480413 RESULTS Fault : 1 PARAMETERS	PASS
238	Test and/CAL Room// Name: (Room) Location: Test code: Earthed App Std Next test of appliance: 05.02.2025 00:00:00	PASS
	Visual Inspection 05.02.2025 09:16:00 Instrument : 18480413 RESULTS Result : 0 PARAMETERS	PASS
	Earth Continuity 05.02.2025 09:16:00 Instrument : 18480413 RESULTS R : 0.14 Ohm Limit : 1.00 Ohm PARAMETERS I out : 200 mA Duration : 2 s	PASS
	Insulation 05.02.2025 09:16:00 Instrument : 18480413 RESULTS Riso : >200 MOhm Limit : 1 MOhm PARAMETERS Output iso voltage : 500 V Duration : 2 s	PASS
239	Test and/CAL Room/TTS0284/	NO RESULT
	Name: (Room) Location: CAL Room Test code: Next test of appliance: 05.08.2025 09:24:02	
240	Test and/RCD/	
241	Test and/Kitchen/	