
view_frames Result
Recorded at time: 1785599072.5369277
map
Broadcaster: default_authority
Average rate: 10000.0
Buffer length: 0.0
Most recent transform: 0.0
Oldest transform: 0.0
survillance_1/ua_nav4/odom
inspection_1/ua_ins1/odom
logistic_1/ua_log3/odom
inspection_1/ua_ins2/odom
Broadcaster: default_authority
Average rate: 100.159
Buffer length: 5.032
Most recent transform: 354.988
Oldest transform: 349.956
survillance_1/ua_nav4/base_link
Broadcaster: default_authority
Average rate: 100.186
Buffer length: 3.224
Most recent transform: 354.988
Oldest transform: 351.764
inspection_1/ua_ins1/base_link
Broadcaster: default_authority
Average rate: 100.368
Buffer length: 2.72
Most recent transform: 354.988
Oldest transform: 352.268
logistic_1/ua_log3/base_link
Broadcaster: default_authority
Average rate: 100.444
Buffer length: 3.156
Most recent transform: 354.988
Oldest transform: 351.832
inspection_1/ua_ins2/base_link
survillance_1/ua_nav4/arm_x_visual
survillance_1/ua_nav4/camera_link
survillance_1/ua_nav4/rotor_1_link
survillance_1/ua_nav4/rotor_2_link
survillance_1/ua_nav4/rotor_3_link
survillance_1/ua_nav4/rotor_4_link
inspection_1/ua_ins1/arm_x_visual
inspection_1/ua_ins1/camera_link
inspection_1/ua_ins1/rotor_1_link
inspection_1/ua_ins1/rotor_2_link
inspection_1/ua_ins1/rotor_3_link
inspection_1/ua_ins1/rotor_4_link
logistic_1/ua_log3/arm_x_visual
logistic_1/ua_log3/camera_link
logistic_1/ua_log3/rotor_1_link
logistic_1/ua_log3/rotor_2_link
logistic_1/ua_log3/rotor_3_link
logistic_1/ua_log3/rotor_4_link
inspection_1/ua_ins2/arm_x_visual
inspection_1/ua_ins2/camera_link
inspection_1/ua_ins2/rotor_1_link
inspection_1/ua_ins2/rotor_2_link
inspection_1/ua_ins2/rotor_3_link
inspection_1/ua_ins2/rotor_4_link