

PARTE Nº 8

CLIENT	WORKER	DATE	START TIME	FINISH TIME
Cliente 1	santi	14/05/2016	13:49	15:48
SIGNER		LOCATION		
Santi		Carrer de Ramon de Montcada, 32, 07183 Rotes Velles, Illes Balears, Spain		

Tasks:

TASK	VALUE
RAKING LEAVES	YES
CLEANING SKIMERS	YES
CLEANING PREFILTER	YES
RINSE FILTER	YES
OTHERS	Change main engine

Measurements:

MEASURING	VALUE
CHLORINE	1
PH	45
SALT	35
ISOCYANURIC	6
TURBIDITY	9

Observations:

The pool had a water loss

Incidences:

Filter number 2 out of service

Signature:



Signer:

Santi

