

FORM SURVEY RISIKO KENDARAAN BERMOTOR

No. SPPA	:	Merk Kendaraan	: TOYOTA KIJANG INNOVA G 2.0 M/T
Tertanggung	:	Tahun Pembuatan	: 2014
Tgl. Survey	:	No. Polisi	: D 1014 UY
PIC di Tempat	:	No. Rangka	: MHFXW42GXE2291492
No. Telp. Survey	:	No Mesin	: 1TR7813959
Alamat Survey	:	Warna	: Putih
Teten blazer, komp bukit mekar B64 Rt01/21 ds.cimekar kec.cileunyi kab.bandung			

1. Cacat Semula

	OK	NO	Keterangan
Bumper Belakang Leced			
Pintu Depan Dan Tengah Kanan	Leced	+1jengkal	

2. Perlengkapan Tambahan

	OK	NO	Keterangan
Kaca Film 3m			untuk kaca pintu depan belakang kanan kiri me
Kaca Film Cp F1			untuk kaca bagasi belakang dan kaca depan mem

3. Keterangan Tambahan & Rekomendasi

Casem lebih dari 2 panel

TLO

[Click](#)

ATTACHMENT

DATA

- KTP : <http://ricoapp.ptdtsu.id/files/upload/23913-2019-07-31-14-07-18.png>
- STNK : <http://ricoapp.ptdtsu.id/files/upload/12249-2019-07-31-14-07-08.png>

EXTERIOR

- Kiri Depan : <http://ricoapp.ptdtsu.id/files/upload/28825-2019-07-31-14-07-18.png>
- Tampak Depan : <http://ricoapp.ptdtsu.id/files/upload/21772-2019-07-31-14-07-08.png>
- Kanan Depan : <http://ricoapp.ptdtsu.id/files/upload/14288-2019-07-31-14-07-32.png>
- Kiri Belakang : <http://ricoapp.ptdtsu.id/files/upload/26032-2019-07-31-14-07-52.png>
- Tampak Belakang : <http://ricoapp.ptdtsu.id/files/upload/19288-2019-07-31-14-07-25.png>
- Kanan Belakang : <http://ricoapp.ptdtsu.id/files/upload/13870-2019-07-31-14-07-39.png>
- Velg Kiri Depan : <http://ricoapp.ptdtsu.id/files/upload/19614-2019-07-31-14-07-03.png>
- Velg Kanan Depan : <http://ricoapp.ptdtsu.id/files/upload/21834-2019-07-31-14-07-51.png>
- Velg Kiri Belakang : <http://ricoapp.ptdtsu.id/files/upload/10574-2019-07-31-14-07-26.png>
- Velg Kanan Belakang : <http://ricoapp.ptdtsu.id/files/upload/23089-2019-07-31-14-07-04.png>
- Tampak Atas : <http://ricoapp.ptdtsu.id/files/upload/26846-2019-07-31-14-07-01.png>
- Tampak Bawah : <http://ricoapp.ptdtsu.id/files/upload/19144-2019-07-31-14-07-47.png>
- No Rangka/Mesin : <http://ricoapp.ptdtsu.id/files/upload/26958-2019-07-31-14-07-42.png>

DATA

- Door Trim Kiri Depan : <http://ricoapp.ptdtsu.id/files/upload/IMG-144603.png>-2019-07-31-14-07-03.png
- Door Trim Kanan Depan : <http://ricoapp.ptdtsu.id/files/upload/IMG-144949.png>-2019-07-31-14-07-50.png
- Door Trim Kiri Belakang : <http://ricoapp.ptdtsu.id/files/upload/IMG-144934.png>-2019-07-31-14-07-34.png
- Door Trim Kanan Belakang: <http://ricoapp.ptdtsu.id/files/upload/IMG-144845.png>-2019-07-31-14-07-46.png
- Tongkat Transmisi : <http://ricoapp.ptdtsu.id/files/upload/IMG-144619.png>-2019-07-31-14-07-20.png
- Bagasi : <http://ricoapp.ptdtsu.id/files/upload/IMG-144731.png>-2019-07-31-14-07-31.png
- Dashbaord : <http://ricoapp.ptdtsu.id/files/upload/IMG-144654.png>-2019-07-31-14-07-55.png
- Jok : <http://ricoapp.ptdtsu.id/files/upload/IMG-144704.png>-2019-07-31-14-07-04.png
- Langit - langit : <http://ricoapp.ptdtsu.id/files/upload/IMG-144719.png>-2019-07-31-14-07-20.png
- Console Box : <http://ricoapp.ptdtsu.id/files/upload/IMG-144810.png>-2019-07-31-14-07-12.png
- Tape : <http://ricoapp.ptdtsu.id/files/upload/IMG-144751.png>-2019-07-31-14-07-52.png
- Lainnya : <http://ricoapp.ptdtsu.id/files/upload/IMG-144821.png>-2019-07-31-14-07-22.png

PERLENGKAPAN TAMBAHAN

- kaca film 3m : <http://ricoapp.ptdtsu.id/files/upload/IMG-145148.png>-2019-07-31-14-07-48.png
- kaca film 3m : <http://ricoapp.ptdtsu.id/files/upload/IMG-145157.png>-2019-07-31-14-07-58.png
- kaca film 3m : <http://ricoapp.ptdtsu.id/files/upload/IMG-145209.png>-2019-07-31-14-07-10.png
- kaca film 3m : <http://ricoapp.ptdtsu.id/files/upload/IMG-145219.png>-2019-07-31-14-07-20.png
- kaca film cp f1 : <http://ricoapp.ptdtsu.id/files/upload/IMG-145354.png>-2019-07-31-14-07-56.png
- kaca film cp f1 : <http://ricoapp.ptdtsu.id/files/upload/IMG-145402.png>-2019-07-31-14-07-03.png
- kaca film cp f1 : <http://ricoapp.ptdtsu.id/files/upload/IMG-145414.png>-2019-07-31-14-07-14.png
- kaca film cp f1 : <http://ricoapp.ptdtsu.id/files/upload/IMG-145421.png>-2019-07-31-14-07-22.png
- kaca film cp f1 : <http://ricoapp.ptdtsu.id/files/upload/IMG-145456.png>-2019-07-31-14-07-57.png

CACAT

- bumper belakang leced :
 - Tampak Dekat : <http://ricoapp.ptdtsu.id/files/upload/IMG-145559.png>-2019-07-31-14-07-00.png
 - Tampak Sedang : <http://ricoapp.ptdtsu.id/files/upload/IMG-145551.png>-2019-07-31-14-07-51.png
 - Tampak Jauh : <http://ricoapp.ptdtsu.id/files/upload/IMG-145544.png>-2019-07-31-14-07-44.png
- pintu depan dan tengah kanan leced -+1jengkal :
 - Tampak Dekat : <http://ricoapp.ptdtsu.id/files/upload/IMG-145738.png>-2019-07-31-14-07-38.png
 - Tampak Sedang : <http://ricoapp.ptdtsu.id/files/upload/IMG-145726.png>-2019-07-31-14-07-26.png
 - Tampak Jauh : <http://ricoapp.ptdtsu.id/files/upload/IMG-145716.png>-2019-07-31-14-07-17.png