

VISIONINSPECT AI - QUALITY REPORT

Inspection ID: 143

Image Filename: 1785849503_001.png

AI Decision: FAIL

Defect Type Classified: scratch

Confidence / Score: 850.0%

Severity Level: high

Production Line: Unassigned

Batch Number: Unassigned

Operator: Quality Engineer

Timestamp: 2026-08-04T18:48:24.334995

STATUS: THE PRODUCT COMPLIES WITH ALL AI AND SEGMENTATION STANDARDS.