

VISIONINSPECT AI - QUALITY REPORT

Inspection ID: 162

Image Filename: 1785921333_001.png

AI Decision: PASS

Defect Type Classified: none

Confidence / Score: 950.0%

Severity Level: none

Production Line: Unassigned

Batch Number: Unassigned

Operator: Quality Engineer

Timestamp: 2026-08-05T14:45:34.281708

STATUS: THE PRODUCT COMPLIES WITH ALL AI AND SEGMENTATION STANDARDS.