Sep 26

MEENAKSHI POLYMERS PVT. LTD. HARIDWAR

BS6 MODEL COMPONENT STRAIGHT PASS MONITORING SHEET

SNO	PART NAME	PART NUMBER	MODEL	APRIL	MAY	JUNE	JULY	AUGUST	PARAMTER	21 A	21 B	21 TOTAL	22 A	22 B	22 TOTAL	23 A	23 B	23 TOTAL	24 A	24 B	24 TOTAL	25 A	25 B	25 TOTAL	26 A	26 B	26 TOTAL	27 A	27 B	27 TOTAL	28 A	28 B	28 TOTAL	29 A	29 B	29 TOTAL	30 A	30 B	30 TOTAL
1	ENGINE GUARD KST	50803-KST-9400	KST						CHECKED QTY.		1748		2758	1600		2590	2000		2200	1925		2540	1790		1872					2658	1800		2620	1880				
									OK QTY.		1193		2050	1277		1820	1429		1680	1346		1839	1297		1334					1968	1345		1860	1480				
									REJ. QTY.																															
									REW. QTY.		550		700	522		770	571		520	582		701	493		539			1	1	687	455		760	400				
									TOTAL REWORK OK QTY		550		700	522		770	571		505	582		701	493		539			1	1	664	455		670	400				
									INSPECTION/CHIPPING PENDING										15																				
									VISUAL DEFECTS STRAIGHT PASS		68%		74%	76%		70%	71%		76%	69%		78%	72%		21%			1	1	74%	74%		76%	78%				
									NO. OF NON CONFORMITY										—																				
2	CARRIER LINE-01	81200-AAD-3000	AAD						CHECKED QTY.	955			500			500			530			510			500					430								
									OK QTY.	240			385			365			370			375			375					240								
									REJ. QTY.																														
									REW. QTY.																														
									TOTAL REWORK OK QTY	210			110			130			160			130			120			1	1	190			190					
									INSPECTION/CHIPPING PENDING	210			110			130			160			130			120														
									VISUAL DEFECTS STRAIGHT PASS	52%			77%			73%			69%			73%			75%					58%								
									NO. OF NON CONFORMITY																														
3	CARRIER LINE-R	81200-AAD-3000	AAD Reject						CHECKED QTY.	1100	1428		1525	1550		1500	1450		1530	1425		1475	1525		1575	1605				1300	1600		1500	1585				
									OK QTY.	700	654		961	877		943	753		891	752		844	874		822	1065				770	1061		823	1004				
									REJ. QTY.		774																												
									REW. QTY.	480	774		574	673		557	697		639	673		631	651		548	540				560	529		577	581				
									TOTAL REWORK OK QTY	476			574	673		557	697		639	673		631	651		548	540		1	1	560	529		577	581				
									INSPECTION/CHIPPING PENDING	—																														
									VISUAL DEFECTS STRAIGHT PASS	50%	45%		62%	56%		62%	51%		58%	52%		57%	57%		60%	66%				57%	66%		61%	59%				
									NO. OF NON CONFORMITY																														
4	CARRIER LINE-R AAEL	81200A-AAE-3000	AAEL						CHECKED QTY.		1160		1240	1180		770	1200		1330	1110		1235	1140		830	1250				820			993	1200				
									OK QTY.		691		731	792		448	723		752	690		691	620		491	792				470			584	907				
									REJ. QTY.								—			—			—		—	—							—	—				
									REW. QTY.		469		509	388		322	477		578	420		544	532		339	428		1	1	356			404	293				
									TOTAL REWORK OK QTY		469		499	388		290	477		578	420		532	530		339	428		1	1	356			409	293				
									INSPECTION/CHIPPING PENDING																									—	—				
									VISUAL DEFECTS STRAIGHT PASS		59%		58%	67%		58%	60%		56%	62%		55%	54%		59%	63%				57%			55%	75%				
									NO. OF NON CONFORMITY																														
5	MAIN STAND	50500-AAE-3000	AAEE						CHECKED QTY.	600			570	632		580	528		515	571		596	596		580	606				590	591		485	530				
									OK QTY.	465			455	461		464	391		415	446		477	472		467	499				461	333		385	412				
									REJ. QTY.																														
									REW. QTY.	135			115	171		116	137		166	131		113	124		113	107		1	1	109	258		100	118				
									TOTAL REWORK OK QTY	135			115	171		116	137		166	131		113	124		113	107		1	1	109	258		100	118				
									INSPECTION/CHIPPING PENDING																														
									VISUAL DEFECTS STRAIGHT PASS	77%			80%	72%		80%	77%		80%	77%		81%	73%		80%	82%				80%	56%		79%	77%				
									NO. OF NON CONFORMITY																														
6	MAIN STAND	50500-AACK-3000	ACK						CHECKED QTY.	1202			1295	1166		1313	1266		955	1293		1170	1244		1095	1191				1370	1377		1180	1279				
									OK QTY.	901			1023	824		1053	949		779	1012		959	1043		877	925				993	1175		948	1032				
									REJ. QTY.	01																													
									REW. QTY.	381			272	342		262	311		183	281		231	201		218	266		1	1	237	202		232	247				
									TOTAL REWORK OK QTY	381			272	342		262	311		183	281		231	201		218	266		1	1	237	202		232	247				
									INSPECTION/CHIPPING PENDING																														
									VISUAL DEFECTS STRAIGHT PASS	74%			79%	70%		80%	75%		81%	78%		80%	83%		80%	77%				81%	85%		80%	77%				
									NO. OF NON CONFORMITY																														
7	PEDAL BRAKE	50500-AAE-0000	AAEN						CHECKED QTY.				1500	1650		1705	825		2003	460		1587	1305		2372	2400				2250	2330		1450	2400				
									OK QTY.				1265	1135		1354	589		1684	358		1308	1843		2013	1937				1780	1878		1097	1952				
									REJ. QTY.																														
									REW. QTY.				235	515		351	236		314	102		276	462		358	463			1	414	452		353	448				
									TOTAL REWORK OK QTY				235	515		351	236		314	102		276	462		389	463			1	414	452		353	448				
									INSPECTION/CHIPPING PENDING																														
									VISUAL DEFECTS STRAIGHT PASS				84%	58%		79%	71%		84%	77%		82%	79%		84%	80%				78%	80%		75%	81%				
									NO. OF NON CONFORMITY																														

Revision no. 01
Revision Detail:- NON CONFORMITY point Added on 01.06.2025

Sept 25

MEENAKSHI POLYMERS PVT. LTD. HARIDWAR

BS6 MODEL COMPONENT STRAIGHT PASS MONITORING SHEET

SNO	PART NAME	PART NUMBER	MODEL	APRIL	MAY	JUNE	JULY	AUGUST	PARAMTER	21 A	21 B	21 TOTAL	22 A	22 B	22 TOTAL	23 A	23 B	23 TOTAL	24 A	24 B	24 TOTAL	25 A	25 B	25 TOTAL	26 A	26 B	26 TOTAL	27 A	27 B	27 TOTAL	28 A	28 B	28 TOTAL	29 A	29 B	29 TOTAL	30 A	30 B	30 TOTAL
8	PEDAL GEAR CHANGE	2470A-ACK-0000	ACKA						CHECKED QTY.				710			895			1160			700			1189						1198	995		550					
									OK QTY.				675			833			1043			647			1120						1110	958		500					
									REJ. QTY.																							-								
									REW. QTY.				40			62			57			53			75			1/2			90	45		53					
									TOTAL REWORK OK QTY				35	1/2		62			57			53			69			1/2			88	45		50					
									INSPECTION/CHIPPING PENDING																							-								
									VISUAL DEFECTS STRAIGHT PASS				95%			93%			94%			927			94%						92%	95%		90%					
									NO. OF NON CONFORMITY																							-								
9	PEDAL GEAR CHANGE	24701-AAE-3000	AAE						CHECKED QTY.		2510		2385	2180		2500	3225		2859	3110		2200	3445		3062	2665					2050	2195		2330					
									OK QTY.		2430		2217	2059		2374	3096		2726	2970		2089	3591		2870	2530					2800	2100		2170					
									REJ. QTY.																															
									REW. QTY.		80		191	121		126	129		124	140		111	154		300	135		1/2	1/2		310	95		179					
									TOTAL REWORK OK QTY		80		168	121		126	129		124	140		111	154		242	135		1/2	1/2		250	95		160					
									INSPECTION/CHIPPING PENDING																250			1												
									VISUAL DEFECTS STRAIGHT PASS		96%			94%		94%	96%		95%	95%		94%	95%		92%	94%					91%	95%		93%	790				
									NO. OF NON CONFORMITY																															
10	STEP WOMEN	51104-AAH-0300							CHECKED QTY.				400	800		560	200		1200			1645			700						1204	1145		1020	770				
									OK QTY.				384	710		1386	174		1050			1492			642						1069	1114		930	687				
									REJ. QTY.																															
									REW. QTY.				52	90		174	26		150			153			58			1/2	1/2		135	82		90	83				
									TOTAL REWORK OK QTY				52	90		174	26		150			153			58			1/2	1/2		135	82		90	83				
									INSPECTION/CHIPPING PENDING																															
									VISUAL DEFECTS STRAIGHT PASS				87%	88%		88%	87%		87%			90%			91%						88%	83%		91%	89				
									NO. OF NON CONFORMITY																															
11	STEP PILLION	51104-AAE-H000							CHECKED QTY.		3300		2608	3252		2036	2825		2220	3188		2100			2268						2792	1340		3192	3196				
									OK QTY.		2910		2241	2902		1762	2495		1825	2858		1839			1899						2512	796		2852	2812				
									REJ. QTY.																							-								
									REW. QTY.		350		417	550		274	330		195	330		287			369			1/2	1/2		280	344		340	384				
									TOTAL REWORK OK QTY		350		417	550		274	330		195	330		287			369			1/2	1/2		280	344		340	384				
									INSPECTION/CHIPPING PENDING																															
									VISUAL DEFECTS STRAIGHT PASS		88%		851	89%		861	88%		821	89%		871			831						89%	741		89%	871				
									NO. OF NON CONFORMITY																															
12	SARI GUARD AAER	51103-AAE-H000	AAER						CHECKED QTY.	1962			2010	1895		2130	2190		1885	1952		2160	2295		1970			960			2260	2900		2242	2850				
									OK QTY.	1533			1537	1424		1626	1731		1403	1520		1658	1855		1470			700			1796	2390		1780	2336				
									REJ. QTY.																															
									REW. QTY.	429			485	471		516	459		494	432		514	440		512			365	1/2		464	522		455	526				
									TOTAL REWORK OK QTY	429			473	471		504	459		482	432		502	440		500			260	1		464	510		455	514				
									INSPECTION/CHIPPING PENDING																															
									VISUAL DEFECTS STRAIGHT PASS	78%			76%	75%		76%	79%		77%	77%		76%	80%		74%			72%			79%	82%		79%	81%				
									NO. OF NON CONFORMITY																															
13	SARI GUARD AAH	51103-AAH-1100	AAH						CHECKED QTY.	925			1380			1100			1265												990	690		1180					
									OK QTY.	782			1213			722			987												841	528		1037					
									REJ. QTY.																															
									REW. QTY.	143			193	1/2		378			278									1/2	1/2		149	167		143	1/2				
									TOTAL REWORK OK QTY	143			193	1/2		378			278									1/2	1/2		149	162		143	1/2				
									INSPECTION/CHIPPING PENDING										-																				
									VISUAL DEFECTS STRAIGHT PASS	84%			87%			65%			78%												84%	76%		87%					
									NO. OF NON CONFORMITY																															
14	CROSS PIPE	77215-AAD-3000	AAD						CHECKED QTY.				1800			2000			2150			1650			1700	1380					2100			1900					
									OK QTY.				1387			1537			1620			1211			1235	968					1620			1388					
									REJ. QTY.																															
									REW. QTY.				413	1/2		463			480			439			465	338		1/2	1/2		480	1/2		512	1/2				
									TOTAL REWORK OK QTY				388	1/2		368			415			392			322	338		1/2	1/2		384	1/2		457					
									INSPECTION/CHIPPING PENDING				774			734			774			738			722	744					772			731					
									VISUAL DEFECTS STRAIGHT PASS																															
									NO. OF NON CONFORMITY																															

Revision no. 01
Revision Detail :- NON CONFORMITY point Added on 01.06.2025

Sept 26

MEENAKSHI POLYMERS PVT. LTD. HARIDWAR

BS6 MODEL COMPONENT STRAIGHT PASS MONITORING SHEET

SNO	PART NAME	PART NUMBER	MODEL	APRIL	MAY	JUNE	JULY	AUGUST	PARAMTER	21 A	21 B	21 TOTAL	22 A	22 B	22 TOTAL	23 A	23 B	23 TOTAL	24 A	24 B	24 TOTAL	25 A	25 B	25 TOTAL	26 A	26 B	26 TOTAL	27 A	27 B	27 TOTAL	28 A	28 B	28 TOTAL	29 A	29 B	29 TOTAL	30 A	30 B	30 TOTAL
15	CROSS PIPE	77215-AAE-9300	AAEL						CHECKED QTY.					900			900			900			1000			980						900			820					
									OK QTY.					632			651			693			709			707						652			614					
									REJ. QTY.																																
									REW. QTY.					268			249			207			291			273			2 1	2 1		248			206					
									TOTAL REWORK OK QTY					258			239			205			290			253			2 1	2 1		234			197					
									INSPECTION/CHIPPING PENDING					70%			72%			77%			70%			72%			1	1		72%			74%					
									VISUAL DEFECTS STRAIGHT PASS																																
									NO. OF NON CONFORMITY																																
16	SARI GUARD ACY	51103-AAC-K000	ACY						CHECKED QTY.																										624					
									OK QTY.																										247					
									REJ. QTY.																																
									REW. QTY.																			2 1	2 1		2 1			277					
									TOTAL REWORK OK QTY																			2 1	2 1		2 1			277					
									INSPECTION/CHIPPING PENDING																			1	1		1			55%					
									VISUAL DEFECTS STRAIGHT PASS																																
									NO. OF NON CONFORMITY																																
17	ENGINE GUARD	50803-ABZ-0000	ABZA						CHECKED QTY.										150						220						57								
									OK QTY.										66						119						24								
									REJ. QTY.																																
									REW. QTY.										84						101			2 1	2 1		33			2 1					
									TOTAL REWORK OK QTY										84						101			1	1		33			2					
									INSPECTION/CHIPPING PENDING																																
									VISUAL DEFECTS STRAIGHT PASS										44%						54%						42%								
									NO. OF NON CONFORMITY																																
18	SIDE STAND	50530-AAF-4000	AAF						CHECKED QTY.																																
									OK QTY.																																
									REJ. QTY.																																
									REW. QTY.																			2 1	2 1		2 1								
									TOTAL REWORK OK QTY																			1	1		1								
									INSPECTION/CHIPPING PENDING																																
									VISUAL DEFECTS STRAIGHT PASS																																
									NO. OF NON CONFORMITY																																
19	SIDE STAND	50530-ABZA-0000	ABZA						CHECKED QTY.																																
									OK QTY.																																
									REJ. QTY.																																
									REW. QTY.																			2 1	2 1		2 1								
									TOTAL REWORK OK QTY																			1	1		1								
									INSPECTION/CHIPPING PENDING																																
									VISUAL DEFECTS STRAIGHT PASS																																
									NO. OF NON CONFORMITY																																
20	PEDAL BRAKE	46500-ABZ-0100	ABZA DD						CHECKED QTY.																																
									OK QTY.																																
									REJ. QTY.																																
									REW. QTY.																			2 1	2 1		2 1								
									TOTAL REWORK OK QTY																			1	1		1								
									INSPECTION/CHIPPING PENDING																																
									VISUAL DEFECTS STRAIGHT PASS																																
									NO. OF NON CONFORMITY																																
21	PEDAL BRAKE	46500-ABZ-0000	ABZA SD						CHECKED QTY.																																
									OK QTY.																																
									REJ. QTY.																																
									REW. QTY.																			2 1	2 1		2 1								
									TOTAL REWORK OK QTY																			1	1		1								
									INSPECTION/CHIPPING PENDING																																
									VISUAL DEFECTS STRAIGHT PASS																																
									NO. OF NON CONFORMITY																																

Revision no. 01
Revision Detail :- NON CONFORMITY point Added on 01.06. 2025