FI VISUAL INSPECTION 100%(POWDER COATING)

DATE- 29/01/2026

REV DATE-01.06
REV NO.-02

O.	DESCRIPTION OF DEFECT	SARI GUARD-AAH	SARI GUARD-AAE	STEP WOMEN-AAH	STEP PILLION-AAE	SARI GUARD-AACY	STEP WOMEN AACY	ENGINE GUARD-KVH	CROSS PIPE AAEL	ENGINE GUARD-ABZA	ENGINE GUARD-ABZA PAINTED	PEDAL BRAKE-ABZA	SIDE STAND ABZA	TOTAL	FOR REWORK		REJECTION	B-GRADE/GPC
															MINOR	MAJOR	SCRAP	
1	PEEL OFF	05	08	—	—	03	—	—	—	—	—	—	—	16	—	—	16	—
2	TOUCHING	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
3	DULL PAINT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
4	PAINT DRY/LACK OF PAINT	148	91	05	08	26	03	—	06	06	—	—	—	293	293	—	—	—
5	UNCOVERAGE	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
6	DUST	06	21	—	—	04	—	—	—	53	—	—	—	84	—	84	—	—
7	PIN HOLE	—	36	—	—	—	—	—	—	—	—	—	—	36	36	—	—	—
8	ORANGE PEEL	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
9	OIL MARK	02	03	04	09	—	—	—	—	04	—	—	—	22	—	22	—	—
10	WATER FLOW/MARK	—	—	06	21	—	04	—	—	—	—	—	—	31	—	31	—	—
11	CESSING	08	28	—	—	—	—	—	—	—	—	—	—	36	—	36	—	—
12	PAINT OVER FLOW	04	31	—	—	03	—	—	02	06	—	—	—	46	—	46	—	—
13	PAINT MIXING	[redacted]	[redacted]	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
14	DENT/SCRATCH AFTER P.C	09	13	—	—	04	—	—	03	04	—	—	—	28	—	28	—	—
TAL		177	231	15	38	40	07	—	11	73	—	—	—	592	329	247	16	—
	FABRICATION DEFECT																	
1	BLOW HOLE	—	07	02	06	—	—	—	—	—	—	—	—	—	—	—	—	—
2	WELDING SPATTER	04	09	03	04	02	02	—	04	02	—	—	—	15	—	—	—	—
3	SPATTER SOUND	—	—	—	—	—	—	—	—	—	—	—	—	30	—	—	—	—
4	U-BKT NUT MISS/OUT	—	08	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
5	U-BKT NUT BROKEN	—	06	—	—	—	—	—	—	—	—	—	—	08	—	—	—	—
6	U-BKT SHIFT	—	—	—	—	—	—	—	—	—	—	—	—	06	—	—	—	—
7	STAY BEND	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
8	U- BKT BEND	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
9	PIPE CHOCK	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
10	GRINDER MARK	—	04	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
11	DRAIN HOLE WRONG SIDE	—	—	—	—	—	—	—	—	—	—	—	—	04	—	—	—	—
12	PIPE CRECK/LINE	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
13	GAUGE CUT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
14	U-BKT THREAD WASH/NOT OK	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
15	DENT & SCRATCH	—	06	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
16	OVER WELDING	—	08	—	—	—	—	—	03	01	—	—	—	10	—	—	—	—
17	WIRE SHORT	—	—	—	—	—	—	—	—	—	—	—	—	04	—	—	—	—
18	WELDING IN COMPLETE	—	01	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
19	WELDING BROKEN BAR-A	—	03	—	—	—	—	—	—	—	—	—	—	01	—	—	—	—
20	WELDING BROKEN BAR-B	—	08	—	—	—	—	—	—	—	—	—	—	03	—	—	—	—
21	WELDING BROKEN BAR-C	03	02	—	—	—	—	—	—	—	—	—	—	08	—	—	—	—
22	WELDING BROKEN BAR-D	—	—	—	—	—	—	—	—	—	—	—	—	05	—	—	—	—
23	WELDING BROKEN BAR-E	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
24	WELDING SHIFT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
25	METERIAL FAULT	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
26	PUNCH MISS [redacted]CATION/ MISS	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
28	NOU OUT WELD	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
29	NUT INSIDE WELD	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
30		—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
TAL		07	58	05	10	02	02	—	07	03	—	—	—	94	—	94	—	—
TAL REJECTION OF THE DAY		184	289	20	48	42	09	—	18	76	—	—	—	686	—	341	—	—
ODUCTION		1304	5809	1220	1568	832	489	—	787	176	—	—	—	15746	—	15746	—	—
AIGHTPASS		0617	95.02	98.36	99.13	97.95	98.15	—	96.08	56.81	—	—	—	95.64	—	97.83	—	—
TAL REJECTION %																		
TAL REJECTION PPM.																		

VISION DETAIL: 22.01.2025 -REV-1-FI CHECK SHEET COMMONIZE (DUBLE SHEET CONVERTED TO SINGAL SHEET)
01.06.2025 -REV-2-FI REWORK REJECTION COLUMN ADDED,DEFECTS UPDATED AS PER CUSTOMER COMPLAINT AND FI/PDI

EPARED BY-

CHECKED BY -

APPROVED BY:-

29/01/26

29/01/26