MEENAKSHI POLYMERS PVT. LTD. HARIDWAR

BS6 MODEL COMPONENT STRAIGHT PASS MONITORING SHEET

SNO	PART NAME	PART NUM	MODEL	PARAMTER	21			22			23			24			25			26			27			28			29			30		
					A	B	TOTAL	A	B	TOTAL	A	B	TOTAL	A	B	TOTAL	A	B	TOTAL	A	B	TOTAL	A	B	TOTAL	A	B	TOTAL	A	B	TOTAL	A	B	TOTAL
1	ENGINE GUARD KST	50803-KST-9400	KST	CHECKED QTY.	2920	1763		2900	2180		2700	2350																					
				OK QTY.	2419	1093		2283	1445		1983	1968																					
				REJ. QTY.																													
				REW. QTY.	495	672		581	735		717	582																					
				TOTAL REWORK OK QTY	495	672		561	735		717	582																					
				INSPECTION/CHIPPING PENDING	82%																													
				VISUAL DEFECTS STRAIGHT PASS	82%	61%		78%	66%		73%	71%																					
				NO. OF NON CONFORMITY																													
2	CARRIER LINE-01	81200-AAD-3000	AAD	CHECKED QTY.																													
				OK QTY.																													
				REJ. QTY.		NO PLAN			NO PLAN			NO PLAN																					
				REW. QTY.																													
				TOTAL REWORK OK QTY																													
				INSPECTION/CHIPPING PENDING																													
				VISUAL DEFECTS STRAIGHT PASS																													
				NO. OF NON CONFORMITY					1																								
3	CARRIER LINE-R	81200-AAD-3000	AAD	CHECKED QTY.		1812			1464		1467																						
				OK QTY.		680					789																						
				REJ. QTY.							-																						
				REW. QTY.		834					698																						
				TOTAL REWORK OK QTY		834					698																						
				INSPECTION/CHIPPING PENDING							-																						
				VISUAL DEFECTS STRAIGHT PASS		44%					52%																						
				NO. OF NON CONFORMITY							-																						
4	CARRIER LINE-R AAEL	81200A-AAE-3000	AAEL	CHECKED QTY.	1185	1210	1200		1180		1215	1200																					
				OK QTY.	705	894	711		537		685	701																					
				REJ. QTY.							-																						
				REW. QTY.	480	616	489		633		530	499																					
				TOTAL REWORK OK QTY	480	611	489		633		530	499																					
				INSPECTION/CHIPPING PENDING							-																						
				VISUAL DEFECTS STRAIGHT PASS	59%	50%	58%		48%		56%	58%																					
				NO. OF NON CONFORMITY							-																						
5	MAIN STAND	50500-AAE-3000	AAEE	CHECKED QTY.	527	572		610	689		573	551																					
				OK QTY.	363	277		408	339		339	283																					
				REJ. QTY.																													
				REW. QTY.	164	315		202	350		234	268																					
				TOTAL REWORK OK QTY	164	315		202	350		234	268																					
				INSPECTION/CHIPPING PENDING	68%																													
				VISUAL DEFECTS STRAIGHT PASS		48%		66%	48%		59%	51%																					
				NO. OF NON CONFORMITY																													
6	MAIN STAND	50500-AACK-3000	ACK	CHECKED QTY.	953	1100		1118	1019	1008	1008	1161																					
				OK QTY.	623	638		749	495	617	617	579																					
				REJ. QTY.																													
				REW. QTY.	330	462		366	515	391	391	582																					
				TOTAL REWORK OK QTY	330	462		366	524	391	391	582																					
				INSPECTION/CHIPPING PENDING																													
				VISUAL DEFECTS STRAIGHT PASS	65%	58%		67%	48%	61%	61%	49%																					
				NO. OF NON CONFORMITY																													
7	PEDAL BRAKE	50500-AAE-0000	AAEN	CHECKED QTY.	1530	1950		1460	1920		1700	2200																					
				OK QTY.	1272	1532		1221	1565		1413	1638																					
				REJ. QTY.																													
				REW. QTY.	258	418		239	355		287	562																					
				TOTAL REWORK OK QTY	258	418		239	355		287	562																					
				INSPECTION/CHIPPING PENDING																													
				VISUAL DEFECTS STRAIGHT PASS	83%	78%		83%	81%		83%	74%																					
				NO. OF NON CONFORMITY																													