
AD31D, AD31XD, TAMD31D, TMD31D



Upd:2012-01-30

AD31D, AD31XD, TAMD31D, TMD31D

REF	PART NO.	QTY	DESCRIPTION	SEE SEC.	NOTES
1	PART NO. (875000) 828761	1	Thermo monitor	522 525.	For engines with reverse gear Obsolete part
2	828761	1	Thermo monitor		For engines with reverse gear., Obsolete part 80°C
3	828750	1	• Nut		
4	828776	2	Washer		
5	828817	1	Sensor		
6	973122 949597	2	Cable terminal	1963 1963	
	949597	2	Housing	1963	
1					
1					
1					
	10.05.075				11. 1.0040.04.00

7746610-25-975 22977 Upd:2012-01-30