DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE ANTANANARIVO-ALASORA



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
870364/ANT/004/Sur_site/2021	SIG29	8222TBK	Mr RANDRIAMANANTENA Gérald
870321/ANT/004/Sur_site/2021	CAR20	4514TAA	GPHC RAKOTONIRINA J. Alexandre
870277/ANT/004/Sur_site/2021	ACC3,MOT21	2805TJ	GP1C RANDRIATSIMIALONA L El'no
870248/ANT/004/Sur_site/2021	MOT17	4959TAM	GP1C RANDRIATSIMIALONA L El'no
870165/ANT/004/Sur_site/2021	СНЗ	7674TBP	GPHC RAVAKA RABOTOVAO
870135/ANT/004/Sur_site/2021	DIR13,FR13,PN3,PN4,SIG12	0203TBN	GPHC DONAVAO Rock Well
870115/ANT/004/Sur_site/2021	MOT2	4352TR	GP1C RANDRIATSIMIALONA L El'no
870047/ANT/004/Sur_site/2021	CAR12,CAR13,PAP10	7121TBP	GP1C RANDRIATSIMIALONA L El'no
869940/ANT/004/Sur_site/2021	CAR20	7129TL	Mr RANDRIAMANANTENA Gérald
869577/ANT/004/Sur_site/2021	СНЗ	1609TAE	Mr TSIMBAZAFY Edith Adelphe
869233/ANT/004/Sur_site/2021	MOT2	2853UD	Mr RANDRIAMANANTENA Gérald
869129/ANT/004/Sur_site/2021	SIG17,SIG18	8714TBJ	GP1C RANDRIATSIMIALONA L El'no
869117/ANT/004/Sur_site/2021	FR13,MOT2	2470AH	GP1C RANDRIATSIMIALONA L El'no
•			TOTAL: 13

A ALASORA, le 05/10/2021 Le Chef de Centre