DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE FIANARANTSOA - BESOROHITRA



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
923223/FNR/007/Sur_site/2021	MOT18	7694FE	ANDRIAMASIARISOLO JEAN ARNAUD
922984/FNR/007/Sur_site/2021	CAR1,CAR2,CAR23	3347FE	ANDRIAMASIARISOLO JEAN ARNAUD
922977/FNR/007/Sur_site/2021	CAR13,CAR52,MOT9	7680FE	ANDRIAMASIARISOLO JEAN ARNAUD
922747/FNR/007/Sur_site/2021	PN1,PN4	0211FE	Mr RANDRIAMIHAMINA J B ROLAND
922549/FNR/007/Sur_site/2021	FR13,MOT18,MOT2,MOT17	1531FE	Mr RANDRIAMIHAMINA J B ROLAND
922520/FNR/007/Sur_site/2021	CAR20,CH3,FR13,PN1,PN2,PN3,S IG10,TR6	4215DG	Mr RANDRIAMIHAMINA J B ROLAND
922341/FNR/007/Sur_site/2021	ACC3,CAR1,CAR2	3046TN	ANDRIAMASIARISOLO JEAN ARNAUD
922305/FNR/007/Sur_site/2021	DIR13	0463FE	GPHC ANDRIANARISON Solofoniaina
			Didier
			TOTAL:8

A BESOROHITRA, le 25/11/2021 Le Chef de Centre