DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE ANTANANARIVO - ALASORA



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
929884/ANT/004/Sur_site/2021	FR1,MOT18,PN2,DIR12,CAR3	2476TBJ	GPHC RAVAKA RABOTOVAO
929873/ANT/004/Sur_site/2021	MOT1	4245TAF	GPHC RAVAKA RABOTOVAO
929828/ANT/004/Sur_site/2021	CAR6,CAR7	7892TBB	GP1C RANDRIATSIMIALONA L El'no
929680/ANT/004/Sur_site/2021	ACC6,CAR24	5375TBG	GPHC DONAVAO Rock Well
929572/ANT/004/Sur_site/2021	FR13,MOT2	5088TAB	GPHC RAVAKA RABOTOVAO
929563/ANT/004/Sur_site/2021	MOT2	4427TAM	GPHC RAVAKA RABOTOVAO
929426/ANT/004/Sur_site/2021	CAR6,MOT2	5507AG	GPHC RAVAKA RABOTOVAO
			TOTAL: 7

A ALASORA, le 02/12/2021 Le Chef de Centre