DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE FIANARANTSOA - BESOROHITRA



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
927657/FNR/007/Sur_site/2021	DIR18,DIR20,SIG2	1673TBG	Mr RANDRIAMIHAMINA J B ROLAND
927346/FNR/007/Sur_site/2021	CH6	7354FD	ANDRIAMASIARISOLO JEAN ARNAUD
927307/FNR/007/Sur_site/2021	FR13,FR18,MOT2,PN6,SIG10,SIG 9	5898FD	Mr RANDRIAMIHAMINA J B ROLAND
927055/FNR/007/Sur_site/2021	ACC11,ACC13,CAR24,CAR8,MO T18	9632FE	ANDRIAMASIARISOLO JEAN ARNAUD
926693/FNR/007/Sur_site/2021	FR13	5103FB	ANDRIAMASIARISOLO JEAN ARNAUD
			TOTAL:5

A BESOROHITRA, le 30/11/2021 Le Chef de Centre