## DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE ANTANANARIVO - ALASORA



## **FICHE ANOMALIES**

Ncontrole	INAPTE	Imm	Verificateur
878044/ANT/004/Sur_site/2021	ACC6,CAR24	1642TBN	GPHC DONAVAO Rock Well
878024/ANT/004/Sur_site/2021	CAR6,CAR7	2083FE	GP1C RANDRIATSIMIALONA L El'no
878016/ANT/004/Sur_site/2021	PAP10,PN1,PN3	5404ME	GPHC RAKOTONIRINA J. Alexandre
877952/ANT/004/Sur_site/2021	CAR6,CAR7	3290TAF	Mr RANDRIAMANANTENA Gérald
877937/ANT/004/Sur_site/2021	CAR24,FR1	6668TAE	GPHC DONAVAO Rock Well
877934/ANT/004/Sur_site/2021	MOT1,PN3	1255TM	GPHC DONAVAO Rock Well
877544/ANT/004/Sur_site/2021	CAR2,CAR20,MOT6	5845TV	GPHC DONAVAO Rock Well
877494/ANT/004/Sur_site/2021	MOT2	4154TBA	GPHC DONAVAO Rock Well
877351/ANT/004/Sur_site/2021	СН3	6738TAC	GPHC DONAVAO Rock Well
877337/ANT/004/Sur_site/2021	CAR6,DIR13	8072TAB	Mr RANDRIAMANANTENA Gérald
877304/ANT/004/Sur_site/2021	CAR2,CAR20,MOT18	6032TBA	GPHC DONAVAO Rock Well
877008/ANT/004/Sur_site/2021	ACC6,CAR24,PN4	5482DG	Mr TSIMBAZAFY Edith Adelphe
876729/ANT/004/Sur_site/2021	ACC6,CAR24	3399TBM	GP1C RANDRIATSIMIALONA L El'no
•			TOTAL: 13

A ALASORA, le 12/10/2021 Le Chef de Centre