DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE ANTANANARIVO-BETONGOLO



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
864000/ANT/002/Sur_site/2021	СНЗ	1149TBM	GPHC RANDRANTONIRINA José B.A
863952/ANT/002/Sur_site/2021	MOT1	4349TAL	GPHC RANDRANTONIRINA José B.A
863617/ANT/002/Sur_site/2021	СНЗ	3812TBG	GPHC RANDRANTONIRINA José B.A
863599/ANT/002/Sur_site/2021	CAR6	7228TAS	Mr RABEARISOA Jerry Christian
863534/ANT/002/Sur_site/2021	CAR6	0201TBH	GPHC RAZAFINDRARIVO Chrésus
863505/ANT/002/Sur_site/2021	CAR42	5969TAR	GPHC ANDRIAMBOLOLONA Nary
863369/ANT/002/Sur_site/2021	CH5	1410TAF	Mr RABEARISOA Jerry Christian
		·	TOTAL: 7

A BETONGOLO, le 29/09/2021 Le Chef de Centre