## DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE FIANARANTSOA - BESOROHITRA



## **FICHE ANOMALIES**

Ncontrole	INAPTE	Imm	Verificateur
905034/FNR/007/Sur_site/2021	CAR1,FR13,MOT12,PN10	2395FD	Mr RANDRIAMIHAMINA J B ROLAND
904896/FNR/007/Sur_site/2021	CAR1,SIG10,SIG9	5998FE	Mr RANDRIAMIHAMINA J B ROLAND
904102/FNR/007/Sur_site/2021	CH6	4881FE	Mr RANDRIAMIHAMINA J B ROLAND
904097/FNR/007/Sur_site/2021	SIG17,SIG32,SIG5	0947TBL	Mr RANDRIAMIHAMINA J B ROLAND
904089/FNR/007/Sur_site/2021	CAR24,CH3,MOT18	8594FE	Mr RANDRIAMIHAMINA J B ROLAND
904045/FNR/007/Sur_site/2021	PN3,PN4	5033FE	Mr RANDRIAMIHAMINA J B ROLAND
904027/FNR/007/Sur_site/2021	FR13	2763FD	GPHC ANDRIANARISON Solofoniaina
			Didier
			TOTAL: 7

A BESOROHITRA, le 08/11/2021 Le Chef de Centre