DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE FIANARANTSOA - BESOROHITRA



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
919424/FNR/007/Sur_site/2021	PN3,PN4,SIG3	8157FE	Mr RANDRIAMIHAMINA J B ROLAND
919118/FNR/007/Sur_site/2021	CH3	7201FB	ANDRIAMASIARISOLO JEAN ARNAUD
918981/FNR/007/Sur_site/2021	FR13,FR17,FR18	9007TAB	Mr RANDRIAMIHAMINA J B ROLAND
918957/FNR/007/Sur_site/2021	FR1,PN6,SIG9	9317FD	Mr RANDRIAMIHAMINA J B ROLAND
918812/FNR/007/Sur_site/2021	PN2	2603FC	GPHC ANDRIANARISON Solofoniaina
			Didier
918758/FNR/007/Sur_site/2021	DIR14,FR13,FR17,PN6	5806FD	Mr RANDRIAMIHAMINA J B ROLAND
918747/FNR/007/Sur_site/2021	FR13,MOT2,SIG10	8741FD	Mr RANDRIAMIHAMINA J B ROLAND
918676/FNR/007/Sur_site/2021	CAR2,CAR3,CAR54,DIR14,FR13,	6204FE	Mr RANDRIAMIHAMINA J B ROLAND
	FR18,MOT1,MOT12,SIG18,SIG19,		
	SIG2		
			TOTAL:8

A BESOROHITRA, le 22/11/2021 Le Chef de Centre