DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE ANTANANARIVO - ALASORA



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
923113/ANT/004/Sur_site/2021	CAR24	0300TBR	GPHC DONAVAO Rock Well
923091/ANT/004/Sur_site/2021	CAR2,MOT2,MOT6,SUS2	2941TV	GPHC RAKOTONIRINA J. Alexandre
923016/ANT/004/Sur_site/2021	CH5	6974TAM	GPHC RAKOTONIRINA J. Alexandre
922925/ANT/004/Sur_site/2021	ACC13,ACC6,FR1,SIG31,SIG4	6667TBM	GP1C RANDRIATSIMIALONA L El'no
922748/ANT/004/Sur_site/2021	SIG3,SIG5	6539TBD	GPHC RAKOTONIRINA J. Alexandre
922521/ANT/004/Sur_site/2021	CAR2,CAR20	5856TBK	GPHC DONAVAO Rock Well
922397/ANT/004/Sur_site/2021	PAP5	0300TAB	Mr TSIMBAZAFY Edith Adelphe
922364/ANT/004/Sur_site/2021	CAR20,CAR6	8688TAV	Mr RANDRIAMANANTENA Gérald
922300/ANT/004/Sur_site/2021	CAR13,MOT1	7476DF	Mr RANDRIAMANANTENA Gérald
922200/ANT/004/Sur_site/2021	CH3	0572TBN	GP1C RANDRIATSIMIALONA L El'no
			TOTAL: 10

A ALASORA, le 25/11/2021 Le Chef de Centre