DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE ANTANANARIVO - ALASORA



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
920832/ANT/004/Sur_site/2021	CAR20,CAR6,CAR7,CH5,FR2	6545TAN	GPCE FARALAHY
920633/ANT/004/Sur_site/2021	CAR2,CAR20,MOT9	8062TAD	GPHC DONAVAO Rock Well
920631/ANT/004/Sur_site/2021	DIR9,SUS23,SUS24	8726TK	GPCE FARALAHY
920363/ANT/004/Sur_site/2021	CAR2,CAR20,CAR42	4130TBM	GPHC DONAVAO Rock Well
920244/ANT/004/Sur_site/2021	CAR23	1172TAK	GPCE RAFALIMANANA Jocelyn
920218/ANT/004/Sur_site/2021	CAR55,CAR7,FR1,SIG9	0496TBN	GPCE RAFALIMANANA Jocelyn
920178/ANT/004/Sur_site/2021	CAR12	0988TBK	Mr RANDRIAMANANTENA Gérald
920082/ANT/004/Sur_site/2021	MOT2	5993TAP	Mr RANDRIAMANANTENA Gérald
920064/ANT/004/Sur_site/2021	MOT2	0220TBC	Mr RANDRIAMANANTENA Gérald
920012/ANT/004/Sur_site/2021	CAR2	8051TAD	GPCE FARALAHY
			TOTAL: 10

A ALASORA, le 23/11/2021 Le Chef de Centre