DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE FIANARANTSOA - BESOROHITRA



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
908867/FNR/007/Sur_site/2021	CAR24,MOT12	5843FD	Mr RANDRIAMIHAMINA J B ROLAND
908404/FNR/007/Sur_site/2021	SIG2	9472FE	ANDRIAMASIARISOLO JEAN ARNAUD
908370/FNR/007/Sur_site/2021	CAR25,CAR28,FR1	2763FE	Mr RANDRIAMIHAMINA J B ROLAND
908305/FNR/007/Sur_site/2021	FR13	7355TAS	Mr RANDRIAMIHAMINA J B ROLAND
908086/FNR/007/Sur_site/2021	CAR11,CAR20,CAR25,CAR4,FR1 3,MOT2	0401FC	Mr RANDRIAMIHAMINA J B ROLAND
			TOTAL:5

A BESOROHITRA, le 11/11/2021 Le Chef de Centre