DIRECTION GENERALE DE LA SECURITE ROUTIERE

CENTRE DE SECURITE ROUTIERE ANTANANARIVO - ALASORA



FICHE ANOMALIES

Ncontrole	INAPTE	Imm	Verificateur
934161/ANT/004/Sur_site/2021	MOT17	0862TAP	GP1C RANDRIATSIMIALONA L El'no
934069/ANT/004/Sur_site/2021	FR1,PAP11,SIG18,SIG20,SIG21,SI	0731TP	GP1C RANDRIATSIMIALONA L El'no
	G3,SIG5		
934003/ANT/004/Sur_site/2021	PAP10	1032TBP	GP1C RANDRIATSIMIALONA L El'no
933693/ANT/004/Sur_site/2021	MOT2	1497TBF	GPCE FARALAHY
933276/ANT/004/Sur_site/2021	CAR2,DIR13,PN2	2728TAU	Mr RANDRIAMANANTENA Gérald
933063/ANT/004/Sur_site/2021	DIR17,FR13	9833TAF	GP1C RANDRIATSIMIALONA L El'no
933018/ANT/004/Sur_site/2021	CAR13,PAP10	8003TBN	Mr RANDRIAMANANTENA Gérald
			TOTAL: 7

A ALASORA, le 07/12/2021 Le Chef de Centre