



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/09/2026

Incharge(s): K SANKARA RAO

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-26	olr acted (2TIMES)	RESET DONE	09:40:00 12:10:00	09:45:00 12:15:00	
2	OHP	TBS ON CO-21	REPORTED LT NOT TAKING PLACE FOUND DRIVE TRIP	RESET DONE	12:30:00	12:40:00	
3	OHP	CO-26	OLR ACTED	RESET DONE	13:30:00	13:35:00	
4	CHP	CC-29	STOPPING ON ZSS FOUND ZSS CAGE STUCK UP WITH COAL PICK	REMOVED THAN OK	10:30:00	10:45:00	
5	CHP	CC-28, F/G	OLR ACTED	RESET DONE	10:00:00	10:10:00	
6	CHP	CC-131	TRIPPED ON OLR	RESET DONE	11:40:00	11:50:00	
7	CHP	CC-58	TRIPPED ON OLR	RESET DONE	11:20:00	11:30:00	
8	WT	CO-4	REPORTED NOT RUNNING FOUND E/STOP ACTED	RELEASED THAN OK	07:30:00	07:40:00	