



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 12/05/2026

Area: OHP

Equipment	Job
co-16	panel side voltages and currents checked and module found ok, observed return side jamming and idlers not available, informed operation.
repair bay HT transformer	The tank base leakage welding job is in progress.
tbs-1 on co-23	shifted from co-23 to co-22