



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 28/07/2026

Area: OHP

Equipment	Job
tis-6 on co-29	checked after mechanical work, restored in circuit.
tis-6 on co-29	checked after mechanical work, restored in circuit.
tt-2 chute vibrator	counter weight adjustment is done to reduce vibration and cjd is restored in circuit.
tt-2 chute vibrator	counter weight adjustment is done to reduce vibration and cjd is restored in circuit.
jh o-2	welding machine supply lugs damaged, replaced.
jh o-2	welding machine supply lugs damaged, replaced.
crmp stream	hoists and chute vibrators inspection is done. faults found to be rectified.
crmp stream	hoists and chute vibrators inspection is done. faults found to be rectified.
tbs-3 on co-5a, transfer car	ppm is done
tbs-3 on co-5a, transfer car	ppm is done
co-33a,34a,65, 66 chute vibrators	ppm is done
co-33a,34a,65, 66 chute vibrators	ppm is done
rco-2a	motor and safety devices ppm is done
rco-2a	motor and safety devices ppm is done
locp-1,vf level, 44 ,49 gallery , vf-19, levels	lighting is improved
locp-1,vf level, 44 ,49 gallery , vf-19, levels	lighting is improved
co-12a spare motor	For motor replacement spare motor shifted to H/E
co-12a spare motor	For motor replacement spare motor shifted to H/E