



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 10/07/2026

Area: OHP

| Equipment                                     | Job                                                                                                                   |
|-----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|
| co-38a,38b hoists                             | ppm is done.                                                                                                          |
| co-38a,38b hoists                             | ppm is done.                                                                                                          |
| OM-16,1-141LC3,1-141LC4<br>GROUND FLOOR, LC-7 | RIO's PPM is done.                                                                                                    |
| OM-16,1-141LC3,1-141LC4<br>GROUND FLOOR, LC-7 | RIO's PPM is done.                                                                                                    |
| JH O-3 ; JH O-2                               | LDB PPM is done, JH O-2 hoists ppm is done.                                                                           |
| JH O-3 ; JH O-2                               | LDB PPM is done, JH O-2 hoists ppm is done.                                                                           |
| vs-1 removed motor                            | shifted to lc-7, coupling removed. planned to be sent for overhauling. Spare motor identified and trail run is taken. |
| vs-1 removed motor                            | shifted to lc-7, coupling removed. planned to be sent for overhauling. Spare motor identified and trail run is taken. |
| LOSP-1 vf-19 level                            | 100A mcb burnt, replaced and restored welding machine supply.                                                         |
| LOSP-1 vf-19 level                            | 100A mcb burnt, replaced and restored welding machine supply.                                                         |
| co-24 brs                                     | sensors canopy is provided.                                                                                           |
| co-24 brs                                     | sensors canopy is provided.                                                                                           |
| space heaters of HT couplers                  | inspection done, found working.                                                                                       |
| space heaters of HT couplers                  | inspection done, found working.                                                                                       |
| Failed BRC transformer                        | oil removed and cleaning done, planned to be sent to ERS.                                                             |
| Failed BRC transformer                        | oil removed and cleaning done, planned to be sent to ERS.                                                             |
| brc-2 on repair bay                           | mcc cleaning, cable dressing done                                                                                     |
| brc-2 on repair bay                           | mcc cleaning, cable dressing done                                                                                     |
| tbs-1 on co-22, co-22                         | motor and panel side ppm is done.                                                                                     |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL GENERAL SHIFT REPORT**

Date: 10/07/2026

Area: OHP

| Equipment             | Job                               |
|-----------------------|-----------------------------------|
| tbs-1 on co-22, co-22 | motor and panel side ppm is done. |