



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 18/06/2026

Area: OHP

Equipment	Job
jh o-14	sump pump failed, to be replaced.
jh o-14	sump pump failed, to be replaced.
1-141lc3 battery bank	batteries discharging is started. To be charged again.
1-141lc3 battery bank	batteries discharging is started. To be charged again.