



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/08/2026

Incharge(s): Nagendra Midde

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-27a	zss probe replaced	found ok. to be checked in run condition	06:00:00	06:45:00	
2	OHP	co-29	dmpr tripped on olr twice	reset done	07:45:00 13:20:00	07:50:00 13:25:00	
3	OHP	co-26	dmp tripped on olr twice	reset done	11:50:00 13:15:00	12:00:00 13:20:00	
4	CHP	SCR 6	Slew problem	Material jamming cleared	12:50:00	13:00:00	
5	CHP	CC 54	OLR acted	Reset	10:20:00	10:30:00	
6	WT	OP-7	FWD not moving	Tipper clamp limits switch MCB tripped in PLC panel,Reset	11:01:00	11:10:00	